



VEHICLE SERVICE HISTORY

VEHICLE DETAILS:

| Make & Model | Year | Plate No. | Current Mileage | VIN

BMW X7 M50I. 2020. DXB N 9354 112443 Km. #WBXCX6A02M9E97988

SERVICE HISTORY:

ID	DATE	MILEAGE	WORK DONE
01	31/Mar/26.	112398 Km	1- Engine oil service & full check up 2-Rear brake pads & rear sensor
02.	6/Oct/26	122443 Km	1- Engine oil service & full check up

FUTURE WORK / RECOMMENDATIONS:

| ID | RECOMMENDED WORK. | DUE / MILEAGE |