Crash Summary

Unannotated Image

Annotated Image

Incident Information

Incident Detected	True
Status	active
Types	collision, disabled_vehicle
Confidence	1.0
Why	Two passenger vehicles have clearly collided, resulting in visible front-end damage to both vehicles and smoke/steam emanating from one. They are in a collision position on a paved surface.
Actual Accident Verified By Gemini	True
Accident Verification Status	confirmed_by_both
Accident Verification Note	Both the unannotated image and video clip confirm a true accident. Image note: The image clearly shows two vehicles in a collision position with visible damage to both front ends. The silver car has a crumpled hood and visible smoke/fumes emanating from beneath the front of the vehicle, which are strong indicators of an actual crash. Video note: The video clearly shows a black minivan backing into a silver car. Upon impact, the silver car's front hood is visibly crumpled, and smoke/steam emanates from its front, indicating collision damage.

Verification Details

Image Verification	True
Image Verification Note	The image clearly shows two vehicles in a collision position with visible damage to both front ends. The silver car has a crumpled hood and visible smoke/fumes emanating from beneath the front of the vehicle, which are strong indicators of an actual crash.
Video Verification	True
Video Verification Note	The video clearly shows a black minivan backing into a silver car. Upon impact, the silver car's front hood is visibly crumpled, and smoke/steam emanates from its front, indicating collision damage.

Severity Assessment



Score: 21 **Category:** MINOR

Severity Criteria

Lane Blockage Score	UNKNOWN

Lane Blockage Evidence	Roadway type is unclear; appears to be a paved area or parking lot, not a clearly defined highway with lanes.
Lane Blockage Confidence	UNKNOWN
Vehicle Count Score	1
Vehicle Count Evidence	Two vehicles, a dark minivan/wagon and a silver sedan, are involved in the collision.
Vehicle Count Confidence	1.0
Vehicle Type Score	0
Vehicle Type Evidence	Both vehicles appear to be passenger cars (minivan/wagon and sedan).
Vehicle Type Confidence	1.0
Hazards Score	3
Hazards Evidence	Smoke/steam is clearly visible emanating from the front of the silver sedan.
Hazards Confidence	0.9
Vehicle Orientation Score	1
Vehicle Orientation Evidence	Both vehicles are upright but are angled relative to each other and the general direction of flow, indicating a collision.
Vehicle Orientation Confidence	1.0
Damage / Deformation Score	1
Damage / Deformation Evidence	The front hood of the silver sedan is visibly crumpled. The front of the dark minivan/wagon also shows impact damage.
Damage / Deformation Confidence	0.9
Debris Extent Score	0
Debris Extent Evidence	No significant debris field is visible on the paved surface.
Debris Extent Confidence	1.0
Fire Visible Trigger	NO
Rollover Confirmed Trigger	NO
Major Structural Collapse Trigger	NO
Full Roadway Blocked Trigger	UNKNOWN
Large Debris Field Across Multiple Lanes Trigger	NO
Critical Unknown Count	1
Should Return Unknown	NO
Severity Notes / Uncertainty	

General Information

Camera ID	
Camera Name	
Description	
Public URL	
Latitude	
Longitude	
City	
Categories	
Route	
Milepost	
Direction	
Direction Confidence	
Weather	
Lane Count	
Operational Status	
Camera IP	

Vehicle Summary

Vehicle Count	2
Count Confidence	1.0
Type Confidence	1.0

People

People Visible	0
Injuries	NO
Signs	
Confidence	1.0

Hazards

Fire	NO
Smoke	YES
Debris	NO
Fluid Spill	YES
Notes	Smoke/steam is emanating from the front of the silver sedan.
Confidence	0.9

Lane Impact

Lanes Affected	
Shoulder	NO
Traffic Flow	stopped
Confidence	0.7
Notes	Two vehicles are stopped in a collision position on a paved surface, blocking movement in that area. It is unclear if this is a highway or a parking lot/private road.

Location in View

Region	center
Distance	near
Lane	
Shoulder	
Median	
Statement	Incident involving two vehicles on a paved surface, possibly a parking lot or low-speed road.

Media Inputs

Unannotated Image	/home/group1/chart-incident-management/chart-incident-management/Final Detection From Video Files/dashboard_runs/job_e48f36997577/best_accident_frame_raw.jpg
Annotated Image	/home/group1/chart-incident-management/chart-incident-management/Final Detection From Video Files/dashboard_runs/job_e48f36997577/best_accident_frame_annotated.jpg
Video	/home/group1/chart-incident-management/chart-incident-management/Final Detection From Video Files/dashboard_runs/job_e48f36997577/accident_context_clip_raw.mp4