

Caribbean Coral Reef Institute (CCRI) Water Quality Monitoring Lab University of Puerto Rico – Mayagüez Campus Department of Marine Sciences			
Document Title	Document Number	Version	
Field Sampling Log	Appendix F	1.0	

Field Team Member Names:

Date	Jan 16/25		01/16/25		01/16/25			
Time	10:24		10:40		11:15			
Site Code	CDH V10		COM V10		DFRR 70			
Parameter	R1	Depth	R1	Depth	R1	Depth	R1	Depth
Surface Temperature (°C)	27.70	0.55	27.70	0.66	28.09	0.65		
Surface Salinity (psu)	35.54	0.52	35.60	0.54	35.60	0.57		
Surface DO (mg/L)	6.35	0.48	6.48	0.57	6.50	0.56		
Surface pH_NBS	8.17	0.46	8.16	0.65	8.17	0.67		
Bottom Temperature (°C)	27.70	6.65	27.71	6.17	27.99	18.69		
Bottom Salinity (psu)	35.56	6.71	35.60	6.14	35.70	18.38		
Bottom DO (mg/L)	6.38	6.83	6.43	6.18	6.37	18.66		
Bottom pH_NBS	8.17	6.74	8.17	6.14	8.16	18.60		
Replicate	R1	R2	R1	R2	R1	R2	R1	R2
Secchi Depth 1 (m)		6.00		6.00		17.00		
Secchi Depth 2 (m)		6.50		6.50		19.00		
Secchi Depth 3 (m)		8.00		8.00		18.00		
Van Dorn Depth (m)	0.5	8.00	0.5	8.00	0.5	18		
TA/DIC (+50uL HgCl ₂)	+S	638	639	625	626	622	678	
BOD Bottle	+S	640	641	627	628	679	680	
Chl-a Bottle Number		642		629		681		
Turbidity Bottle Number		643		630		682		
Settleable Solids Bottle Number		644		631		683		
TSS Bottle Number		645		632		684		
Nutrients (80 µL H ₂ SO ₄ + filter on lab)		646		633		685		
TKN (38 µL H ₂ SO ₄ + filter on lab)		647		634		686		
Enterococcus Bag + time (h:min)	10:38	648	11:00	635	11:28	687		

+S = surface sample needed (~0.5m)

Notes: