

Caribbean Coral Reef Institute (CCRI) Water Quality Monitoring Lab University of Puerto Rico – Mayagüez Campus Department of Marine Sciences			
Document Title	Document Number	Version	
Field Sampling Log	Appendix F	1.0	

Field Team Member Names: *M. Olmeda, V. Mendez, A. Santiago*

Date	<i>Nov/11/21</i>							
Time	<i>11:41</i>							
Site Code	<i>MLUND5</i>							
Parameter	R1	Depth	R1	Depth	R1	Depth	R1	Depth
Surface Temperature (°C)	<i>29.58</i>	<i>0.54</i>						
Surface Salinity (psu)	<i>33.86</i>	<i>0.48</i>						
Surface DO (mg/L)	<i>6.34</i>	<i>0.50</i>						
Surface pH_NBS	<i>8.13</i>	<i>0.52</i>						
Bottom Temperature (°C)	<i>29.37</i>	<i>3.00</i>						
Bottom Salinity (psu)	<i>33.80</i>	<i>3.01</i>						
Bottom DO (mg/L)	<i>6.13</i>	<i>3.71</i>						
Bottom pH_NBS	<i>8.11</i>	<i>3.71</i>						
Replicate	R1	R2	R1	R2	R1	R2	R1	R2
Secchi Depth 1 (m)								
Secchi Depth 2 (m)								
Secchi Depth 3 (m)								
Van Dorn Depth (m)								
TA/DIC (+50uL HgCl)	+S	<i>53</i>	<i>54</i>					
BOD Bottle	+S	<i>55</i>	<i>56</i>					
Chl-a Bottle Number		<i>57</i>						
Turbidity Bottle Number		<i>58</i>						
Settleable Solids Bottle Number		<i>59</i>						
TSS Bottle Number		<i>60</i>						
Nutrients (80 µL H2SO4 + filter on lab)		<i>61</i>						
TKN (38 µL H2SO4 + filter on lab)		<i>62</i>						
Enterococcus Bag + time (h:min)		<i>63</i>						

+S = surface sample needed (~0.5m)

Notes: