

Caribbean Coral Reef Institute (CCRI) Water Quality Monitoring Lab University of Puerto Rico – Mayagüez Campus Department of Marine Sciences			
Document Title	Document Number	Version	
Field Sampling Log	Appendix F	1.0	

Field Team Member Names: M. Olmeda J. Colina, Capitan Julio (w.)

Date	Nov/20/24							
Time	10:29		11:20					
Site Code	PALN20		CABED5					
Parameter	R1	Depth	R1	Depth	R1	Depth	R1	Depth
Surface Temperature (°C)	28.98	0.49	29.12	0.55				
Surface Salinity (psu)	35.30	0.53	35.32	0.46				
Surface DO (mg/L)	6.35	0.51	6.21	0.47				
Surface pH_NBS	8.14	0.53	8.12	0.44				
Bottom Temperature (°C)	28.88	17.33	28.89	4.23				
Bottom Salinity (psu)	35.31	17.48	35.32	4.34				
Bottom DO (mg/L)	6.05	17.17	6.12	4.14				
Bottom pH_NBS	8.13	17.58	8.12	4.37				
Replicate	R1	R2	R1	R2	R1	R2	R1	R2
Secchi Depth 1 (m)	5.25		3.25m					
Secchi Depth 2 (m)	5.25		3.25m					
Secchi Depth 3 (m)	5.50		3.25m					
Van Dorn Depth (m)	0.5	16m	4m					
TA/DIC (+50uL HgCl)	+S	261	262	183	184			
BOD Bottle	+S	263	264	185	186			
Chl-a Bottle Number		265		187				
Turbidity Bottle Number		266		188				
Settleable Solids Bottle Number		267		189				
TSS Bottle Number		268		190				
Nutrients (80 µL H2SO4 + filter on lab)		269		191				
TKN (38 µL H2SO4 + filter on lab)		270		192				
Enterococcus Bag + time (h:min)	10:47	271	11:35	193				

+S = surface sample needed (~0.5m)

Notes: