California Closets - Exhibit C

PRE-SALE REPRESENTATIONS VS POST-SALE RESULTS

California Closets publicly represents that its products and services provide custom-fit design solutions, professional installation standards, post-installation support, and long-term warranty protection.

Documented project outcomes were materially inconsistent with several of those representations. Observed conditions included dimensional non-conformance, omitted design-process deliverables, installation protection deficiencies, unresolved post-installation defects, early hardware and electrical failures, and incomplete warranty remediation efforts.

This exhibit summarizes material inconsistencies between public-facing representations and the delivered installation outcome.

No.	Category	Public Representation	Documented Outcome	Impact
1	Custom Fit Seamless Integration	Systems are custom-designed to fit client needs and integrate seamlessly into the home Record Ref. C1	Installed units exhibited visible side gaps, oversized filler requirements, and non-flush built-in appearance Record Ref. C7	**Major** Core custom-fit representation not achieved
2	Design Process Visualization	Design process includes virtual 3-D modeling to review function, appearance, and final selections Record Ref. C2	3-D rendering not provided or reviewed prior to installation	**Moderate** Promised design-process step not completed
3	Installation Standards Home Protection	Installers are trained professionals who protect walls, floors, and the home during installation Record Ref. C3	Masonite floor/hallway protection not used despite requests/building requirements; excessive wall marks reported after installation Record Ref. C8 Record Ref. C9	**Major** Installation process inconsistency

No.	Category	Public Representation	Documented Outcome	Impact
4	Post-Installation Support	Company follows up after installation and makes adjustments as needed Record Ref. C4	Multiple service communications occurred without complete remediation Record Ref. Exhibit D	**Major** Service commitment not fulfilled
5	Product Durability	Systems are built to high standards and intended to stand the test of time Record Ref. C5	Lighting and push-to-open mechanism failures occurred shortly after installation Record Ref. Exhibit D Record Ref. C10 Record Ref. C11	**Major** Early performance concerns
6	Limited Lifetime Warranty	Custom-designed and installed products covered against defects in materials and workmanship Record Ref. C6	Warranty-related remediation requested multiple times without complete resolution Record Ref. Exhibit D	**Major** Warranty support concern