California Closets - Exhibit C

PUBLIC REPRESENTATIONS VS. DOCUMENTED OUTCOMES

The Company publicly describes its products and services as providing custom-fit design solutions, professional installation standards, post-installation support, and long-term warranty protection. The table below compares those statements, as summarized from the Company's public materials, with documented project outcomes. Impact ratings are the Customer's own assessment.

Exhibit B sets out the dimensional and functional conditions in detail, and **Exhibit D** sets out the service and follow-up history.

No.	Category	Public Representation	Documented Outcome	Impact (Customer-Assessed)
1	Custom Fit and Integration	Systems are custom-designed to fit client needs and integrate seamlessly into the home **Record Ref. C1**	Installed units show visible side gaps of approximately 2 inches, fillers of approximately 3 inches, and a non-flush built-in appearance (**Exhibit B**, rows 4 and 5) **Record Ref. C2**	**Major** Fit and finish differ from the representation
2	Design Process Visualization	Design process includes virtual 3-D modeling to review function, appearance, and final selections **Record Ref. C3**	Rendered views were included with the Plans signed October 16, 2025, the date the Contract was executed. No virtual 3-D review of function, appearance, and final selections with the Customer before installation is documented. **Record Ref. B1**	**Moderate** Renderings provided; no 3-D review documented
3	Installation Standards and Home Protection	Installers are trained professionals who protect walls, floors, and the home during installation **Record Ref. C4**	Masonite floor and hallway protection was not used despite requests and building requirements. Wall marks were reported after installation. **Record Ref. C5** **Record Ref. C6**	**Major** Home-protection practices differed from the representation

No.	Category	Public Representation	Documented Outcome	Impact (Customer-Assessed)
4	Post-Installation Support	Company follows up after installation and makes adjustments as needed **Record Ref. C7**	Multiple service communications occurred without complete remediation (**Exhibit D**) **Record Ref. Exhibit D**	**Major** Follow-up did not resolve the reported conditions
5	Product Durability	Systems are built to high standards and intended to stand the test of time **Record Ref. C8**	Lighting and push-to-open mechanism failures were reported shortly after installation (**Exhibit D**) **Record Ref. Exhibit D** **Record Ref. C9** **Record Ref. C10**	**Major** Early performance problems reported
6	Limited Lifetime Warranty	Custom-designed and installed products are covered against defects in materials and workmanship **Record Ref. C11**	Warranty-related remediation was requested multiple times without complete resolution (**Exhibit D**) **Record Ref. Exhibit D**	**Major** Warranty requests not completely resolved