| | | | |
|---|---|---|---|
| Identification | Receiving Date: | 04/17/2026 | |
| | Kit/Tray Name: | 2840 | Loose instruments Returned: ☒ Yes ☐ No |
| | Tracking Number: | 870545167868 | |
| Incoming Insp.& Cleaning | Bioburden present: | ☐ Yes (describe):<br>☒ No | |
| | Cleaning performed:<br>(multiple choices possible) | ☐ Yes<br>☐ Manual precleaning (prior to automated cleaning)<br>☐ Ultrasonic cleaning, Equipment ID:<br>☐ Automated cleaning, Equipment ID:<br>Doc. No(s)., Rev.:<br>☐ No | |
| | Confirmation: | Name: DM | Date: 04/17/2026 |
| Instrument Tray Check In / Inspection | Inspection Date: | 04/17/2026 | |
| | Returning Distributor (ISP) /Customer: | Bay Fusion | |
| | Functional Inspection: | ☐ Yes Doc. No., Rev.:<br>☐ No<br>Torque test result [Nm]: | Test Equipment ID: |
| | Identification number of the tray/lid match: | ☐ No (describe):<br>☐ Yes | |
| | Additional cleaning performed:<br>(multiple choices possible) | ☐ Yes<br>☐ Manual precleaning (prior to automated cleaning)<br>☐ Ultrasonic cleaning, Equipment ID:<br>☐ Automated cleaning, Equipment ID:<br>Doc. No(s)., Rev.:<br>☐ No | |
| | Lubrication carried out? | ☐ Yes ☐ N/A | |
| | Damaged items identified? | ☐ No ☐ Yes (REF, Lot/SN): | |
| | Extra Items identified? | ☐ No ☐ Yes (REF, Lot/SN): | |
| | Expired item identified? | ☐ No ☐ Yes (REF, SN): | |
| | Physically missing items? | ☐ No ☐ Yes (REF, Lot/SN): | |
| | Articles, Lots/SNs and qty. match in Surgio Health? | ☐ Yes ☐ No (REF, Lot/SN): | |
| | Moved to "Lot code discrepancy" location in Surgio Health | ☐ No ☐ Yes (REF, Lot/SN): | |
| | Generate **CN** (if applicable) | ☐ N/A **CN #:** | |
| | Confirmation: | Name: | Date: |
| Closing | Case Number (if applicable): | 957646 | |
| | Return Transfer Number: | | |
| | System updated: | Name: Dwayne Mills Date: | Signature: |