Identification	Receiving Date:	04/13/2026	
	Kit/Tray Name:	940	Loose instruments Returned: ☐ Yes ☐ No
	Tracking Number:	10028260715300085260008703716095 95	
Incoming Insp.& Cleaning	Bioburden present:	☐ Yes (describe): ☐ No	
	Cleaning performed: (multiple choices possible)	☐ Yes ☐ Manual precleaning (prior to automated cleaning) ☐ Ultrasonic cleaning, Equipment ID: ☐ Automated cleaning, Equipment ID: Doc. No(s)., Rev.: ☐ No	
	Confirmation:	Name:	Date:
Instrument Tray Check In / Inspection	Inspection Date:		
	Returning Distributor (ISP) /Customer:	Broarka	
	Functional Inspection:	☐ Yes Doc. No., Rev.: ☐ No Torque test result [Nm]:	Test Equipment ID:
	Identification number of the tray/lid match:	☐ No (describe): ☐ Yes	
	Additional cleaning performed: (multiple choices possible)	☐ Yes ☐ Manual precleaning (prior to automated cleaning) ☐ Ultrasonic cleaning, Equipment ID: ☐ Automated cleaning, Equipment ID: Doc. No(s)., Rev.: ☐ No	
	Lubrication carried out?	☐ Yes ☐ N/A	
	Damaged items identified?	☐ No ☐ Yes (REF, Lot/SN):	
	Extra Items identified?	☐ No ☐ Yes (REF, Lot/SN):	
	Expired item identified?	☐ No ☐ Yes (REF, SN):	
	Physically missing items?	☐ No ☐ Yes (REF, Lot/SN):	
	Articles, Lots/SNs and qty. match in Surgio Health?	☐ Yes ☐ No (REF, Lot/SN):	
	Moved to "Lot code discrepancy" location in Surgio Health	☐ No ☐ Yes (REF, Lot/SN):	
	Generate **CN** (if applicable)	☐ N/A **CN #:**	
	Confirmation:	Name:	Date:
Closing	Case Number (if applicable):	960025	
	Return Transfer Number:		
	System updated:	Name: Date:	Signature: