Identification	Receiving Date:		
	Kit/Tray Name:	3105	Loose instruments Returned: ☒ Yes ☐ No
	Tracking Number:		
Incoming Insp.& Cleaning	Bioburden present:	☐ Yes (describe): ☒ No	
	Cleaning performed: (multiple choices possible)	☐ Yes ☐ Manual precleaning (prior to automated cleaning) ☐ Ultrasonic cleaning, Equipment ID: ☐ Automated cleaning, Equipment ID: Doc. No(s)., Rev.: ☒ No	
	Confirmation:	Name: DM	Date:
Instrument Tray Check In / Inspection	Inspection Date:		
	Returning Distributor (ISP) /Customer:	Arc Surgical	
	Functional Inspection:	☒ Yes Doc. No., Rev.: 0331US.2025-10 ☐ No Torque test result [Nm]: NA	Test Equipment ID: NA
	Identification number of the tray/lid match:	☐ No (describe): ☒ Yes	
	Additional cleaning performed: (multiple choices possible)	☐ Yes ☐ Manual precleaning (prior to automated cleaning) ☐ Ultrasonic cleaning, Equipment ID: ☐ Automated cleaning, Equipment ID: Doc. No(s)., Rev.: ☒ No	
	Lubrication carried out?	☒ Yes ☐ N/A	
	Damaged items identified?	☒ No ☐ Yes (REF, Lot/SN):	
	Extra Items identified?	☒ No ☐ Yes (REF, Lot/SN):	
	Expired item identified?	☒ No ☐ Yes (REF, SN):	
	Physically missing items?	☒ No ☐ Yes (REF, Lot/SN):	
	Articles, Lots/SNs and qty. match in Surgio Health?	☒ Yes ☐ No (REF, Lot/SN):	
	Moved to "Lot code discrepancy" location in Surgio Health	☒ No ☐ Yes (REF, Lot/SN):	
	Generate **CN** (if applicable)	☒ N/A **CN #:**	
	Confirmation:	Name: JW	Date:
Closing	Case Number (if applicable):	957694	
	Return Transfer Number:	52236	
	System updated:	Name: Jaden Williamson Date:	Signature: