Identification	Receiving Date:	04/10/2026	
	Kit/Tray Name:	387	Loose instruments Returned: ☐ Yes ☒ No
	Tracking Number:	Terry Return	
Incoming Insp.& Cleaning	Bioburden present:	☐ Yes (describe): ☒ No	
	Cleaning performed: (multiple choices possible)	☐ Yes ☐ Manual precleaning (prior to automated cleaning) ☐ Ultrasonic cleaning, Equipment ID: ☐ Automated cleaning, Equipment ID: Doc. No(s)., Rev.: ☒ No	
	Confirmation:	Name: Blaze Claeson	Date: 04/10/2026
Instrument Tray Check In / Inspection	Inspection Date:	04/10/2026	
	Returning Distributor (ISP) /Customer:	Innotec	
	Functional Inspection:	☒ Yes Doc. No., Rev.: 0248US.2025-11 ☐ No	
		Torque test result [Nm]: N/A	Test Equipment ID: N/A
	Identification number of the tray/lid match:	☐ No (describe): ☒ Yes	
	Additional cleaning performed: (multiple choices possible)	☐ Yes ☐ Manual precleaning (prior to automated cleaning) ☐ Ultrasonic cleaning, Equipment ID: ☐ Automated cleaning, Equipment ID: Doc. No(s)., Rev.: ☒ No	
	Lubrication carried out?	☒ Yes ☐ N/A	
	Damaged items identified?	☒ No ☐ Yes (REF, Lot/SN):	
	Extra Items identified?	☒ No ☐ Yes (REF, Lot/SN):	
	Expired item identified?	☒ No ☐ Yes (REF, SN):	
	Physically missing items?	☒ No ☐ Yes (REF, Lot/SN):	
	Articles, Lots/SNs and qty. match in Surgio Health?	☒ Yes ☐ No (REF, Lot/SN):	
	Moved to "Lot code discrepancy" location in Surgio Health	☒ No ☐ Yes (REF, Lot/SN):	
	Generate **CN** (if applicable)	☒ N/A **CN #:**	
	Confirmation:	Name: Blaze Claeson	Date: 04/10/2026
Closing	Case Number (if applicable):	962205	
	Return Transfer Number:	52099	
	System updated:	Name: Blaze Claeson Date: 04/10/2026 Signature:	