

# Vegetation Overgrowth Inspection Report for 2025-11-13

## Introduction

### Objective:

Schedule inspection task for specific road segment.

### Scope of Work:

Details of the roads that require vegetation inspection.

Update the vegetation situation of road segments that require vegetation inspection.

## Inspection Schedule

For 2025-11-13

segment_id	Inspector ID	Inspection ID
18	5	749
19	1	750
20	2	751
21	3	752

# Inspection Location Details

## Segment Maps:

Maps showing the specific segments of the road where vegetation needs clearing.

## Segment Location Details.

Segment ID	GPS Coordinates EPSG:27700	Road Section
18	1127.31	POINT(603820.5000025216 260206.4189003497)
19	497.58	POINT(597716.3190054032 263106.33790064533)
20	551.58	POINT(597724.8090054265 263119.7379006574)
21	274.67	POINT(597514.2130059018 263265.1179007562)

## Segment Detail Images

### Location for Segment: 18




Aerial



Map

---

## Location for Segment: 19



Aerial



Map

---

**Location for Segment: 20**



Aerial



Map

---

**Location for Segment: 21**




Aerial




Map

## Inspection Result

### Inspection Result for Segment: 18



Horiz




Veg




Vert

---

## Inspection Result for Segment: 19



Horiz




Veg




Vert

---

## Inspection Result for Segment: 20



Horiz




Veg




Vert

## Inspection Result for Segment: 21



Horiz



Veg



Vert