

MERIDIAN ELEVATOR SERVICES

Annual Safety Inspection Certificate

Certificate No: MES-2026-4100
Unit ID: D97-6
Building: Kestrel Plaza
Address: 88 Ninth Ave, Denver, CO 80202
Unit Type: Freight
Capacity (lbs): 4000
Inspection Date: 01/13/2026
Next Due: 01/13/2027
Inspector: A. Vasquez
Result: FAIL
Invoice Total: \$1,766.82

Defects Noted:

- Buffer oil level low
- Governor tripping speed out of range
- Door restrictor worn beyond tolerance