

MERIDIAN ELEVATOR SERVICES

Annual Safety Inspection Certificate

Certificate No: MES-2026-4124
Unit ID: C94-4
Building: Kestrel Plaza
Address: 88 Ninth Ave, Denver, CO 80202
Unit Type: Traction Passenger
Capacity (lbs): 6000
Inspection Date: 05/13/2026
Next Due: 05/13/2027
Inspector: R. Okonkwo
Result: FAIL
Invoice Total: \$317.14

Defects Noted:

- Pit ladder handhold missing