

Fleet Maintenance Report

Company: Gulf Coast Logistics Services **Report Date:** April 8, 2025
Fleet ID: GCLS-HOU-FLT-01 **Prepared By:** Fleet Maintenance Department

Vehicle Information

Field	Details
Vehicle ID	TRK-2071
License Plate	TX-5QR-2287
Make / Model	Volvo VNL 860
Year	2019
VIN	4V4NC9EH3KN456789
Engine Type	Volvo D13
Odometer Reading	301,550 miles
Assigned Route	Texas Corridor Express
Primary Driver	D. Brown

Maintenance Summary

Service Type: Preventive Maintenance (PM-D) – 300,000 Mile Interval
Service Location: Houston Fleet Maintenance Facility
Work Order #: WO-2025-04-2071
Service Date: April 7, 2025
Technician: R. Thompson (ASE Certified)

Inspection Checklist

Engine & Powertrain

- ✓ Engine oil level checked – within spec
- Engine oil & filter replaced
- Fuel filters replaced (primary & secondary)
- ✓ Coolant level inspected – topped off 0.3 gal
- Turbocharger showing slight play – monitor closely

Transmission

- Transmission fluid replaced
- ✓ No abnormal noise or vibration

Braking System

- Front brake pads at 22% remaining – immediate replacement recommended
- Rear brake pads at 35% remaining – schedule replacement
- ✓ Air brake system pressure test – passed

Suspension & Steering

- ✓ Steering linkage inspected – no play
- All four shocks showing wear – replace at next service
- ✓ Leaf springs intact, one bushing cracked – replace at next service

Tires

Position	Tread Depth	Condition
Steer Axle L	4/32"	Worn – replace soon
Steer Axle R	4/32"	Worn – replace soon
Drive Axles	6/32" avg	Moderate wear

Tire pressure adjusted to manufacturer specification (110 PSI steer, 100 PSI drive)

Electrical System

- Battery voltage: 12.3V – battery load test recommended
- ✓ Alternator output within range
- Replaced two clearance lights

Safety & Compliance

- ✓ DOT inspection completed
- ✓ Fire extinguisher certified
- ✓ Emergency triangles present
- ✓ ELD system operational

Diagnostic Scan Results

- No active engine fault codes
- Historical codes: DEF level low, DPF regen required (both resolved)
- Emissions system functioning normally

Parts Replaced

Part	Part Number	Qty
Engine Oil Filter	VLV-D13-FLT	1
Fuel Filter Kit	FF-VD13-KIT	1
15W-40 Synthetic Oil (gal)	OIL-1540-SYN	11
Transmission Fluid (qt)	TF-VLV-ATD	8
Clearance Light Assembly	CL-AMB-TRK	2

Labor Summary

Task	Hours
Preventive Maintenance Service	5.0
Brake Inspection	1.5
Transmission Service	1.0
Electrical Repair	0.5

Diagnostic Scan	0.5
Total Labor Hours	8.5 hrs

Cost Summary

Category	Cost
Parts	\$1,142.00
Labor	\$977.50
Shop Supplies	\$75.00
Total Service Cost	\$2,194.50

Upcoming Recommended Maintenance

Item	Recommended At
Front Brake Pad Replacement	IMMEDIATE – schedule within 5,000 miles
Steer Tires Replacement	ASAP – below safe threshold
Battery Replacement	305,000 miles
Shock Absorbers (all)	310,000 miles
Annual DOT Inspection	April 2026

Vehicle Status

Current Condition:	Roadworthy
Released to Service:	April 7, 2025
Next Scheduled Maintenance:	305,000 miles or 60 days (whichever occurs first)