

HALITE
Maintenance Intelligence
Assets
Service Records
Diagnostics
Review Queue
9
Ingest
Knowledge Graph
Settings
Service history intelligence for maintenance teams
Analysis
The ranking reflects how directly each component is linked to the observed crack on the drag angle. 1) DRAG ANGLE is top because three fleet records explicitly describe cracks in drag angles (SWIA2025122876590, SWIA2026070676519, SWIA2025112576494). These matches are active and mention removal or damage, making them the strongest evidence. 2) ANGLE is second with a higher evidence count (17) but the cited records (AALA202504164624, AALA202511175408) refer to corrosion or cracks in general angles rather than the specific drag angle, so the relevance is slightly lower. 3) STRINGER SPLICE appears third; its four records (SWIA2026070606541, SWIA2025120676586, SWIA2025120576544) involve splice issues, which can affect drag angle integrity but are less directly tied to a crack. 4) FRAME is fourth with a single record (SWIA2025122076513) that mentions a frame issue; it is less specific to the drag angle symptom. 5) STRINGER is fifth; its five records (SWIA2026070676558, SWIA2025120676529, SWIA2026070676497) describe stringer problems that may indirectly influence the drag angle but provide the weakest direct correlation.
✓ 12 cited record IDs verified against the graph. This confirms the records exist, not that every statement is supported by them.
Evidence Records
SWIA2025122076513
813SK · 2025-12-20 · FRAME
SWIA2025112576494
813SK · 2025-11-25 · DRAG ANGLE
SWIA2026070676558
813SK · 2025-12-13 · STRINGER
SWIA2025120676586
813SK · 2025-12-06 · STRINGER SPLICE