

BUILDING SAFETY CERTIFICATE

To be filled by the inspection officer (Asst. Engineer)

(Re: G.O. Ms.20/70/PWD Dt.13-01-1970)

- | | | | | | | | | | |
|---|---|---------------------------|-----------|----------------------|-----------|----------------------|-----------|----------|---------------|
| 1. Name of the Officer | :- Sub Divisional Engineer, P.W subdivision (Rural), Nagpur. | | | | | | | | |
| 2. Name of the School | :- Late Durgabai Mulik education Society Sanskar Vidya Sagar School. | | | | | | | | |
| 3. Location with name of Education District Sub District | :- Digori Gonhisim Tah. Nagpur (Rural) Dist. Nagpur | | | | | | | | |
| 4. Classification of Building as specified in column 4 of the application for fitness Certificate and size. | <table border="0" style="width: 100%;"><tbody><tr><td style="width: 60%;">:- R.C.C. Frame Structure</td><td style="width: 40%;">(2019-20)</td></tr><tr><td>:- G.F - 3.80 Height</td><td>(2017-18)</td></tr><tr><td>:- F.F - 3.80 Height</td><td>(2019-20)</td></tr><tr><td>:- S.F -</td><td>(In Progress)</td></tr></tbody></table> | :- R.C.C. Frame Structure | (2019-20) | :- G.F - 3.80 Height | (2017-18) | :- F.F - 3.80 Height | (2019-20) | :- S.F - | (In Progress) |
| :- R.C.C. Frame Structure | (2019-20) | | | | | | | | |
| :- G.F - 3.80 Height | (2017-18) | | | | | | | | |
| :- F.F - 3.80 Height | (2019-20) | | | | | | | | |
| :- S.F - | (In Progress) | | | | | | | | |
| 5. Period for which the certificate is issued | :- 2022-2023 | | | | | | | | |
| 6. Nature of defects, if any | | | | | | | | | |
| a) Foundation and basement | :- | | | | | | | | |
| b) SuperStructure | :- | | | | | | | | |
| c) Door and Windows | :- | | | | | | | | |
| d) Wood work wrought and put up | :- | | | | | | | | |
| e) Roof | :- | | | | | | | | |
| f) Flooring | :- | | | | | | | | |
| g) Miscellaneous (Crackes etc.) | :- | | | | | | | | |
| | } No Any defects Occure | | | | | | | | |
| 7. Any major defects noticed which will render the building unsafe in any manner. | :- No | | | | | | | | |
| 8. Whether maintenance woks have been done property | :- Seen | | | | | | | | |
| 9. Whether the structure is sound or not conducting classes | :- Structure is Good Condition | | | | | | | | |

Note :- 1 *The stability of the structure should be examined also with reference to location, altitude, instensity of wind, exposure of flood etc.*
2 *Any additional observation if demed necessary for the certificate may be furnished separately with this certificate.*

CERTIFICATE

Certified that the structure of School Building was inspected by me on Dt. 10/12/2022 and found to be fit / unfit to conduct classes for the period 2022-2023 For the reason stated above. Necessary certificate regarding Electrification Fitness and Fire fighting provision as per Building Code be obtained by owner of Building.

Place : Nagpur

Date : ~~05-05-2022~~

10.12.22


Sub Divisional Engineer

P.W. Subdivision (Rural)

Nagpur


Executive Engineer

Public Works Division No.2

Nagpur