


Mechanic's HUD



LUNADINO



Tomáš Novotný, Nikola Blaňárová,
Martin Červený, Tomáš Soukal

Vize

- revizní scénář (dokončený, přerušený, zaseknutý)
- AI component inspector
- kreslení virtuálním stylusem



Plane #4779F

Next flight: in 2 days

Some important info
Plane manager would like to see:



Reported problems

1 Oil leak

[Assign employee](#)

Required tasks

1 Oil change required

[Assign employee](#)

1 Check A required

[Assign employee](#)

Tasks history

12.3.2019 Oil change 1

[Assign employee](#)

10.3.2019 Check A

[Assign employee](#)

01.3.2019 Check B

[Assign employee](#)

01.3.2019 Something


[Assign employee](#)

Remove this part



Remove this part

Carefully remove this part
using this tool



! Be careful when doing
this because that can
happen

◀ Prev

Done ▶

Worklog

| | |
|-------|---------------------|
| 12:30 | Done that |
| 12:36 | Check: part X fine |
| 12:46 | Removed that part |
| 12:59 | Problem: Part Y bad |
| 13:09 | Part Y replaced |

! Problem found

Start engine



Start engine

Start engine to see if it works

! Your colleagues were warned. Wait for them to clear the area.

◀ Prev

Finish ▶

Worklog

| | |
|-------|---------------------|
| 12:30 | Done that |
| 12:36 | Check: part X fine |
| 12:46 | Removed that part |
| 12:59 | Problem: Part Y bad |
| 13:09 | Part Y replaced |
| 13:20 | Assembly |
| 13:30 | Engine start |

! Problem found

Problem



Problem found

! Fatal problem discovered.
It's impossible to continue.



3 more pictures

Edit report

Finish ▶

Worklog

| | |
|-------|---------------------|
| 12:30 | Done that |
| 12:36 | Check: part X fine |
| 12:46 | Removed that part |
| 12:59 | Problem: Part Y bad |
| 13:09 | Part Y replaced |


! Problem found


Remove this part



Remove this part

Carefully remove this part
using this tool



 Be careful when doing
this because that can
happen

WARNING

Elon Musk is starting the
engine. Get out!

Worklog

| | |
|-------|---------------------|
| 12:30 | Done that |
| 12:36 | Check: part X fine |
| 12:46 | Removed that part |
| 12:59 | Problem: Part Y bad |
| 13:09 | Part Y replaced |





◀ Prev

Done ▶

 Problem found

Heads-up UI

- tap-to-center UI
 - přivolání pomoci
 - pořízení vizuálního záznamu
-
- UX, které uživatel zná
(= šťastný mechanik :))



The background image is a close-up of a radial engine from a vintage biplane. The engine has eight cylinders arranged in a circle. The wings are visible on either side, with a circular logo on the left wing that reads "SURVEYOR" and "WILLIAMS". The scene is outdoors on a grassy field.

Can you continue your task?

No

Yes

All done

Finished



Worklog

- | | |
|-------|---------------------|
| 12:30 | Done that |
| 12:36 | Check: part X fine |
| 12:46 | Removed that part |
| 12:59 | Problem: Part Y bad |
| 13:09 | Part Y replaced |
| 13:20 | Assembly |
| 13:30 | Start engine |
| 13:45 | Finished |

Vaše dotazy



LUNADINO

Src

<https://pxhere.com/en/photo/565307>

<https://www.acc.af.mil/News/Art/igphoto/2001042283/>

https://www.flaticon.com/free-icon/edit_1159876#term=notes&page=1&position=59

https://www.flaticon.com/free-icon/open-wrench-tool-silhouette_25371#term=wrench&page=1&