


OCCUPANCY CERTIFICATE


As per Rule no. 17 of Model Rajasthan (Urban Area) Building Regulation, 2020, I do hereby certify:-

That the building "PALLACIA" constructed on A-2, Prithviraj Road, Near NCR Building Jaipur, (Rajasthan) owned and developed OM METALS CONSORTIUM Pvt. Ltd. having registered office at Ramakrishna Sadan, Ground Floor, 63, Sir Pochkhanawala Road, Near Worli, R.T.O. Mumbai-400025, for which completion certificate was issued by Jaipur Development Authority, has been inspected by me, the building constructed is as per approved maps & is as per prevailing building bye-laws. It is certified that essential facilities as mentioned in Rule no. 17.1 of Model Rajasthan (Urban Area) Building Regulation, 2020. Has been found on site thus the building is complete for Occupancy. Hence the Occupancy Certificate is issued under my signature on 28.04.2022.

Architect: BRAHMANAND KUMAWAT
COA REGISTRATION NO -CA/203/59525
EMPANELMENT REGISTRATION NO -CTP RAJ/ARCHITECT/2021/61



Ar. Brahmanand Kumawat
B.Arch.
CA/2013/59525



Ar-BRAHMA NAND KUMAWAT
CTP Raj/Architect/2021/61


Subject: General check list for completion/ occupancy Certificate.

- 1 Name of Plot Owner/ Developer:- **OM Metal Consortium PVT.LTD.**
- 2 Ownership details:-
 - . Date of Issue of Lease Deed:20/08/2010
 - . Type of Plot : (Auctioned/ Allotted/ Converted under 90- A Rules/ Other) - Other
- 3 Name of Present Owner:
- 4 Use of Plot (Land Use) (As per Lease Deed):-**Residential**
- 5 Plot no./ Address of Building/ Site :**A-2,Prithviraj Road ,C-Scheme,Jaipur**

- 6 Plot Area (As per Approved Building Plan) : **19125.45 SQM.**
- 7 Approval of Building Plan vide committee meeting dated : **201, 21-02-2018**
- 8 Building Plan Approved as per Building Byelaws- 2000/2010/2013/2017/2020 :.
- 9 Date of Release of approved building Plan :- **20-07-2021**
- 10 Inspection Report :
 - . Date of Start of Construction :- 30/01/2012
 - . Date of Completion : 20/07/2021
 - . Date of Site Inspection : 27-04-2022

Following Parameters to be checked during inspection for Completion Certificate:

A- Technical Parameters :					
S. No.	Details	Comments		Essentials	
		As per approved Plan	As per Site	For Completion	For at the time of Utilization Certificate
1	Size of the Plot (Sq.mt)	19125.45	19125.45	-	-
2	Width of Road/ Roads	90'-0" WIDE		-	-
3	Direction/ Facing of Plot (East/ West/ North/ South/ Other)	NORTH	NORTH	-	-
4	Setbacks Direction				
	Front North	15.46 MTR	15.46 MTR	-	-
	Side I West	10.06 Mtr	10.06 Mtr	-	-
	Side II East	10.0 Mtr	10.0 Mtr	-	-
	Rear South	10.18 Mtr	10.18 Mtr	-	-
5	(i.) Ground Coverage	38.84 Mtr	38.84 Mtr	-	-
	(ii.) Basement Floor/Floors/ Stilt Floor/ Podium if any				
	(iii.) Ramp (Slope)	1:8	1:8	-	-
	(iv.) No. of Staircase	21			
		. Riser 0.3	0.3	-	-
		. Tread 0.15	0.15	-	-
		. Width 1.2	1.2	-	-
	(v.) Lift/ Elevator/ Escalator			Installed (Yes/ No)	Operational (Yes/ No)
	No. of Lift	29	29	YES	YES
	Size of Lift	1.9X2.5,2.7X1.9,1.90X1.90,1.90X2.14, 1.60X2.10			


Ar-BRAHMA NAND KUMAWAT
CTP Raj/Architect/2021/61

6	(i.)	Height (From Plinth Level)	30.0 M	30.0 M		
	(ii.)	No. of Floor	3B+G+8	3B+G+8	-	-
	(iii.)	Total Height Excluding parapet/ Mumty/ Lift Machine Room/ any other architectural element	30.0 M	30.0 M	-	-
		Including parapet/ Mumty/ Lift Machine Room/ any other architectural element	As Per Elevation Approved	As Per Elevation Approved	-	-
7	F.A.R./B.A.R. (As applicable floor wise F.A.R./B.A.R.)		42970.65 sq.mt.	42970.65 sq.mt.	-	-
8	Height of Compound wall		Builder has confirm that they are submitting a presentation to competent Authority regarding front wall	AS per Site	-	-
	No. of Entry/Exit & width		02(10.10 m,9.0 M)	02(10.10 m,9.0 M)	-	-
	Security Room Size		NA	NA	-	-
	Other Services in Setback		Sub station, Gas Bank, Ventilation cut-out for basement, Entry/Exit	As per approved plan	-	-

B- Parking Parameters :

S. No.	Details	Comments		Essentials	
		As per approved Plan	As per Site	For Completion	For at the time of Utilization Certificate
1	Total E.C.U. aquired	716.25 ECU		-	-
2	Total No. of Car Parking			-	-
	Basement (I,II,III)	B-1(78 CARS),B-2(213 CARS)B-3(286CARS)	Same as Approved plan	-	-
	Stilt			-	-
	Open Area	4	4	-	-
	Visitors	107.43		-	-
	Mechanical Car Parking	NA	NA	-	-
	Provision of Car Lift	NA	NA	-	-
3	Two Wheeler Parking	548	548	-	-

C- Safety Parameters (Fire & Structure):

S. No.	Details	Comments		Essentials	
		As per approved Plan	As per Site	For Completion	For at the time of Utilization Certificate
1	Certificate for Fire Safety and compliance of UDH order dated 21.01.2020 regarding Fire Safety	Available	Available	Installed (Yes)	Operational (Yes)
2	Certificate from Structural	Available	Available	-	-

D- Environmental Parameters :

S. No.	Details	Comments		Essentials	
		As per approved Plan	As per Site	For Completion	For at the time of Utilization Certificate

Signature

Ar-BRAHMA NAND KUMAWAT
CTP Raj/Architect/2021/61

1	Rain Water Harvesting	As per approval	Available	Installed (Yes)	Operational (Yes)
2	Waste Water Treatment/	NA	NA	-	-
3	line and Sewarage Treatment Plant	As per approval	Available	Installed (Yes)	Operational (Yes)
4	Provision of Solid Waste Management	-	-	-	-
5	Certificate for Environment Clearance (	Available	Available	-	-
6	Provision of Solar Panes/ Solar Water Heater	Available	Provided	Installed (Yes)	Operational (Yes)

E- Green Parameters :

S. No.	Details	Comments		Essentials	
		As per approved Plan	As per Site	For Completion	For at the time of Utilization Certificate
1	Plantation & Green area and Park/ Landscaping	As per approved	As per approval	-	-

F- Genral Parameters :

S. No.	Details	Comments		Essentials	
		As per approved Plan	As per Site	For Completion	For at the time of Utilization Certificate
1	Cut-Outs/ Open to Sky/ Ducts	As per approval	Available	-	-
2	Projections/ balconies etc. (Covered/	1.5 mt	1.5 mt.	-	-
3	Provision of Water Supply	As per approval	Available	-	-
4	Provision of Power/ Electrical connectivity including transformerr placement (if require)	As per approval	Available	-	Operational (Yes)
5	Site development including parking sinages,	As per approval	Available	-	-
6	Provisions for physically challenged persons	As per approval	Available	-	-
7	Architecture finishing i.e. paint false ceiling and interior furnishing etc.	As per approval	Available	-	-
8	Internal Changes Deviation if any	NA	NA	-	-
9	Any other Observation				

Architect :- Brahmanand Kumawat

Reg. No Provide by Coa:-CA/2013/59525

Reg. No Provide CTP (Raj):-CTP Raj./Aechitect/2021/61

Structure Engineer Signed.Certificate Dated 17.12.2020 Attached


Ar-BRAHMA NAND KUMAWAT
CTP Raj/Architect/2021/61