

BTS not found or type unknown	celljoint 15814039536
-------------------------------	--------------------------

Date: Sun, Oct 23, 2022 5:10 PM	Service type: Carry In	Expected Delivery Date: 2022-10-26
	Job sheet number: #CJ20221023171004	
Customer: Dinesh saminathan Mobile: 8668052624		Brand: Oppo Device: Mobile Phones Device Model: Oppo Reno 5 Serial Number: 12345678901234 Password: 12345678
Invoice No.:		29
Estimated Cost:		1000.00
Status:		Repair Received
Location:		celljoint
Pre Repair Checklist:		
Product Configuration:		
Condition Of The Product: Broken Glass, Sensor Not working, Camera Not working		
Parts used:		
Problem Reported By The Customer: Display Not Working, Display Broken, Display Glass Broken, Not Charging, No Wifi, No network		
Terms & conditions		
Customer signature:		Authorized signature: