	celljoint
Image not found or type unknown	15814039536

Date: **Tue, Oct 25, 2022 11:25 AM**	**Service type:** Carry In	**Expected Delivery Date:** **2022-10-30**
	Job sheet number: #CJ20221025112551	

Customer: Kumar Mobile: 9884893017	**Brand:** Oppo **Device:** Mobile Phones **Device Model:** Oppo Reno 5 **Serial Number:** 35555555555555555 **Password:** 123456
Invoice No.:	30
Estimated Cost:	1000.00
Status:	Job Accepted
Location:	celljoint
Pre Repair Checklist:	
Product Configuration:	

Condition Of The Product:
Broken Glass, Frame Broken, USB Port damaged

Parts used:	

Problem Reported By The Customer:
Display Not Working, Display Broken, Display Glass Broken

Passport	Image not found or type unknown
Passport	Image not found or type unknown
Terms & conditions	

Customer signature:	**Authorized signature:**

Image not found or type unknown