



**Inspection Report for ESN: E-577**

<b>Inspector</b>	Demo User (12345678)
<b>Template</b>	Passport Demo (v1)
<b>Location</b>	Air France Industries
<b>Operator</b>	Air
<b>Date Started</b>	2025-08-12 09:29
<b>Date Completed</b>	2025-08-12 09:39
<b>Engine Serial Number</b>	E-577
<b>Shop Visit Number</b>	8892979222

<b>Operator:</b> Air	<b>Engine Serial Number:</b> E-577
<b>Shop Visit Number:</b> 8892979222	<b>Date Completed:</b> 2025-08-12 09:39

<b>GE Passport Demo</b>
-------------------------

<b>Step</b>	Left Hand Side
-------------	----------------




<b>Operator:</b> Air	<b>Engine Serial Number:</b> E-577
<b>Shop Visit Number:</b> 8892979222	<b>Date Completed:</b> 2025-08-12 09:39

<b>Step</b>	Forward Looking Aft
-------------	---------------------



<b>Operator:</b> Air	<b>Engine Serial Number:</b> E-577
<b>Shop Visit Number:</b> 8892979222	<b>Date Completed:</b> 2025-08-12 09:39




<b>Step</b>	Right Hand Side
-------------	-----------------



<b>Parts</b>	
SV Actuator	Damaged
ACC Valve	Damaged
AGT Support Bracket	Installed



<b>Operator:</b> Air	<b>Engine Serial Number:</b> E-577
<b>Shop Visit Number:</b> 8892979222	<b>Date Completed:</b> 2025-08-12 09:39

<b>SV Actuator: Damage</b>	
	
Corroded	Corroded
	
Careful corrosion	


<b>Operator:</b> Air	<b>Engine Serial Number:</b> E-577
<b>Shop Visit Number:</b> 8892979222	<b>Date Completed:</b> 2025-08-12 09:39

**ACC Valve: Damage**



Now ready

<b>Operator:</b> Air	<b>Engine Serial Number:</b> E-577
<b>Shop Visit Number:</b> 8892979222	<b>Date Completed:</b> 2025-08-12 09:39





Operator: Air	Engine Serial Number: E-577
Shop Visit Number: 8892979222	Date Completed: 2025-08-12 09:39

Step	Engine Data Plate	
		
Parts		
Engine Data Plate	Installed	