

GAADI INSPECTOR

AI-assisted visible vehicle damage inspection

INSPECTION REPORT



GI-20260830-DEMO01

STATUS	DETECTED	ACCEPTED	REJECTED
REVIEW REQUIRED	2	1	0

Vehicle & inspection details

REG. NUMBER	BA 01 PA 1234	VEHICLE	2020 Toyota Corolla
INSPECTOR	Aayush Phuyal	PURPOSE	Used-vehicle assessment
CAPTURED	30 Aug 2026, 10:00 AM	SOURCE	Uploaded photo

Inspection evidence

ORIGINAL	AI-ANNOTATED
	

Detection review

ID	Damage	Confidence	Review	Inspector note
D-01	Dent	86.0%	Accepted	Visible deformation on the left door panel.
D-02	Scratch	67.0%	Needs review	Confirm under neutral lighting; reflection is present.

Image quality record

Resolution: 1400 x 900 (1.26 MP) - Brightness: Good - Sharpness: Good

IMPORTANT - This report is an AI-assisted preliminary assessment of visible exterior damage in the supplied image. It does not assess mechanical, structural, underbody or internal condition. A qualified human inspector must verify all detections and inspect the vehicle before insurance, purchase, safety or repair decisions.