

Check if Amendment	<input type="checkbox"/>
Check if Error Correction	<input type="checkbox"/>

ALABAMA UNIFORM TRAFFIC CRASH REPORT

Crash Report Case No. 0700065

# Vehicles	# Pedestrians	# Injured	# Fatalities	# Unit 1 Type	Unit 2 Type
2	0	0	0	3	5

Local Case No. 2020-00082592

Sheet 1

LOCATION AND TIME	Date	10	06	2020	Time	1247 MT	Day of Week	Tue	County	Jefferson	City	Rural	Local Zone	
		Month	Day	Year								<input checked="" type="checkbox"/>	3	
	Hwy Class.	3	On Street, Road, Highway	FORESTDALE BLVD		At Intersection of or Between (Node 1)		ALLEGHENY DR		And (Node 2)				
			(On) Street/ Road/Hiway		9999	1 2 <--- ---> Node Code	N/A		N/A		From Node 1			
	Mile Post	N/A	Control Access Hwy Loc	97	Primary Contrib Circums	24	Primary Contributing Unit #	1	First Harmful Event	22	First Harmful Event Location	1	Most Harmful Event	22
	Distance to Fixed Object	N/A	Roadway Junction/ Feature	1	Manner of Crash	7	Lat Coordinate	99	Long Coordinate	99	Coordinate Type	97	Hwy Side	1
	School Bus Related	1	Crash Severity	99	Distracted Driving	0								

1 UNIT NO	DRIVER	Driver Full Name	PAUL THOS RICHARDSON				Street Address	358 LOST CREEK RD				City and State	CARBON HILL AL		ZIP	35549	Telephone	2053196992					
		DOB	12	15	1953	Race	1	Sex	1	DL State	AL	Driver License No.	3196992	DL Class	99	DL Status	C	Restrict Violations	97	CDL Status	97	Endorse Violations	97
		Place of Employment	99														Residence Less Than 25 Miles	99					
		Liability Insurance Co.	Allstate				Liability Policy No.	985304918				Insurance NAIC Number											
		Driver Condition	1	Sobriety/ Officer Opinion	Alcohol: No Drugs: No		Type Alcohol Test Given	97	Alcohol Test Results	N/A	Type Drug Test Given	97	Drug Test Results	97	Maneuver	1							
		Most Harmful Event for MV	22	Travel Road Name	Forestdale Boulevard				Road Code	US78		Travel Direction	1	Unit Contributing Circumstance	24	Total Injuries in Unit	0						
		Sequence of Events	22	Event 1	97	Event 2	97	Event 3	97	Event 4	97	First Harmful Event Location	1	Areas Damaged Are Shaded									
		Veh Year	2009	Make	CHEV	Veh Model	SLV	Body	1	V.I.N.	1GCEC29049Z207544												
		Owner's Name	PAUL THOS RICHARDSON				License Tag Number	64BF919		State	AL	Year	99	14 Under Carriage									
		Street or R.F.D.	358 LOST CREEK RD				City	CARBON HILL		State	AL	Zip	35549	97 N/A									
		Type	3	Usage	1	Emergency Status	97	Placard Status		Placard Required	97	Hazardous Cargo	97	Hazardous Cargo Released?	97	10 2							
		Attachment	1	Oversized Load	N/A	If Yes, Did Owner Have Permit?	N/A	Contrib Defect	1	Speed Limit	N/A MPH	Est Speed	Unk MPH	Citation Offense(s) Charged	None	9 3							
		Damage Severity	2	Towed?	3	Vehicle Towed By Whom:				97				8 4									
		Towed To Where:	97														7 5						
																6 15 Attachment							
														Point of Initial Impact 12									

2 UNIT NO	DRIVER	Driver Full Name	TRACEY LYNN DAVENPORT				Street Address	1332 7TH WAY				City and State	Pleasant Grove AL		ZIP	35127	Telephone	2057395470					
		DOB	06	24	1986	Race	2	Sex	2	DL State	AL	Driver License No.	7395470	DL Class	99	DL Status	C	Restrict Violations	97	CDL Status	97	Endorse Violations	97
		Place of Employment	99														Residence Less Than 25 Miles	99					
		Liability Insurance Co.	Progressive				Liability Policy No.	940284607				Insurance NAIC Number											
		Driver Condition	1	Sobriety/ Officer Opinion	Alcohol: No Drugs: No		Type Alcohol Test Given	97	Alcohol Test Results	N/A	Type Drug Test Given	97	Drug Test Results	97	Maneuver	1							
		Most Harmful Event for MV	22	Travel Road Name	Forestdale Boulevard				Road Code	US78		Travel Direction	1	Unit Contributing Circumstance	24	Total Injuries in Unit	0						
		Sequence of Events	22	Event 1	97	Event 2	97	Event 3	97	Event 4	97	First Harmful Event Location	1	Areas Damaged Are Shaded									
		Veh Year	2003	Make	TOYT	Veh Model	4RN	Body	3	V.I.N.	JTETB17R930008530												
		Owner's Name	TRACEY LYNN DAVENPORT				License Tag Number	1AG3342		State	AL	Year	99	14 Under Carriage									
		Street or R.F.D.	1332 7TH WAY				City	Pleasant Grove		State	AL	Zip	35127	97 N/A									
		Type	5	Usage	1	Emergency Status	97	Placard Status		Placard Required	97	Hazardous Cargo	97	Hazardous Cargo Released?	97	11 1							
		Attachment	1	Oversized Load	N/A	If Yes, Did Owner Have Permit?	N/A	Contrib Defect	1	Speed Limit	N/A MPH	Est Speed	Unk MPH	Citation Offense(s) Charged	None	10 2							
		Damage Severity	2	Towed?	3	Vehicle Towed By Whom:				97				9 3									
		Towed To Where:	97														8 4						
																7 5							
														6 15 Attachment									
														Point of Initial Impact 6									

Seating Position Codes

2, 4, or 6 Passenger

9 Passenger (add):

12 Passenger (add):

Bicycle, Motorcycle, ATV

12 - Pedestrian

16 - Not in Passenger Compartment

123456

789

171819

1011

13 - Rider of Domestic Animal

14 - Occ. of Non-Motorized Vehicle

15 - Passenger of Bus

97 - Not Applicable

98 - Other (Explain)

99 - Unknown

UNINJURED OCCUPANTS																			
Unit No	Seat Pos	Occ. Type	Safety Equip.	Air-bag	Age Code	Sex	Ejec-tion	Birth Date		Unit No	Seat Pos	Occ. Type	Safety Equip.	Air-bag	Age Code	Sex	Ejec-tion	Birth Date	
1	1	1	2	2	9	1	1	12/15/1953		2	1	1	2	2	8	2	1	06/24/1986	

DIAGRAM

NARRATIVE

The driver of unit two stated she had to slow down quickly because traffic in front of her was stopped. The driver of unit one could not slow down fast enough and struck unit two in the rear causing damage to both vehicles.

ROADWAY ENVIRONMENT																							
Unit No.	1	Involved Road/ Bridge	1	Road Surface Type	1	Roadway Condition	1	Workzone Related?	97	Workzone Type	97	Workers Present ?	NotApplicable		Workzone Law Enforcement Present?		Contributing Circumstances Environment	99	1	Contrib Matl In Roadway	1		
Contrib Material Source	97	Rdway Curve & Grade	3	Vision Obscur ed By	1	Traffic Control	6	Traffic Control Functioning	1	Opposing Lane Separation	4	Trafficway Lanes	5	Turn Lanes	4	One-Way Street	No	Total # Occupant s In Unit	1	Total # Injured in Unit	0	Total # Killed in Unit	0
Total Number of Units		Light		Weather		Locale		Police Present?		DOT Railroad Crossing No.												N/A	
2		1		1		3		No															

ROADWAY ENVIRONMENT																										
Unit No.	2	Involved Road/Bridge	1	Road Surface Type	1	Roadway Condition	1	Workzone Related?	97	Workzone Type	97	Workers Present ?	NotApplicable		Workzone Law Enforcement Present?	99	Contributing Circumstances Environment	1	Contrib Matl In Roadway	1						
Contrib Material Source	97	Rdway Curve & Grade	3	Vision Obscur ed Bv	1	Traffic Control	6	Traffic Control Functioning	1	Opposing Lane Separation	4	Trafficway Lanes	5	Turn Lanes	4	One-Way Street	No	Total # Occupant s In Unit	1	Total # Injured in Unit	0	Total # Killed in Unit	0			
Total Number of Units		2		Light			1		Weather			1		Locale			3		Police Present?		No		DOT Railroad Crossing No.		N/A	
INVESTIGATION																										
Name of Photographer										N/A																
Time Police Notified		1247 MT		Time Police Arrived		1307 MT		Time EMS Arrived		N/A		EMS Response Run #		N/A												
Name of Investigating Officer										Officer ID		267969		Agency ORI								AL0010000				
Name of Investigating Officer										Officer ID				Agency ORI												
The data on this report reflects the best knowledge, opinion, and belief regarding the crash, but no warrant is made as to the factual accuracy thereof.																										

LEGEND							
Location	Category	Code	Description	Location	Category	Code	Description
Report Header	Unit Type	3	Pick-up	Driver	Race	2	Black / African-American
Report Header	Unit Type	5	Cargo van (10,000 lbs or less)	Driver	Residence Within 25 Miles	99	Unknown
Location And Time	Contributing Circumstance	24	Misjudge stopping distance	Driver	Travel Direction	1	North
Location And Time	Contributing Unit	10	Unit1	Vehicle	Attachment	1	None
Location And Time	Controlled Access Highway Location	97	Not a controlled access highway	Vehicle	Body	1	Two door
Location And Time	Coordinate Status	99	Unknown	Vehicle	Body	3	Two door with rear entry / hatchback
Location And Time	Coordinate Type	97	Not applicable	Vehicle	Citation Offense	99	None
Location And Time	Crash Manner	7	Rear end (front-to-rear)	Vehicle	Damage Severity	2	Minor
Location And Time	Crash Severity	99	Unknown	Vehicle	Defect	1	None
Location And Time	Distance Node Unit	0	Unknown	Vehicle	Emergency Status	97	Not applicable
Location And Time	Distracted Driving	0	Not Set	Vehicle	Estimated Speed Code	Unk	Unknown
Location And Time	Harmful Event	22	Collision with vehicle in traffic	Vehicle	Hazardous Cargo	97	Not applicable
Location And Time	Highway Classification	3	State	Vehicle	Hazardous Cargo Release Type	97	Not applicable
Location And Time	Highway Side	1	Northbound	Vehicle	K12 Child Going To Or From School	99	Unknown
Location And Time	Roadway Feature	1	No special feature	Vehicle	Make	CHEV	Chevrolet
Location And Time	School Bus Related	1	No school bus involved	Vehicle	Make	TOYT	Toyota
Location And Time	Time Display Format	20	Military	Vehicle	Non-Motorist Action	97	Not applicable
Driver	Alcohol Test Type	97	Not applicable	Vehicle	Non-Motorist Action	99	Unknown
Driver	Commercial Driver License Status	97	Not applicable / unlicensed	Vehicle	Non-Motorist Location	99	Unknown
Driver	Contributing Circumstance	24	Misjudge stopping distance	Vehicle	Oversized Load	N/A	NotApplicable
Driver	Driver Address Code	0	Not Set	Vehicle	Oversized Load Permit	N/A	NotApplicable
Driver	Driver Condition	1	Apparently normal	Vehicle	Owner Address Code	0	Not Set
Driver	Driver License Class Code	99	Unknown	Vehicle	Owner Name Code		Not Set
Driver	Driver License Endorsement	97	Not applicable	Vehicle	Placard Requirement	97	Not applicable
Driver	Driver License Number	0	Not set	Vehicle	Placard Status	0	Not Set
Driver	Driver License Restriction	97	Not applicable	Vehicle	Tag Number		Not set
Driver	Driver License State Code	0	Not set	Vehicle	Tag State	0	Not set
Driver	Driver License Status	C	Current / valid	Vehicle	Tag Year	99	Unknown
Driver	Driver Name Code	0	Not Set	Vehicle	Tow Status	3	Not towed
Driver	Drug Test Result	97	Not applicable	Vehicle	Towed Code	97	Not applicable
Driver	Drug Test Type	97	Not applicable	Vehicle	Unit Type	3	Pick-up
Driver	Gender	1	Male	Vehicle	Unit Type	5	Cargo van (10,000 lbs or less)
Driver	Gender	2	Female	Vehicle	Usage	1	Personal vehicle
Driver	Harmful Event	22	Collision with vehicle in traffic	Vehicle	VIN	0	Not set
Driver	Liability Ins. Policy Code	0	Not Set	Vehicle	Year		Not set
Driver	Liability Insurance NAIC Number Code		Not Set	Uninjured Occupants	Age Code	8	26 - 64
Driver	Maneuver	1	Movement essentially straight	Uninjured Occupants	Age Code	9	65 or older
Driver	Phone Number Code	0	Not Set	Uninjured Occupants	Airbag	2	Not deployed, no switch
Driver	Place of Employment	99	Unknown	Uninjured Occupants	Birth Date Code	0	Not Set
Driver	Race	1	White / Caucasian	Uninjured Occupants	Ejection Status	1	Not ejected or trapped

LEGEND							
Location	Category	Code	Description	Location	Category	Code	Description
Uninjured Occupants	Gender	1	Male				
Uninjured Occupants	Gender	2	Female				
Uninjured Occupants	Occupant Type	1	Driver				
Uninjured Occupants	Safety Equipment	2	Shoulder and lap belt used				
Roadway Environment	Environmental Contributing Circumstance	1	None apparent				
Roadway Environment	Light Condition	1	Daylight				
Roadway Environment	Locale	3	Shopping or business				
Roadway Environment	Opposing Lane Separation	4	Broken painted line				
Roadway Environment	Road Bridge Condition	1	None apparent				
Roadway Environment	Road Surface Type	1	Asphalt				
Roadway Environment	Roadway Condition	1	Dry				
Roadway Environment	Roadway Curvature And Grade	3	Straight, up grade				
Roadway Environment	Roadway Material	1	None				
Roadway Environment	Roadway Material Source	97	Not applicable				
Roadway Environment	Traffic Control	6	Traffic signals				
Roadway Environment	Traffic Control Status	1	Yes				
Roadway Environment	Trafficway Lane Count	5	Five lanes				
Roadway Environment	Turn Lane Presence	4	Both left and right turn lanes				
Roadway Environment	Vision Obscuration	1	Not obscured				
Roadway Environment	Weather Condition	1	Clear				
Roadway Environment	Workzone Law Enforcement Presence	99	Unknown				
Roadway Environment	Workzone Relationship	97	Not applicable				
Roadway Environment	Workzone Type	97	Not applicable				