

Check if Amendment	<input type="checkbox"/>
Check if Error Correction	<input type="checkbox"/>

## ALABAMA UNIFORM TRAFFIC CRASH REPORT

Crash Report Case No. 0700246

# Vehicles	# Pedestrians	# Injured	# Fatalities	# Unit 1 Type	Unit 2 Type
2	0	0	0	1	1

Local Case No. 2020-00082689

Sheet 1

LOCATION AND TIME	Date	10	06	2020	Time	1852 MT	Day of Week	Tue	County	Jefferson	City	Rural Jefferson	Local Zone	3			
	Hwy Class.	4	On Street, Road, Highway				At Intersection of or Between (Node 1)				And (Node 2)						
	9991				(On) Street/ Road/Hwy <--- Code	9992		1 2 <--- >---> Node Code	N/A		From Node 1						
	Mile Post	N/A		Control Access Hwy Loc	97	Primary Contrib Circums	8	Primary Contributing Unit #	1	First Harmful Event	22	First Harmful Event Location	1	Most Harmful Event	22		
	Distance to Fixed Object	N/A		Roadway Junction/ Feature	1	Manner of Crash	8	Lat Coordinate	99		Long Coordinate	99		Coordinate Type	97	Hwy Side	1
	School Bus Related	1		Crash Severity	O	Distracted Driving	0										

1 UNIT NO	DRIVER	Driver Full Name JENNIFER ILEEN ESSIG										Street Address 1225 PARK AVE										City and State Tarrant AL										ZIP 35217										Telephone 2055026344																																							
		DOB	12	13	1980	Race	1	Sex	2	DL State	AL	Driver License No. 9351731										DL Class	99	DL Status	C	Restrict Violations	97	CDL Status	97	Endorse Violations	97																																																		
		Place of Employment 99																										Residence Less Than 25 Miles 99																																																					
		Liability Insurance Co. Safeway										Liability Policy No. 3332810ALPP001										Insurance NAIC Number																																																											
		Driver Condition 1										Sobriety/ Officer Opinion										Alcohol: No Drugs: No										Type Alcohol Test Given 97										Alcohol Test Results N/A										Type Drug Test Given 97										Drug Test Results 97										Maneuver 2									
		Most Harmful Event for MV 22										Travel Road Name Old Springville Road										Road Code 9991										Travel Direction 1										Unit Contributing Circumstance 8										Total Injuries in Unit 0																													
		Sequence of Events 22										Event 1 97										Event 2 97										Event 3 97										Event 4 97										First Harmful Event Location 1										Areas Damaged Are Shaded																			
		Veh Year 2009										Make 99										Veh Model RIO										Body 2										V.I.N. KNAFG528297275201										14 Under Carriage																													
		Owner's Name JENNIFER ILEEN ESSIG										License Tag Number 1DS1475										State AL										Year 99										11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100																																							
		Street or R.F.D. 1225 PARK AVE										City Tarrant										State AL										Zip 35217										11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100																																							
		Type 1										Usage 1										Emergency Status 97										Placard Status										Placard Required 97										Hazardous Cargo 97										Hazardous Cargo Released? 97										11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100									
		Attachment 1										Oversized Load N/A										If Yes, Did Owner Have Permit? N/A										Contrib Defect 1										Speed Limit N/A MPH										Est Speed Unk MPH										Citation Offense(s) Charged None										11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100									
		Damage Severity 3										Towed? 3										Vehicle Towed By Whom: 97										11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100																																																	
		Towed To Where: 97										11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100										Point of Initial Impact 5																																																											

2 UNIT NO	DRIVER	Driver Full Name ROMEO MOISES ZEMPOALTECA										Street Address 5530 SOUTHFIELD RD N										City and State PINSON AL										ZIP 35126										Telephone 2053298286																																							
		DOB	09	04	2001	Race	1	Sex	1	DL State	AL	Driver License No. 9610846										DL Class	99	DL Status	C	Restrict Violations	97	CDL Status	97	Endorse Violations	97																																																		
		Place of Employment 99																										Residence Less Than 25 Miles 99																																																					
		Liability Insurance Co. State Farm										Liability Policy No. 4299626E0801A										Insurance NAIC Number																																																											
		Driver Condition 1										Sobriety/ Officer Opinion										Alcohol: No Drugs: No										Type Alcohol Test Given 97										Alcohol Test Results N/A										Type Drug Test Given 97										Drug Test Results 97										Maneuver 1									
		Most Harmful Event for MV 22										Travel Road Name Old Springville Road										Road Code 9991										Travel Direction 3										Unit Contributing Circumstance 97										Total Injuries in Unit 0																													
		Sequence of Events 22										Event 1 97										Event 2 97										Event 3 97										Event 4 97										First Harmful Event Location 1										Areas Damaged Are Shaded																			
		Veh Year 2014										Make INFI										Veh Model Q45										Body 2										V.I.N. JN1BV7AP4EM675741										14 Under Carriage																													
		Owner's Name ROMEO MOISES ZEMPOALTECA										License Tag Number RMZQ50										State AL										Year 99										11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100																																							
		Street or R.F.D. 5530 SOUTHFIELD RD N										City PINSON										State AL										Zip 35126										11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100																																							
		Type 1										Usage 1										Emergency Status 97										Placard Status										Placard Required 97										Hazardous Cargo 97										Hazardous Cargo Released? 97										11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100									
		Attachment 1										Oversized Load N/A										If Yes, Did Owner Have Permit? N/A										Contrib Defect 1										Speed Limit N/A MPH										Est Speed Unk MPH										Citation Offense(s) Charged None										11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100									
		Damage Severity 3										Towed? 3										Vehicle Towed By Whom: 97										11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100																																																	
		Towed To Where: 97										11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100										Point of Initial Impact 11																																																											

## Seating Position Codes

2, 4, or 6 Passenger

1	2	3
4	5	6

9 Passenger (add):

7	8	9
---	---	---

12 Passenger (add):

17	18	19
----	----	----

Bicycle, Motorcycle, ATV

10
11

12 - Pedestrian

13 - Rider of Domestic Animal

14 - Occ. of Non-Motorized Vehicle

15 - Passenger of Bus

16 - Not in Passenger Compartment

97 - Not Applicable


98 - Other (Explain)

99 - Unknown

## UNINJURED OCCUPANTS

Unit No	Seat Pos	Occ. Type	Safety Equip.	Air-bag	Age Code	Sex	Ejec-tion	Birth Date	Unit No	Seat Pos	Occ. Type	Safety Equip.	Air-bag	Age Code	Sex	Ejec-tion	Birth Date
1	1	1	2	2	8	2	1	12/13/1980	2	1	1	2	2	6	1	1	09/04/2001

## DIAGRAM



## NARRATIVE

Driver 1 stated that vehicle 1 was turning left at the green signal when vehicle 1 collided with vehicle 2.

Driver 2 stated that vehicle 2 was proceeding through the intersection with the green signal when vehicle 1 turned left in front of vehicle 2. This caused vehicle 1 to collide with vehicle 2.

## ROADWAY ENVIRONMENT

Unit No.	1	Involved Road/Bridge	1	Road Surface Type	1	Roadway Condition	1	Workzone Related?	97	Workzone Type	97	Workers Present ?	NotApplicable			Workzone Law Enforcement Present?	99	Contributing Circumstances Environment	1	Contrib Matl In Roadway	1		
Contrib Material Source	97	Rdway Curve & Grade	1	Vision Obscured By	1	Traffic Control	6	Traffic Control Functioning	1	Opposing Lane Separation	5	Trafficway Lanes	5	Turn Lanes	2	One-Way Street	No	Total # Occupants In Unit	1	Total # Injured in Unit	0	Total # Killed in Unit	0
Total Number of Units			Light			Weather			Locale			Police Present?			DOT Railroad Crossing No.								
2			4			1			3			No			N/A								

ROADWAY ENVIRONMENT																													
Unit No.	2	Involved Road/Bridge	1	Road Surface Type	1	Roadway Condition	1	Workzone Related?	97	Workzone Type	97	Workers Present ?	NotApplicable		Workzone Law Enforcement Present?	99	Contributing Circumstances Environment	1	Contrib Matl In Roadway	1									
Contrib Material Source	97	Rdway Curve & Grade	1	Vision Obscur ed Bv	1	Traffic Control	6	Traffic Control Functioning	1	Opposing Lane Separation	5	Trafficway Lanes	5	Turn Lanes	2	One-Way Street	No	Total # Occupant s In Unit	1	Total # Injured in Unit	0	Total # Killed in Unit	0						
Total Number of Units		2		Light			4		Weather			1		Locale			3		Police Present?		No		DOT Railroad Crossing No.		N/A				
INVESTIGATION																													
Name of Photographer												N/A																	
Time Police Notified				Time Police Arrived				Time EMS Arrived				EMS Response Run #																	
1852 MT				1945 MT				N/A				N/A																	
Name of Investigating Officer																Officer ID											Agency ORI		
Karl Proctor																571835							AL0010000						
Name of Investigating Officer																Officer ID							Agency ORI						
The data on this report reflects the best knowledge, opinion, and belief regarding the crash, but no warrant is made as to the factual accuracy thereof.																													

LEGEND							
Location	Category	Code	Description	Location	Category	Code	Description
Report Header	Unit Type	1	Passenger car	Driver	Race	1	White / Caucasian
Location And Time	Contributing Circumstance	8	Made improper turn	Driver	Residence Within 25 Miles	99	Unknown
Location And Time	Contributing Unit	10	Unit1	Driver	Travel Direction	1	North
Location And Time	Controlled Access Highway Location	97	Not a controlled access highway	Driver	Travel Direction	3	South
Location And Time	Coordinate Status	99	Unknown	Vehicle	Attachment	1	None
Location And Time	Coordinate Type	97	Not applicable	Vehicle	Body	2	Four door
Location And Time	Crash Manner	8	Side impact (angled)	Vehicle	Citation Offense	99	None
Location And Time	Crash Severity	O	Property damage only	Vehicle	Damage Severity	3	Major, not disabled
Location And Time	Distance Node Unit	0	Unknown	Vehicle	Defect	1	None
Location And Time	Distracted Driving	0	Not Set	Vehicle	Emergency Status	97	Not applicable
Location And Time	Harmful Event	22	Collision with vehicle in traffic	Vehicle	Estimated Speed Code	Unk	Unknown
Location And Time	Highway Classification	4	County	Vehicle	Hazardous Cargo	97	Not applicable
Location And Time	Highway Side	1	Northbound	Vehicle	Hazardous Cargo Release Type	97	Not applicable
Location And Time	Roadway Feature	1	No special feature	Vehicle	K12 Child Going To Or From School	99	Unknown
Location And Time	School Bus Related	1	No school bus involved	Vehicle	Make	99	* Unknown
Location And Time	Time Display Format	20	Military	Vehicle	Make	INFI	Infiniti
Driver	Alcohol Test Type	97	Not applicable	Vehicle	Non-Motorist Action	97	Not applicable
Driver	Commercial Driver License Status	97	Not applicable / unlicensed	Vehicle	Non-Motorist Action	99	Unknown
Driver	Contributing Circumstance	8	Made improper turn	Vehicle	Non-Motorist Location	99	Unknown
Driver	Contributing Circumstance	97	Not applicable	Vehicle	Oversized Load	N/A	NotApplicable
Driver	Driver Address Code	0	Not Set	Vehicle	Oversized Load Permit	N/A	NotApplicable
Driver	Driver Condition	1	Apparently normal	Vehicle	Owner Address Code	0	Not Set
Driver	Driver License Class Code	99	Unknown	Vehicle	Owner Name Code		Not Set
Driver	Driver License Endorsement	97	Not applicable	Vehicle	Placard Requirement	97	Not applicable
Driver	Driver License Number	0	Not set	Vehicle	Placard Status	0	Not Set
Driver	Driver License Restriction	97	Not applicable	Vehicle	Tag Number		Not set
Driver	Driver License State Code	0	Not set	Vehicle	Tag State	0	Not set
Driver	Driver License Status	C	Current / valid	Vehicle	Tag Year	99	Unknown
Driver	Driver Name Code	0	Not Set	Vehicle	Tow Status	3	Not towed
Driver	Drug Test Result	97	Not applicable	Vehicle	Towed Code	97	Not applicable
Driver	Drug Test Type	97	Not applicable	Vehicle	Unit Type	1	Passenger car
Driver	Gender	1	Male	Vehicle	Usage	1	Personal vehicle
Driver	Gender	2	Female	Vehicle	VIN	0	Not set
Driver	Harmful Event	22	Collision with vehicle in traffic	Vehicle	Year		Not set
Driver	Liability Ins. Policy Code	0	Not Set	Uninjured Occupants	Age Code	6	16 - 20
Driver	Liability Insurance NAIC Number Code		Not Set	Uninjured Occupants	Age Code	8	26 - 64
Driver	Maneuver	1	Movement essentially straight	Uninjured Occupants	Airbag	2	Not deployed, no switch
Driver	Maneuver	2	Turning left	Uninjured Occupants	Birth Date Code	0	Not Set
Driver	Phone Number Code	0	Not Set	Uninjured Occupants	Ejection Status	1	Not ejected or trapped
Driver	Place of Employment	99	Unknown	Uninjured Occupants	Gender	1	Male

LEGEND							
Location	Category	Code	Description	Location	Category	Code	Description
Uninjured Occupants	Gender	2	Female				
Uninjured Occupants	Occupant Type	1	Driver				
Uninjured Occupants	Safety Equipment	2	Shoulder and lap belt used				
Roadway Environment	Environmental Contributing Circumstance	1	None apparent				
Roadway Environment	Light Condition	4	Dark, roadway not lighted				
Roadway Environment	Locale	3	Shopping or business				
Roadway Environment	Opposing Lane Separation	5	Solid painted lines				
Roadway Environment	Road Bridge Condition	1	None apparent				
Roadway Environment	Road Surface Type	1	Asphalt				
Roadway Environment	Roadway Condtion	1	Dry				
Roadway Environment	Roadway Curvature And Grade	1	Straight, level				
Roadway Environment	Roadway Material	1	None				
Roadway Environment	Roadway Material Source	97	Not applicable				
Roadway Environment	Traffic Control	6	Traffic signals				
Roadway Environment	Traffic Control Status	1	Yes				
Roadway Environment	Trafficway Lane Count	5	Five lanes				
Roadway Environment	Turn Lane Presence	2	Left turn lane(s) only				
Roadway Environment	Vision Obscuration	1	Not obscured				
Roadway Environment	Weather Condition	1	Clear				
Roadway Environment	Workzone Law Encorcement Presence	99	Unknown				
Roadway Environment	Workzone Relationship	97	Not applicable				
Roadway Environment	Workzone Type	97	Not applicable				