

Local Case No.	2020-00076109

Sheet 1

## LOCATION AND TIME

VEHICLEVEHICLE

Seating Position Codes																															
2, 4, or 6 Passenger			9 Passenger (add):			12 Passenger (add):			Bicycle, Motorcycle, ATV			12 - Pedestrian			16 - Not in Passenger Compartment																
<table><tr><td>1</td><td>2</td><td>3</td></tr><tr><td>4</td><td>5</td><td>6</td></tr></table>			1	2	3	4	5	6	<table><tr><td>7</td><td>8</td><td>9</td></tr></table>			7	8	9	<table><tr><td>17</td><td>18</td><td>19</td></tr></table>			17	18	19	<table><tr><td>10</td></tr><tr><td>11</td></tr></table>			10	11	13 - Rider of Domestic Animal			97 - Not Applicable		
1	2	3																													
4	5	6																													
7	8	9																													
17	18	19																													
10																															
11																															
									14 - Occ. of Non-Motorized Vehicle			98 - Other (Explain)																			
									15 - Passenger of Bus			99 - Unknown																			

UNINJURED OCCUPANTS																			
Unit No	Seat Pos	Occ. Type	Safety Equip.	Air-bag	Age Code	Sex	Ejec-tion	Birth Date		Unit No	Seat Pos	Occ. Type	Safety Equip.	Air-bag	Age Code	Sex	Ejec-tion	Birth Date	
1	1	1	2	2	8	1	1	10/30/1978		2	1	1	2	2	8	1	1	12/30/1978	
2	3	2	2	2	4	1	1	99											

DIAGRAM
<div>No Diagram</div>

NARRATIVE
Unit 2 stated he was stopped at the traffic signal at Stadium Trace Pkwy at the Learning Lane intersection heading northbound and was hit in the rear by Unit 1. Unit 1 stated he was traveling behind Unit 2, thought the light turned green, and was unable to stop before colliding with the rear of Unit 2. Unit 1 clarified the left turn arrow to Brocks Gap Pkwy from Stadium Trace Pkwy was the light that changed to green and not the straight lane, which was the lane he was in. No injuries were reported.

ROADWAY ENVIRONMENT																							
Unit No.	1	Involved Road/Bridge	1	Road Surface Type	1	Roadway Condition	1	Workzone Related?	97	Workzone Type	97	Workers Present ?	NotApplicable		Workzone Law Enforcement Present?		Contributing Circumstances Environment	1	Contrib Matl In Roadway	1			
Contrib Material Source	97	Rdway Curve & Grade	1	Vision Obscur ed Bv	1	Traffic Control	6	Traffic Control Functioning	97	Opposing Lane Separation	2	Trafficway Lanes	4	Turn Lanes	4	One-Way Street	No	Total # Occupant s In Unit	1	Total # Injured in Unit	0	Total # Killed in Unit	0
Total Number of Units		Light		Weather		Locale		Police Present?		DOT Railroad Crossing No.												N/A	
2		6		2		5		No															

ROADWAY ENVIRONMENT																																						
Unit No.	2	Involved Road/ Bridge	1	Road Surface Type	1	Roadway Condition	1	Workzone Related?	97	Workzone Type	97	Workers Present ?	NotApplicable		Workzone Law Enforcement Present?	97	Contributing Circumstances Environment	1	Contrib Matl In Roadway	1																		
Contrib Material Source	97	Rdway Curve & Grade	1	Vision Obscur ed Bv	1	Traffic Control	6	Traffic Control Functioning	97	Opposing Lane Separation	2	Trafficway Lanes	4	Turn Lanes	4	One-Way Street	No	Total # Occupant s In Unit	2	Total # Injured in Unit	0	Total # Killed in Unit	0															
Total Number of Units		2		Light			6		Weather			2		Locale			5		Police Present?		No		DOT Railroad Crossing No.		N/A													
INVESTIGATION																																						
Name of Photographer										N/A																												
Time Police Notified			1943 MT			Time Police Arrived			1944 MT			Time EMS Arrived			N/A			EMS Response Run #			N/A																	
Name of Investigating Officer										Matthew Ryan Bond										Officer ID			12655								Agency ORI			AL0011200				
Name of Investigating Officer																				Officer ID											Agency ORI							
The data on this report reflects the best knowledge, opinion, and belief regarding the crash, but no warrant is made as to the factual accuracy thereof.																																						

LEGEND							
Location	Category	Code	Description	Location	Category	Code	Description
Report Header	Unit Type	3	Pick-up	Driver	Race	1	White / Caucasian
Location And Time	Contributing Circumstance	15	Followed too close	Driver	Residence Within 25 Miles	No	No
Location And Time	Contributing Unit	10	Unit1	Driver	Residence Within 25 Miles	Yes	Yes
Location And Time	Controlled Access Highway Location	97	Not a controlled access highway	Driver	Travel Direction	1	North
Location And Time	Coordinate Status	99	Unknown	Vehicle	Attachment	1	None
Location And Time	Coordinate Type	97	Not applicable	Vehicle	Body	97	Not applicable - not passenger car, personal van, or SUV
Location And Time	Crash Manner	7	Rear end (front-to-rear)	Vehicle	Citation Offense	99	None
Location And Time	Crash Severity	O	Property damage only	Vehicle	Damage Severity	2	Minor
Location And Time	Distance Node Unit	0	Unknown	Vehicle	Defect	1	None
Location And Time	Distracted Driving	0	Not Set	Vehicle	Emergency Status	97	Not applicable
Location And Time	Harmful Event	22	Collision with vehicle in traffic	Vehicle	Estimated Speed Code	Unk	Unknown
Location And Time	Highway Classification	5	Municipal	Vehicle	Hazardous Cargo	97	Not applicable
Location And Time	Highway Side	1	Northbound	Vehicle	Hazardous Cargo Release Type	97	Not applicable
Location And Time	Roadway Feature	22	Four-way intersection	Vehicle	K12 Child Going To Or From School	99	Unknown
Location And Time	School Bus Related	1	No school bus involved	Vehicle	Make	DODG	Dodge
Location And Time	Time Display Format	20	Military	Vehicle	Make	GMC	General Motors Corp.
Driver	Alcohol Test Type	97	Not applicable	Vehicle	Non-Motorist Action	97	Not applicable
Driver	Commercial Driver License Status	97	Not applicable / unlicensed	Vehicle	Non-Motorist Action	99	Unknown
Driver	Contributing Circumstance	15	Followed too close	Vehicle	Non-Motorist Location	99	Unknown
Driver	Contributing Circumstance	97	Not applicable	Vehicle	Oversized Load	N/A	NotApplicable
Driver	Driver Address Code	0	Not Set	Vehicle	Oversized Load Permit	N/A	NotApplicable
Driver	Driver Condition	1	Apparently normal	Vehicle	Owner Address Code	0	Not Set
Driver	Driver License Class Code	0	Not set	Vehicle	Owner Name Code		Not Set
Driver	Driver License Class Code	99	Unknown	Vehicle	Placard Requirement	97	Not applicable
Driver	Driver License Endorsement	97	Not applicable	Vehicle	Placard Status	0	Not Set
Driver	Driver License Number	0	Not set	Vehicle	Tag Number		Not set
Driver	Driver License Restriction	97	Not applicable	Vehicle	Tag State	0	Not set
Driver	Driver License State Code	0	Not set	Vehicle	Tag Year	0	Not set
Driver	Driver License Status	C	Current / valid	Vehicle	Tow Status	3	Not towed
Driver	Driver Name Code	0	Not Set	Vehicle	Towed Code	97	Not applicable
Driver	Drug Test Result	97	Not applicable	Vehicle	Unit Type	3	Pick-up
Driver	Drug Test Type	97	Not applicable	Vehicle	Usage	1	Personal vehicle
Driver	Gender	1	Male	Vehicle	VIN	0	Not set
Driver	Harmful Event	22	Collision with vehicle in traffic	Vehicle	Year		Not set
Driver	Liability Ins. Policy Code	0	Not Set	Uninjured Occupants	Age Code	4	9 - 12
Driver	Liability Insurance NAIC Number Code		Not Set	Uninjured Occupants	Age Code	8	26 - 64
Driver	Maneuver	1	Movement essentially straight	Uninjured Occupants	Airbag	2	Not deployed, no switch
Driver	Maneuver	12	Stopped for sign / signal	Uninjured Occupants	Birth Date Code	0	Not Set
Driver	Phone Number Code	0	Not Set	Uninjured Occupants	Birth Date Code	99	Unknown
Driver	Place of Employment		Not Set	Uninjured Occupants	Ejection Status	1	Not ejected or trapped

LEGEND							
Location	Category	Code	Description	Location	Category	Code	Description
Uninjured Occupants	Gender	1	Male				
Uninjured Occupants	Occupant Type	1	Driver				
Uninjured Occupants	Occupant Type	2	Passenger				
Uninjured Occupants	Safety Equipment	2	Shoulder and lap belt used				
Roadway Environment	Environmental Contributing Circumstance	1	None apparent				
Roadway Environment	Light Condition	6	Dark, spot illumination, both sides of roadway				
Roadway Environment	Locale	5	School				
Roadway Environment	Opposing Lane Separation	2	Paved surface				
Roadway Environment	Road Bridge Condition	1	None apparent				
Roadway Environment	Road Surface Type	1	Asphalt				
Roadway Environment	Roadway Condition	1	Dry				
Roadway Environment	Roadway Curvature And Grade	1	Straight, level				
Roadway Environment	Roadway Material	1	None				
Roadway Environment	Roadway Material Source	97	Not applicable				
Roadway Environment	Traffic Control	6	Traffic signals				
Roadway Environment	Traffic Control Status	97	Not applicable				
Roadway Environment	Trafficway Lane Count	4	Four lanes				
Roadway Environment	Turn Lane Presence	4	Both left and right turn lanes				
Roadway Environment	Vision Obscuration	1	Not obscured				
Roadway Environment	Weather Condition	2	Cloudy				
Roadway Environment	Workzone Law Enforcement Presence	97	Not applicable				
Roadway Environment	Workzone Relationship	97	Not applicable				
Roadway Environment	Workzone Type	97	Not applicable				