

Check if Amendment	<input type="checkbox"/>
Check if Error Correction	<input type="checkbox"/>

ALABAMA UNIFORM TRAFFIC CRASH REPORT

Crash Report Case No. 0699385

# Vehicles	# Pedestrians	# Injured	# Fatalities	# Unit 1 Type	# Unit 2 Type
2	0	0	0	1	1

Local Case No.	2020-199169
----------------	-------------

Sheet 1

LOCATION AND TIME	Date	10	06	2020	Time	1420 MT	Day of Week	Tue	County	Jefferson	City	Birmingham	Rural	<input type="checkbox"/>	Local Zone	E221			
	Hwy Class.	5	On Street, Road, Highway				1st Ave N				At Intersection of or Between (Node 1)				61st St S		And (Node 2)		
	S007				(On) Street/ Road/Hwy <--- Code	7155				1 2 <---> Node Code	N/A				50.00 Feet		From Node 1		
	Mile Post	N/A				Control Access Hwy Loc	97	Primary Contrib Circums	72	Primary Contributing Unit #	2	First Harmful Event	22	First Harmful Event Location	1	Most Harmful Event	22		
	Distance to Fixed Object	N/A				Roadway Junction/ Feature	1	Manner of Crash	10	Lat Coordinate	NC		Long Coordinate	NC		Coordinate Type	97	Hwy Side	97
	School Bus Related	1				Crash Severity	O	Distracted Driving	97										

1 UNIT NO	DRIVER	Driver Full Name										Street Address										City and State										ZIP		Telephone																							
		MALCOLM ANTHONY MAYNOR										2324 3RD WAY NE										CENTER POINT AL										35215		(205) 585-2350																							
		DOB	06	15	1991	Race	2	Sex	1	DL State	AL	Driver License No.				8245688				DL Class	D	DL Status	R	Restrict Violations	97	CDL Status	97	Endorse Violations	97																												
		Place of Employment										99										Residence Less Than 25 Miles										99																									
		Liability Insurance Co.										99										Liability Policy No.										99										Insurance NAIC Number		Unk													
		Driver Condition				99				Sobriety/ Officer Opinion				Alcohol: Unknown Drugs: Unknown				Type Alcohol Test Given				97				Alcohol Test Results				N/A				Type Drug Test Given				97				Drug Test Results				97				Maneuver				1			
		Most Harmful Event for MV				22				Travel Road Name				1st Ave N				Road Code				S007				Travel Direction				3				Unit Contributing Circumstance				72				Total Injuries in Unit				0											
		Sequence of Events				22				Event 2				97				Event 3				97				Event 4				97				First Harmful Event Location				1				Areas Damaged Are Shaded															
		Veh Year				2000				Make				MERC				Veh Model				GRAND MARQUIS				Body				2				V.I.N.				2MEFM74W1YX656287																			
		Owner's Name										99										License Tag Number				TAB067				State				AL				Year				2021															
		Street or R.F.D.										99										City								State								Zip																			
		Type				1				Usage				1				Emergency Status				97				Placard Status				3				Placard Required				97				Hazardous Cargo				97				Hazardous Cargo Released?				97			
		Attachment				1				Oversized Load				N/A				If Yes, Did Owner Have Permit?				N/A				Contrib Defect				1				Speed Limit				45 MPH				Est Speed				40 MPH				Citation Offense(s) Charged				No proof of insurance			
		Damage Severity				4				Towed?				1				Vehicle Towed By Whom:										Weil Wrecker																													
		Towed To Where:										Weil Wrecker																																													

Areas Damaged Are Shaded									
14 Under Carriage									
12									
1									
97 N/A									
11									
2									
16									
10									
3									
13									
4									
16 Totaled									
9									
5									
8									
15									
7									
6									
Attachment									

Point of Initial Impact 99

2 UNIT NO	DRIVER	Driver Full Name										Street Address										City and State										ZIP		Telephone																							
		LASHUNN DEANN NICHOLS										3110 44TH AVE N										BIRMINGHAM AL										35207		(205) 808-8404																							
		DOB	12	23	1994	Race	2	Sex	2	DL State	97	Driver License No.				97				DL Class	97	DL Status	97	Restrict Violations	97	CDL Status	97	Endorse Violations	97																												
		Place of Employment										UPS										Residence Less Than 25 Miles										Yes																									
		Liability Insurance Co.										Direct General										Liability Policy No.										ALPD280301358										Insurance NAIC Number															
		Driver Condition				1				Sobriety/ Officer Opinion				Alcohol: No Drugs: No				Type Alcohol Test Given				6				Alcohol Test Results				N/A				Type Drug Test Given				4				Drug Test Results				97				Maneuver				2			
		Most Harmful Event for MV				22				Travel Road Name				1st Ave N				Road Code				S007				Travel Direction				3				Unit Contributing Circumstance				72				Total Injuries in Unit				0											
		Sequence of Events				22				Event 2				97				Event 3				97				Event 4				97				First Harmful Event Location				1				Areas Damaged Are Shaded															
		Veh Year				2020				Make				HYUN				Veh Model				ELANTRA SE FWD 2.0-4				Body				2				V.I.N.				5NPD74LF3LH525954																			
		Owner's Name										Kenneth Sermons										License Tag Number				DV80J09				State				AL				Year				2021															
		Street or R.F.D.										3029 41RST CT NORTH										City				BIRMINGHAM				State				AL				Zip				35207															
		Type				1				Usage				1				Emergency Status				97				Placard Status				3				Placard Required				97				Hazardous Cargo				97				Hazardous Cargo Released?				97			
		Attachment				1				Oversized Load				N/A				If Yes, Did Owner Have Permit?				N/A				Contrib Defect				1				Speed Limit				45 MPH				Est Speed				20 MPH				Citation Offense(s) Charged				None			
		Damage Severity				4				Towed?				1				Vehicle Towed By Whom:										Weil Wrecker																													
		Towed To Where:										Weil Wrecker																																													

Areas Damaged Are Shaded									
14 Under Carriage									
12									
1									
97 N/A									
11									
2									
16									
10									
3									
13									
4									
16 Totaled									
9									
5									
8									
15									
7									
6									
Attachment									

Point of Initial Impact 11

Seating Position Codes

2, 4, or 6 Passenger

9 Passenger (add):

12 Passenger (add):

Bicycle, Motorcycle, ATV

12 - Pedestrian

16 - Not in Passenger Compartment

1	2	3
4	5	6

7	8	9
---	---	---

17	18	19
----	----	----

10
11

13 - Rider of Domestic Animal

14 - Occ. of Non-Motorized Vehicle

15 - Passenger of Bus

97 - Not Applicable

98 - Other (Explain)


99 - Unknown

UNINJURED OCCUPANTS

Unit No	Seat Pos	Occ. Type	Safety Equip.	Air-bag	Age Code	Sex	Ejection	Birth Date
1	1	1	99	2	99	1	1	99
2	4	2	5	2	1	1	1	10/20/2016
2	6	2	5	2	2	1	1	07/19/2015

Unit No	Seat Pos	Occ. Type	Safety Equip.	Air-bag	Age Code	Sex	Ejection	Birth Date
2	1	1	2	2	7	2	1	12/23/1994
2	5	2	5	2	1	1	1	07/13/2017

DIAGRAM



NARRATIVE

Unit 2 stated that she went to merge left and struck unit 1.

Unit 1 left the scene in another vehicle prior to officer's arrival but returned later.

Unit 1 stated that he was driving straight and unit 2 struck him.

ROADWAY ENVIRONMENT

Unit No.	1	Involved Road/Bridge	1	Road Surface Type	1	Roadway Condition	1	Workzone Related?	1	Workzone Type	97	Workers Present?	NotApplicable			Workzone Law Enforcement Present?	97	Contributing Circumstances Environment	1	Contrib Matl In Roadway	1		
Contrib Material Source	97	Rdway Curve & Grade	1	Vision Obscured By	1	Traffic Control	1	Traffic Control Functioning	97	Opposing Lane Separation	2	Trafficway Lanes	4	Turn Lanes	1	One-Way Street	No	Total # Occupants In Unit	1	Total # Injured in Unit	0	Total # Killed in Unit	0
Total Number of Units			Light			Weather			Locale			Police Present?			DOT Railroad Crossing No.								
2			1			1			3			No			N/A								

ROADWAY ENVIRONMENT																																						
Unit No.	2	Involved Road/Bridge	1	Road Surface Type	1	Roadway Condition	1	Workzone Related?	1	Workzone Type	97	Workers Present ?	NotApplicable		Workzone Law Enforcement Present?	97	Contributing Circumstances Environment	1	Contrib Matl In Roadway	1																		
Contrib Material Source	97	Rdway Curve & Grade	1	Vision Obscur ed Bv	1	Traffic Control	1	Traffic Control Functioning	97	Opposing Lane Separation	2	Trafficway Lanes	4	Turn Lanes	1	One-Way Street	No	Total # Occupant s In Unit	4	Total # Injured in Unit	0	Total # Killed in Unit	0															
Total Number of Units		2		Light			1		Weather			1		Locale			3		Police Present?		No		DOT Railroad Crossing No.		N/A													
INVESTIGATION																																						
Name of Photographer												N/A																										
Time Police Notified				Time Police Arrived				Time EMS Arrived				EMS Response Run #																										
1422 MT				1430 MT				N/A				N/A																										
Name of Investigating Officer																D . Mason											Officer ID				3546				Agency ORI			
Name of Investigating Officer																							Officer ID								Agency ORI							
The data on this report reflects the best knowledge, opinion, and belief regarding the crash, but no warrant is made as to the factual accuracy thereof.																																						

LEGEND							
Location	Category	Code	Description	Location	Category	Code	Description
Report Header	Unit Type	1	Passenger car	Driver	Liability Ins. Policy Code	0	Not Set
Location And Time	Contributing Circumstance	72	Unseen object / person / vehicle	Driver	Liability Ins. Policy Code	99	Unknown
Location And Time	Contributing Unit	20	Unit2	Driver	Liability Insurance NAIC Number Code		Not Set
Location And Time	Controlled Access Highway Location	97	Not a controlled access highway	Driver	Liability Insurance NAIC Number Code	Unk	Unknown
Location And Time	Coordinate Status	NC	NoCapability	Driver	Maneuver	1	Movement essentially straight
Location And Time	Coordinate Type	97	Not applicable	Driver	Maneuver	2	Turning left
Location And Time	Crash Manner	10	Sideswipe, same direction	Driver	Phone Number Code	0	Not Set
Location And Time	Crash Severity	O	Property damage only	Driver	Place of Employment		Not Set
Location And Time	Distance Node Unit	10	Feet	Driver	Place of Employment	99	Unknown
Location And Time	Distracted Driving	97	Not applicable (not distracted)	Driver	Race	2	Black / African-American
Location And Time	Harmful Event	22	Collision with vehicle in traffic	Driver	Residence Within 25 Miles	99	Unknown
Location And Time	Highway Classification	5	Municipal	Driver	Residence Within 25 Miles	Yes	Yes
Location And Time	Highway Side	97	Not applicable	Driver	Travel Direction	3	South
Location And Time	Roadway Feature	1	No special feature	Vehicle	Attachment	1	None
Location And Time	School Bus Related	1	No school bus involved	Vehicle	Body	2	Four door
Location And Time	Time Display Format	20	Military	Vehicle	Citation Offense	131	No proof of insurance
Driver	Alcohol Test Type	6	No Test Given	Vehicle	Citation Offense	99	None
Driver	Alcohol Test Type	97	Not applicable	Vehicle	Damage Severity	4	Major, disabled
Driver	Commercial Driver License Status	97	Not applicable / unlicensed	Vehicle	Defect	1	None
Driver	Contributing Circumstance	72	Unseen object / person / vehicle	Vehicle	Emergency Status	97	Not applicable
Driver	Driver Address Code	0	Not Set	Vehicle	Estimated Speed Code		Not set
Driver	Driver Condition	1	Apparently normal	Vehicle	Hazardous Cargo	97	Not applicable
Driver	Driver Condition	99	Unknown	Vehicle	Hazardous Cargo Release Type	97	Not applicable
Driver	Driver License Class Code	0	Not set	Vehicle	K12 Child Going To Or From School	0	Not Set
Driver	Driver License Class Code	97	Not applicable	Vehicle	Make	HYUN	Hyundai
Driver	Driver License Endorsement	97	Not applicable	Vehicle	Make	MERC	Mercury
Driver	Driver License Number	0	Not set	Vehicle	Non-Motorist Action	0	Not Set
Driver	Driver License Number	97	Not applicable	Vehicle	Non-Motorist Location	0	Not Set
Driver	Driver License Restriction	97	Not applicable	Vehicle	Oversized Load	N/A	NotApplicable
Driver	Driver License State Code	0	Not set	Vehicle	Oversized Load Permit	N/A	NotApplicable
Driver	Driver License State Code	97	Not applicable, including no license	Vehicle	Owner Address Code	0	Not Set
Driver	Driver License Status	97	Not applicable / unlicensed	Vehicle	Owner Address Code	99	Unknown
Driver	Driver License Status	R	Revoked	Vehicle	Owner Name Code		Not Set
Driver	Driver Name Code	0	Not Set	Vehicle	Owner Name Code	99	Unknown
Driver	Drug Test Result	97	Not applicable	Vehicle	Placard Requirement	97	Not applicable
Driver	Drug Test Type	4	No test given	Vehicle	Placard Status	3	Not applicable (placard not required)
Driver	Drug Test Type	97	Not applicable	Vehicle	Tag Number		Not set
Driver	Gender	1	Male	Vehicle	Tag State	0	Not set
Driver	Gender	2	Female	Vehicle	Tag Year	0	Not set
Driver	Harmful Event	22	Collision with vehicle in traffic	Vehicle	Tow Status	1	Towed due to disabling damage

LEGEND							
Location	Category	Code	Description	Location	Category	Code	Description
Vehicle	Towed Code	0	Not Set				
Vehicle	Unit Type	1	Passenger car				
Vehicle	Usage	1	Personal vehicle				
Vehicle	VIN	0	Not set				
Vehicle	Year		Not set				
Uninjured Occupants	Age Code	1	0 - 3				
Uninjured Occupants	Age Code	2	4 - 5				
Uninjured Occupants	Age Code	7	21 - 25				
Uninjured Occupants	Age Code	99	Unknown				
Uninjured Occupants	Airbag	2	Not deployed, no switch				
Uninjured Occupants	Birth Date Code	0	Not Set				
Uninjured Occupants	Birth Date Code	99	Unknown				
Uninjured Occupants	Ejection Status	1	Not ejected or trapped				
Uninjured Occupants	Gender	1	Male				
Uninjured Occupants	Gender	2	Female				
Uninjured Occupants	Occupant Type	1	Driver				
Uninjured Occupants	Occupant Type	2	Passenger				
Uninjured Occupants	Safety Equipment	2	Shoulder and lap belt used				
Uninjured Occupants	Safety Equipment	5	Forward facing child safety seat used properly				
Uninjured Occupants	Safety Equipment	99	Unknown				
Roadway Environment	Environmental Contributing Circumstance	1	None apparent				
Roadway Environment	Light Condition	1	Daylight				
Roadway Environment	Locale	3	Shopping or business				
Roadway Environment	Opposing Lane Separation	2	Paved surface				
Roadway Environment	Road Bridge Condition	1	None apparent				
Roadway Environment	Road Surface Type	1	Asphalt				
Roadway Environment	Roadway Condtion	1	Dry				
Roadway Environment	Roadway Curvature And Grade	1	Straight, level				
Roadway Environment	Roadway Material	1	None				
Roadway Environment	Roadway Material Source	97	Not applicable				
Roadway Environment	Traffic Control	1	No controls present				
Roadway Environment	Traffic Control Status	97	Not applicable				
Roadway Environment	Trafficway Lane Count	4	Four lanes				
Roadway Environment	Turn Lane Presence	1	None				
Roadway Environment	Vision Obscuration	1	Not obscured				
Roadway Environment	Weather Condition	1	Clear				
Roadway Environment	Workzone Law Encorcement Presence	97	Not applicable				
Roadway Environment	Workzone Relationship	1	Not in / related to workzone				
Roadway Environment	Workzone Type	97	Not applicable				