

# Vehicles	# Pedestrians	# Injured	# Fatalities	# Unit 1 Type	Unit 2 Type
2	0	1	0	1	6

Local Case No.	2020-219374

Sheet 1

LOCATION AND TIME	Date	10	25	2020	Time	Day of Week	County	City	Rural	Local Zone	
	Month	Day	Year	1905 MT	Sun	Montgomery	Montgomery		20		
	Hwy Class.	On Street, Road, Highway				At Intersection of or Between (Node 1)			And (Node 2)		
	5	Woodmere Blvd				EASTERN BLVD					
	6922		(On) Street/ Road/Hwy	10305		1 2 --- -->	N/A	From Node 1			
	---		Code			Node Code					
	Mile Post	Control Access		Primary Contrib	Primary Contributing	First Harmful Event	First Harmful Event	Most Harmful Event			
	N/A	Hwy Loc 1		22	Unit # Unknown	22	Location 1	23			
Distance to Fixed Object	Roadway Junction/	Manner of	Lat Coordinate	Long Coordinate	Coordinate Type	Hwy Side					
N/A	feet	Feature 1	Crash 5	99	99	97	97				
School Bus Related	Crash Severity	Distracted Driving									
1	C	99									

<b>DRIVER</b>	<b>Driver Full Name</b> SARAH KIM VANDERVOORT		<b>Street Address</b> 201 WILTSHIRE DR				<b>City and State</b> MONTGOMERY AL			<b>ZIP</b> 36117		<b>Telephone</b> (334) 868-7845		
	<b>DOB</b>	<b>09</b>	<b>25</b>	<b>1959</b>	<b>Race</b>	<b>Sex</b>	<b>DL State</b>	<b>Driver License No.</b> 8252856		<b>DL Class</b>	<b>DL Status</b>	<b>Restrict Violations</b>	<b>CDL Status</b>	<b>Endorse Violations</b>
		Month	Day	Year	99	2	AL			D	C		97	97
	<b>Place of Employment</b> 99											<b>Residence Less Than 25 Miles</b> Yes		
	<b>Liability Insurance Co.</b> USAA							<b>Liability Policy No.</b> 0017989017116				<b>Insurance NAIC Number</b>		
	<b>Driver Condition</b> 1		<b>Sobriety/ Officer Opinion</b>		<b>Alcohol: No Drugs: No</b>		<b>Type Alcohol Test Given</b> 6		<b>Alcohol Test Results</b> N/A		<b>Type Drug Test Given</b> 4		<b>Drug Test Results</b> 97	
	<b>Most Harmful Event for MV</b> 22		<b>Travel Road Name</b> Woodmere Blvd					<b>Road Code</b> 6922		<b>Travel Direction</b> 4		<b>Unit Contributing Circumstance</b> 37		
	<b>Sequence of Events</b>		<b>Event 1</b> 22		<b>Event 2</b> 97		<b>Event 3</b> 97		<b>Event 4</b> 97		<b>First Harmful Event Location</b> 1		<b>Total Injuries in Unit</b> 0	
	<b>Veh Year</b> 2014		<b>Make</b> BMW		<b>Veh Model</b> 750LI			<b>Body</b> 2		<b>V.I.N.</b> WBAYE8C57ED134477				
	<b>Owner's Name</b> Vandervoort Peter Allison And Sarah Kim							<b>License Tag Number</b> 1ST TEE		<b>State</b> AL		<b>Year</b> 2021		
<b>Street or R.F.D.</b> 201 WILTSHIRE DR							<b>City</b> MONTGOMERY		<b>State</b> AL		<b>Zip</b> 36117-0000			
<b>Type</b> 1		<b>Usage</b> 1		<b>Emergency Status</b> 97		<b>Placard Status</b> 3		<b>Placard Required</b> 97		<b>Hazardous Cargo</b> 97		<b>Hazardous Cargo Released?</b> 97		
<b>Attachment</b> 97		<b>Oversized Load</b> N/A		<b>If Yes, Did Owner Have Permit?</b> N/A		<b>Contrib Defect</b> 97		<b>Speed Limit</b> 30 MPH		<b>Est Speed</b> Unk MPH		<b>Citation Offense(s) Charged</b> None		
<b>Damage Severity</b> 3		<b>Towed?</b> 3		<b>Vehicle Towed By Whom:</b> 97										
<b>Towed To Where:</b> 97														

<b>VEHICLE OR NON-MOTORIST</b>	
<input checked="" type="checkbox"/> VEHICLE	<input type="checkbox"/> NON-MOTORIST

<b>Areas Damaged Are Shaded</b>	
14 Under Carriage	97 N/A
	16 Totalled 15 Attachment
Point of Initial Impact <u>1</u>	

<div>2</div> <div>UNIT NO</div> <div><input type="checkbox"/></div> <div>LEFT SCENE</div> <div><input type="checkbox"/></div> <div>COM VEH</div> <div><input checked="" type="checkbox"/></div> <div>VEHICLE or</div> <div><input type="checkbox"/></div> <div>NON-MOTORIST</div>	DRIVER	Driver Full Name		Street Address				City and State			ZIP	Telephone																	
		BRIAN MAURICE JONES		2204 OLD MILL CT				MONTGOMERY AL			36117	(334) 659-7513																	
		DOB	08	09	1980	Race	2	Sex	1	DL State	AL	Driver License No.		6657959	DL Class	D	DL Status	C	Restrict Violations	97	CDL Status	97	Endorse Violations	97					
		Month		Day		Year																							
		Place of Employment												Residence Less Than 25 Miles															
		99												Yes															
		Liability Insurance Co.										Liability Policy No.										Insurance NAIC Number							
		Allstate										000000821554447																	
		Driver Condition		1		Sobriety/ Officer Opinion		Alcohol: No		Type Alcohol Test Given		6		Alcohol Test Results		N/A		Type Drug Test Given		4		Drug Test Results		97		Maneuver		1	
		Most Harmful Event for MV		22		Travel Road Name		Woodmere Blvd		Road Code		6922		Travel Direction		4		Unit Contributing Circumstance		97		Total Injuries in Unit		1					
Sequence of Events		Event 1		Event 2		Event 3		Event 4		First Harmful Event Location		1		Areas Damaged Are Shaded															
Veh Year		2004		Make		CADI		Veh Model		ESCALADE ESV AWD		Body		4		V.I.N.		3GYFK66N04G251963		14		Under Carriage							
Owner's Name		Jones Brian Sr.		License Tag Number		JNS690		State		AL		Year		2021															
Street or R.F.D.		2204 OLD MILL CT		City		MONTGOMERY		State		AL		Zip		36117-0000															
Type		6		Usage		1		Emergency Status		97		Placard Status		3		Placard Required		97		Hazardous Cargo		97		Hazardous Cargo Released?		97			
Attachment		97		Oversized Load		N/A		If Yes, Did Owner Have Permit?		N/A		Contrib Defect		97		Speed Limit		30 MPH		Est Speed		Unk MPH		Citation Offense(s) Charged		None			
Damage Severity		3		Towed?		3		Vehicle Towed By Whom:		97																			
Towed To Where:		97																											

11

10

9

8

7

6

12

13

1

2

3

4

5

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

101

102

103

104

105

106

107

108

109

110

111

112

113

114

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

130

131

132

133

134

135

136

137

138

139

140

141

142

143

144

145

146

147

148

149

150

151

152

153

154

155

156

157

158

159

160

161

162

163

164

165

166

167

168

169

170

171

172

173

174

175

176

177

178

179

180

181

182

183

184

185

186

187

188

189

190

191

192

193

194

195

196

197

198

199

200

201

202

203

204

205

206

207

208

209

210

211

212

213

214

215

216

217

218

219

220

221

222

223

224

225

226

227

228

229

230

231

232

233

234

235

236

237

238

239

240

241

242

243

244

245

246

247

248

249

250

251

252

253

254

255

256

257

258

259

260

261

262

263

264

265

266

267

268

269

270

271

272

273

274

275

276

277

278

279

280

281

282

283

284

285

286

287

288

289

290

291

292

293

294

295

296

297

29

## Seating Position Codes

2, 4, or 6 Passenger

9 Passenger (add):

12 Passenger (add):

Bicycle, Motorcycle, ATV

12 - Pedestrian

16 - Not in Passenger Compartment

1	2	3
4	5	6

7	8	9
---	---	---

17	18	19
----	----	----

10
11

13 - Rider of Domestic Animal

14 - Occ. of Non-Motorized Vehicle

15 - Passenger of Bus

97 - Not Applicable

98 - Other (Explain)

99 - Unknown


## UNINJURED OCCUPANTS

Unit No	Seat Pos	Occ. Type	Safety Equip.	Air-bag	Age Code	Sex	Ejection	Birth Date	Unit No	Seat Pos	Occ. Type	Safety Equip.	Air-bag	Age Code	Sex	Ejection	Birth Date
1	1	1	2	4	8	2	1	09/25/1959	2	3	2	2	4	8	2	1	10/20/1980
2	4	2	2	4	2	2	1	03/14/2015	2	6	2	2	4	2	1	1	12/11/2015
2	7	2	6	4	1	2	1	01/10/2019	2	9	2	2	4	1	1	1	08/11/2017

## VICTIMS

N/A <input type="checkbox"/>										Unit No	Seat Pos	Occ. Type	Safety Equip.	Air-bag	Injury Type	Age	Sex	Ejection	First Aid By
Name <b>BRIAN MAURICE JONES</b>										2	1	1	2	4	4	8	1	1	1
Address <b>2204 OLD MILL CT MONTGOMERY AL 36117</b>																			
Taken To <b>BAPTIST SOUTH ER</b>										Taken By <b>HAYNES AMBULANCE</b>									
Medical Facility <b>Law enforcement</b>															Birth Date <b>08/09/1980</b>				

## DIAGRAM



## NARRATIVE

THE DRIVER OF UNIT TWO STATED HE WAS IN THE LEFT LANE OF WOODMERE BLVD HEADING WESTBOUND WHEN THE DRIVER OF UNIT ONE CAME OUT ONTO THE ROADWAY AND HIT HIS VEHICLE. THE DRIVER OF UNIT TWO REPORTED HE HAD MINOR INJURIES AND WAS TAKEN TO BAPTIST SOUTH ER FOR FURTHER MEDICAL ATTENTION. NO REPORT OF ANY INJURIES FROM THE PASSENGERS OF UNIT TWO.

## NARRATIVE

THE DRIVER OF UNIT ONE STATED SHE WAS MAKING A LEFT TURN FROM THE PARKING LOT OF PET BOYS AUTO PARTS ONTO WOODMERE BLVD GOING INTO THE LEFT LANE WHEN THE DRIVER OF UNIT TWO CAME OVER INTO HER LANE AND HIT HER VEHICLE IN THE ROADWAY. THE DRIVER OF UNIT ONE FURTHER STATED SHE WAS IN THE MIDDLE LANE ATTEMPTING TO ENTER THE LEFT LANE OF WOODMERE BLVD. THE DRIVER OF UNIT ONE ALSO STATED THE DRIVER OF UNIT TWO WAS SPEEDING AND HE WAS IN THE RIGHT LANE BEFORE SHE CAME ON TO THE ROADWAY FO WOODMERE BLVD. NO REPORT OF ANY INJURIES FROM THE DRIVER OF UNIT ONE.

## ROADWAY ENVIRONMENT

Unit No.	1	Involved Road/ Bridge	1	Road Surface Type	1	Roadway Condition	1	Workzone Related?	1	Workzone Type	97	Workers Present ?	NotApplicable	Workzone Law Enforcement Present?	97	Contributing Circumstances Environment	1	Contrib Matl In Roadway	1				
Contrib Material Source	97	Rdway Curve & Grade	1	Vision Obscur ed Bv	1	Traffic Control	1	Traffic Control Functioning	97	Opposing Lane Separation	4	Trafficway Lanes	4	Turn Lanes	1	One-Way Street	No	Total # Occupant s In Unit	1	Total # Injured in Unit	0	Total # Killed in Unit	0
Total Number of Units		2		Light		7		Weather		1		Locale		3		Police Present?		No		DOT Railroad Crossing No.			
																				N/A			

Unit No.	2	Involved Road/ Bridge	1	Road Surface Type	1	Roadway Condition	1	Workzone Related?	1	Workzone Type	97	Workers Present ?	NotApplicable	Workzone Law Enforcement Present?	97	Contributing Circumstances Environment	1	Contrib Matl In Roadway	1				
Contrib Material Source	97	Rdway Curve & Grade	1	Vision Obscur ed Bv	1	Traffic Control	1	Traffic Control Functioning	97	Opposing Lane Separation	4	Trafficway Lanes	4	Turn Lanes	1	One-Way Street	No	Total # Occupant s In Unit	6	Total # Injured in Unit	1	Total # Killed in Unit	0
Total Number of Units		2		Light		7		Weather		1		Locale		3		Police Present?		No		DOT Railroad Crossing No.			
																				N/A			

## INVESTIGATION

Name of Photographer				N/A							
Time Police Notified		Time Police Arrived		Time EMS Arrived		EMS Response Run #					
1909 MT		1930 MT		1914 MT		2020-34054					
Name of Investigating Officer						Officer ID		Agency ORI			
L C BLALOCK						2650		AL0030100			
Name of Investigating Officer						Officer ID		Agency ORI			
The data on this report reflects the best knowledge, opinion, and belief regarding the crash, but no warrant is made as to the factual accuracy thereof.											

LEGEND							
Location	Category	Code	Description	Location	Category	Code	Description
Report Header	Unit Type	1	Passenger car	Driver	Phone Number Code	0	Not Set
Report Header	Unit Type	6	Sport utility vehicle (SUV)	Driver	Place of Employment	99	Unknown
Location And Time	Contributing Circumstance	22	Improper lane change / use	Driver	Race	2	Black / African-American
Location And Time	Contributing Unit	0	Unknown	Driver	Race	99	Unknown
Location And Time	Controlled Access Highway Location	1	Main road	Driver	Residence Within 25 Miles	Yes	Yes
Location And Time	Coordinate Status	99	Unknown	Driver	Travel Direction	4	West
Location And Time	Coordinate Type	97	Not applicable	Vehicle	Attachment	97	Not applicable
Location And Time	Crash Manner	5	Angle (front-to-side), same direction	Vehicle	Body	2	Four door
Location And Time	Crash Severity	C	Possible injury	Vehicle	Body	4	Four door with rear entry
Location And Time	Distance Node Unit	0	Unknown	Vehicle	Citation Offense	99	None
Location And Time	Distracted Driving	99	Unknown	Vehicle	Damage Severity	3	Major, not disabled
Location And Time	Harmful Event	22	Collision with vehicle in traffic	Vehicle	Defect	97	Not applicable
Location And Time	Harmful Event	23	Collision with vehicle in (or from) other roadway	Vehicle	Emergency Status	97	Not applicable
Location And Time	Highway Classification	5	Municipal	Vehicle	Estimated Speed Code	Unk	Unknown
Location And Time	Highway Side	97	Not applicable	Vehicle	Hazardous Cargo	97	Not applicable
Location And Time	Roadway Feature	1	No special feature	Vehicle	Hazardous Cargo Release Type	97	Not applicable
Location And Time	School Bus Related	1	No school bus involved	Vehicle	K12 Child Going To Or From School	0	Not Set
Location And Time	Time Display Format	20	Military	Vehicle	Make	BMW	BMW
Driver	Alcohol Test Type	6	No Test Given	Vehicle	Make	CADI	Cadillac
Driver	Commercial Driver License Status	97	Not applicable / unlicensed	Vehicle	Non-Motorist Action	0	Not Set
Driver	Contributing Circumstance	37	Failed to yield right-of-way from driveway	Vehicle	Non-Motorist Location	0	Not Set
Driver	Contributing Circumstance	97	Not applicable	Vehicle	Oversized Load	N/A	NotApplicable
Driver	Driver Address Code	0	Not Set	Vehicle	Oversized Load Permit	N/A	NotApplicable
Driver	Driver Condition	1	Apparently normal	Vehicle	Owner Address Code	0	Not Set
Driver	Driver License Class Code	0	Not set	Vehicle	Owner Name Code		Not Set
Driver	Driver License Endorsement	97	Not applicable	Vehicle	Placard Requirement	97	Not applicable
Driver	Driver License Number	0	Not set	Vehicle	Placard Status	3	Not applicable (placard not required)
Driver	Driver License Restriction	97	Not applicable	Vehicle	Tag Number		Not set
Driver	Driver License State Code	0	Not set	Vehicle	Tag State	0	Not set
Driver	Driver License Status	C	Current / valid	Vehicle	Tag Year	0	Not set
Driver	Driver Name Code	0	Not Set	Vehicle	Tow Status	3	Not towed
Driver	Drug Test Result	97	Not applicable	Vehicle	Towed Code	97	Not applicable
Driver	Drug Test Type	4	No test given	Vehicle	Unit Type	1	Passenger car
Driver	Gender	1	Male	Vehicle	Unit Type	6	Sport utility vehicle (SUV)
Driver	Gender	2	Female	Vehicle	Usage	1	Personal vehicle
Driver	Harmful Event	22	Collision with vehicle in traffic	Vehicle	VIN	0	Not set
Driver	Liability Ins. Policy Code	0	Not Set	Vehicle	Year		Not set
Driver	Liability Insurance NAIC Number Code		Not Set	Uninjured Occupants	Age Code	1	0 - 3
Driver	Maneuver	1	Movement essentially straight	Uninjured Occupants	Age Code	2	4 - 5
Driver	Maneuver	2	Turning left	Uninjured Occupants	Age Code	8	26 - 64

LEGEND							
Location	Category	Code	Description	Location	Category	Code	Description
Uninjured Occupants	Airbag	4	Not deployed, switch on				
Uninjured Occupants	Birth Date Code	0	Not Set				
Uninjured Occupants	Ejection Status	1	Not ejected or trapped				
Uninjured Occupants	Gender	1	Male				
Uninjured Occupants	Gender	2	Female				
Uninjured Occupants	Occupant Type	1	Driver				
Uninjured Occupants	Occupant Type	2	Passenger				
Uninjured Occupants	Safety Equipment	2	Shoulder and lap belt used				
Uninjured Occupants	Safety Equipment	6	Rear facing child safety seat used properly				
Victims	Age Code	8	26 - 64				
Victims	Airbag	4	Not deployed, switch on				
Victims	Birth Date Code	0	Not Set				
Victims	Ejection Status	1	Not ejected or trapped				
Victims	First Aid Provider	1	Paramedic / EMT				
Victims	Gender	1	Male				
Victims	Injury Type	4	(C) Possible injury				
Victims	Medical Facility Transport	3	Law enforcement				
Victims	Occupant Type	1	Driver				
Victims	Safety Equipment	2	Shoulder and lap belt used				
Victims	Victim Taken By		Not Set				
Victims	Victim Taken To		Not Set				
Roadway Environment	Environmental Contributing Circumstance	1	None apparent				
Roadway Environment	Light Condition	7	Dark, continuous illumination, one side of roadway				
Roadway Environment	Locale	3	Shopping or business				
Roadway Environment	Opposing Lane Separation	4	Broken painted line				
Roadway Environment	Road Bridge Condition	1	None apparent				
Roadway Environment	Road Surface Type	1	Asphalt				
Roadway Environment	Roadway Condtion	1	Dry				
Roadway Environment	Roadway Curvature And Grade	1	Straight, level				
Roadway Environment	Roadway Material	1	None				
Roadway Environment	Roadway Material Source	97	Not applicable				
Roadway Environment	Traffic Control	1	No controls present				
Roadway Environment	Traffic Control Status	97	Not applicable				
Roadway Environment	Trafficway Lane Count	4	Four lanes				
Roadway Environment	Turn Lane Presence	1	None				
Roadway Environment	Vision Obscuration	1	Not obscured				
Roadway Environment	Weather Condition	1	Clear				
Roadway Environment	Workzone Law Encorcement Presence	97	Not applicable				
Roadway Environment	Workzone Relationship	1	Not in / related to workzone				
Roadway Environment	Workzone Type	97	Not applicable				