

Check if Amendment

☐

Check if Error Correction

☐

ALABAMA UNIFORM TRAFFIC CRASH REPORT

Crash Report Case No. 0699897

# Vehicles	# Pedestrians	# Injured	# Fatalities	# Unit 1 Type	# Unit 2 Type
2	0	0	0	3	3

Local Case No. 2020-199243

Sheet 1

LOCATION AND TIME

Date	10	06	2020	Time	2025 MT	Day of Week	Tue	County	Jefferson	City	Birmingham	Rural	Local Zone	427
Hwy Class.	5	On Street, Road, Highway				At Intersection of or Between (Node 1)				And (Node 2)				
3964				(On) Street/ Road/Hwy <--- Code	467		1 2 <--- ---> Node Code	N/A		From Node 1 N/A				
Mile Post	N/A		Control Access Hwy Loc	97	Primary Contrib Circums	26	Primary Contributing Unit #	1	First Harmful Event	22	First Harmful Event Location	1	Most Harmful Event	22
Distance to Fixed Object	N/A		Roadway Junction/ Feature	22	Manner of Crash	7	Lat Coordinate	99		Long Coordinate	99		Coordinate Type	97
School Bus Related	1		Crash Severity	O	Distracted Driving	97								

1
UNIT
NO

LEFT
SCENE

COM
VEH

VEHICLE or
NON-MOTORIST

DRIVER

VEHICLE

Driver Full Name JULIUS CLARENCE NORWOOD				Street Address 301 HIGHLAND DR				City and State BIRMINGHAM AL				ZIP 35228	Telephone (205) 369-4096																		
DOB	05	29	1977	Race	2	Sex	1	DL State	AL	Driver License No.	7311760	DL Class	D	DL Status	C	Restrict Violations	97	CDL Status	97	Endorse Violations	97										
Place of Employment 99																		Residence Less Than 25 Miles Yes													
Liability Insurance Co. State Auto Insurance										Liability Policy No. bap238845004										Insurance NAIC Number											
Driver Condition		1		Sobriety/ Officer Opinion		Alcohol: Drugs:		No No		Type Alcohol Test Given		6		Alcohol Test Results		N/A		Type Drug Test Given		4		Drug Test Results		97		Maneuver		1			
Most Harmful Event for MV		22		Travel Road Name South Park Rd								Road Code 3964		Travel Direction 1		Unit Contributing Circumstance		24		Total Injuries in Unit		0									
Sequence of Events		22		Event 1		97		Event 2		97		Event 3		97		Event 4		97		First Harmful Event Location		1		Areas Damaged Are Shaded							
Veh Year		2005		Make		CHEV		Veh Model		SILVERADO 1500 WT EX		Body		2		V.I.N.		2GCEC19V651120429		14		Under Carriage		97		N/A					
Owner's Name Professional Masonry Inc										License Tag Number				1CN8343				State		AL		Year		2020		11		1		97	
Street or R.F.D. 2505 PAWNEE VILLAGE RD										City				BIRMINGHAM				State		AL		Zip		35217		10		2		16	
Type		3		Usage		1		Emergency Status		97		Placard Status		3		Placard Required		97		Hazardous Cargo		97		Hazardous Cargo Released?		97		13			
Attachment		1		Oversized Load		N/A		If Yes, Did Owner Have Permit?		N/A		Contrib Defect		1		Speed Limit		40 MPH		Est Speed		Unk MPH		Citation Offense(s) Charged		No proof of insurance		8			
Damage Severity		3		Towed?		3		Vehicle Towed By Whom: 97														7		5		15					
Towed To Where: 97																		Point of Initial Impact		12		Attachment									

2
UNIT
NO

LEFT
SCENE

COM
VEH

VEHICLE or
NON-MOTORIST

DRIVER

VEHICLE

Driver Full Name ALLEN . LEWIS				Street Address 3017 AVENUE S				City and State BIRMINGHAM AL				ZIP 35208	Telephone (205) 218-7985																		
DOB	09	20	1960	Race	2	Sex	1	DL State	AL	Driver License No.	4441822	DL Class	DM	DL Status	C	Restrict Violations	A	CDL Status	97	Endorse Violations	97										
Place of Employment 99																		Residence Less Than 25 Miles Yes													
Liability Insurance Co. Farmers Insurance										Liability Policy No. 191855157										Insurance NAIC Number											
Driver Condition		1		Sobriety/ Officer Opinion		Alcohol: Drugs:		No No		Type Alcohol Test Given		6		Alcohol Test Results		N/A		Type Drug Test Given		4		Drug Test Results		97		Maneuver		10			
Most Harmful Event for MV		22		Travel Road Name South Park Rd								Road Code 3964		Travel Direction 1		Unit Contributing Circumstance		81		Total Injuries in Unit		0									
Sequence of Events		22		Event 1		97		Event 2		97		Event 3		97		Event 4		97		First Harmful Event Location		1		Areas Damaged Are Shaded							
Veh Year		2004		Make		DODG		Veh Model		RAM 1500 SLT QUAD CA		Body		2		V.I.N.		1D7HA18N34S647515		14		Under Carriage		97		N/A					
Owner's Name Green Alice L										License Tag Number				1AJ1849				State		AL		Year		2021		11		1		97	
Street or R.F.D. 1230 HIGHLAND DR										City				FAIRFIELD				State		AL		Zip		350641617		10		2		16	
Type		3		Usage		1		Emergency Status		97		Placard Status		3		Placard Required		97		Hazardous Cargo		97		Hazardous Cargo Released?		97		9			
Attachment		1		Oversized Load		N/A		If Yes, Did Owner Have Permit?		N/A		Contrib Defect		1		Speed Limit		40 MPH		Est Speed		Unk MPH		Citation Offense(s) Charged		None		8			
Damage Severity		2		Towed?		3		Vehicle Towed By Whom: 97														7		5		15					
Towed To Where: 97																		Point of Initial Impact		6		Attachment									

Seating Position Codes

2, 4, or 6 Passenger

1	2	3
4	5	6

9 Passenger (add):

7	8	9
---	---	---

12 Passenger (add):

17	18	19
----	----	----

Bicycle, Motorcycle, ATV

10
11

12 - Pedestrian

13 - Rider of Domestic Animal

14 - Occ. of Non-Motorized Vehicle

15 - Passenger of Bus

16 - Not in Passenger Compartment

97 - Not Applicable


98 - Other (Explain)

99 - Unknown

UNINJURED OCCUPANTS

Unit No	Seat Pos	Occ. Type	Safety Equip.	Air-bag	Age Code	Sex	Ejection	Birth Date	Unit No	Seat Pos	Occ. Type	Safety Equip.	Air-bag	Age Code	Sex	Ejection	Birth Date
1	1	1	2	4	8	1	1	05/29/1977	2	1	1	2	4	8	1	1	09/20/1960

DIAGRAM



NARRATIVE

Source of Activity

On October 6, 2020 I (Officer S. Jones, 3718) was assigned to West Precinct, Unit 461 C. I was in full uniform and a marked police vehicle with an internal emergency lights and sirens system. I was dispatched via radio communications to the 2400 block of Pearson Ave SW on a vehicle accident.

Investigation

Upon my arrival I spoke with Unit 2. Unit 2 stated that he had just went through the green light when he noticed pedestrians about to cross the street. Unit 2 stated that the pedestrians began crossing the street and that there was no crosswalk where they were crossing. Unit 2 stated he stopped in the road to prevent from hitting the pedestrians and when he stopped he was rear ended by unit 1. Unit 2 refused medical treatment at the time of this report. Case card was issued to unit 2.

I then spoke with Unit 1. Unit 1 stated that he and unit 2's light was green. Unit 1 stated that unit 2 stopped in the roadway unexpectedly and he did not have time to stop and rear ended unit 2. Unit 1 refused medical treatment at the time of this report. Case card was issued to unit 1.

ROADWAY ENVIRONMENT																															
Unit No.	1	Involved Road/ Bridge	1	Road Surface Type	1	Roadway Condition	1	Workzone Related?	1	Workzone Type	97	Workers Present ?	NotApplicable		Workzone Law Enforcement Present?	97	Contributing Circumstances Environment	1	Contrib Matl In Roadway	1											
Contrib Material Source	97	Rdway Curve & Grade	1	Vision Obscur ed Bv	1	Traffic Control	6	Traffic Control Functioning	1	Opposing Lane Separation	4	Trafficway Lanes	2	Turn Lanes	1	One-Way Street	No	Total # Occupant s In Unit	1	Total # Injured in Unit	0	Total # Killed in Unit	0								
Total Number of Units		2		Light			7			Weather			1			Locale			2			Police Present?		No		DOT Railroad Crossing No.				N/A	
Unit No.	2	Involved Road/ Bridge	1	Road Surface Type	1	Roadway Condition	1	Workzone Related?	1	Workzone Type	97	Workers Present ?	NotApplicable		Workzone Law Enforcement Present?	97	Contributing Circumstances Environment	1	Contrib Matl In Roadway	1											
Contrib Material Source	97	Rdway Curve & Grade	1	Vision Obscur ed Bv	1	Traffic Control	6	Traffic Control Functioning	1	Opposing Lane Separation	4	Trafficway Lanes	2	Turn Lanes	1	One-Way Street	No	Total # Occupant s In Unit	1	Total # Injured in Unit	0	Total # Killed in Unit	0								
Total Number of Units		2		Light			7			Weather			1			Locale			2			Police Present?		No		DOT Railroad Crossing No.				N/A	
INVESTIGATION																															
Name of Photographer											N/A																				
Time Police Notified				Time Police Arrived				Time EMS Arrived				EMS Response Run #																			
2032 MT				2041 MT				N/A				N/A																			
Name of Investigating Officer											Officer ID				Agency ORI																
S . Jones											03718				AL0010200																
Name of Investigating Officer											Officer ID				Agency ORI																
The data on this report reflects the best knowledge, opinion, and belief regarding the crash, but no warrant is made as to the factual accuracy thereof.																															

LEGEND							
Location	Category	Code	Description	Location	Category	Code	Description
Report Header	Unit Type	3	Pick-up	Driver	Race	2	Black / African-American
Location And Time	Contributing Circumstance	26	Improper parking / stopped in road	Driver	Residence Within 25 Miles	Yes	Yes
Location And Time	Contributing Unit	10	Unit1	Driver	Travel Direction	1	North
Location And Time	Controlled Access Highway Location	97	Not a controlled access highway	Vehicle	Attachment	1	None
Location And Time	Coordinate Status	99	Unknown	Vehicle	Body	2	Four door
Location And Time	Coordinate Type	97	Not applicable	Vehicle	Citation Offense	131	No proof of insurance
Location And Time	Crash Manner	7	Rear end (front-to-rear)	Vehicle	Citation Offense	99	None
Location And Time	Crash Severity	O	Property damage only	Vehicle	Damage Severity	2	Minor
Location And Time	Distance Node Unit	0	Unknown	Vehicle	Damage Severity	3	Major, not disabled
Location And Time	Distracted Driving	97	Not applicable (not distracted)	Vehicle	Defect	1	None
Location And Time	Harmful Event	22	Collision with vehicle in traffic	Vehicle	Emergency Status	97	Not applicable
Location And Time	Highway Classification	5	Municipal	Vehicle	Estimated Speed Code	Unk	Unknown
Location And Time	Highway Side	97	Not applicable	Vehicle	Hazardous Cargo	97	Not applicable
Location And Time	Roadway Feature	22	Four-way intersection	Vehicle	Hazardous Cargo Release Type	97	Not applicable
Location And Time	School Bus Related	1	No school bus involved	Vehicle	K12 Child Going To Or From School	0	Not Set
Location And Time	Time Display Format	20	Military	Vehicle	Make	CHEV	Chevrolet
Driver	Alcohol Test Type	6	No Test Given	Vehicle	Make	DODG	Dodge
Driver	Commercial Driver License Status	97	Not applicable / unlicensed	Vehicle	Non-Motorist Action	0	Not Set
Driver	Contributing Circumstance	24	Misjudge stopping distance	Vehicle	Non-Motorist Location	0	Not Set
Driver	Contributing Circumstance	81	Improper crossing	Vehicle	Oversized Load	N/A	NotApplicable
Driver	Driver Address Code	0	Not Set	Vehicle	Oversized Load Permit	N/A	NotApplicable
Driver	Driver Condition	1	Apparently normal	Vehicle	Owner Address Code	0	Not Set
Driver	Driver License Class Code	0	Not set	Vehicle	Owner Name Code		Not Set
Driver	Driver License Endorsement	97	Not applicable	Vehicle	Placard Requirement	97	Not applicable
Driver	Driver License Number	0	Not set	Vehicle	Placard Status	3	Not applicable (placard not required)
Driver	Driver License Restriction	97	Not applicable	Vehicle	Tag Number		Not set
Driver	Driver License Restriction	A	Corrective lenses	Vehicle	Tag State	0	Not set
Driver	Driver License State Code	0	Not set	Vehicle	Tag Year	0	Not set
Driver	Driver License Status	C	Current / valid	Vehicle	Tow Status	3	Not towed
Driver	Driver Name Code	0	Not Set	Vehicle	Towed Code	97	Not applicable
Driver	Drug Test Result	97	Not applicable	Vehicle	Unit Type	3	Pick-up
Driver	Drug Test Type	4	No test given	Vehicle	Usage	1	Personal vehicle
Driver	Gender	1	Male	Vehicle	VIN	0	Not set
Driver	Harmful Event	22	Collision with vehicle in traffic	Vehicle	Year		Not set
Driver	Liability Ins. Policy Code	0	Not Set	Uninjured Occupants	Age Code	8	26 - 64
Driver	Liability Insurance NAIC Number Code		Not Set	Uninjured Occupants	Airbag	4	Not deployed, switch on
Driver	Maneuver	1	Movement essentially straight	Uninjured Occupants	Birth Date Code	0	Not Set
Driver	Maneuver	10	Slowing / stopping	Uninjured Occupants	Ejection Status	1	Not ejected or trapped
Driver	Phone Number Code	0	Not Set	Uninjured Occupants	Gender	1	Male
Driver	Place of Employment	99	Unknown	Uninjured Occupants	Occupant Type	1	Driver

LEGEND							
Location	Category	Code	Description	Location	Category	Code	Description
Uninjured Occupants	Safety Equipment	2	Shoulder and lap belt used				
Roadway Environment	Environmental Contributing Circumstance	1	None apparent				
Roadway Environment	Light Condition	7	Dark, continuous illumination, one side of roadway				
Roadway Environment	Locale	2	Residential				
Roadway Environment	Opposing Lane Separation	4	Broken painted line				
Roadway Environment	Road Bridge Condition	1	None apparent				
Roadway Environment	Road Surface Type	1	Asphalt				
Roadway Environment	Roadway Condtion	1	Dry				
Roadway Environment	Roadway Curvature And Grade	1	Straight, level				
Roadway Environment	Roadway Material	1	None				
Roadway Environment	Roadway Material Source	97	Not applicable				
Roadway Environment	Traffic Control	6	Traffic signals				
Roadway Environment	Traffic Control Status	1	Yes				
Roadway Environment	Trafficway Lane Count	2	Two lanes				
Roadway Environment	Turn Lane Presence	1	None				
Roadway Environment	Vision Obscuration	1	Not obscured				
Roadway Environment	Weather Condition	1	Clear				
Roadway Environment	Workzone Law Encorcement Presence	97	Not applicable				
Roadway Environment	Workzone Relationship	1	Not in / related to workzone				
Roadway Environment	Workzone Type	97	Not applicable				