

AST-27 REV. 06/08		Check if A	mendment	T	LA	BAMA	UNIF	ORM	TR	AFFI	C CR	ASH	REP	OR	Γ	Crash F	Report Case	No.	070	00099
112 7 . 00/00		Check if Error	Correction		# Veh	icles # Pe	edestrians 0	# Injure	ed	# Fatalitie	s # Uı	nit 1 Type	Unit 2	2 Type	Loca	al Case No).	202	200002	25208
Sheet_	1						0	U		U		1								
Щ		Date 10	06 2	020	Time		1 .	of Week	Cour	•			City				Rura	ı	ocal Zo	
I ≧		☐ Month I Hwy Class.		Year Street, R	oad, Hi	1618 MT ghway	T	ue	A	Jeff t Intersection	erson on of or Be	tween (No	de 1)			ewood And (Node	2)		22	
9		5				NALLEY A	VE			1 2		KHAM [DR				HILLSI	DE DR	2	
¥		5130			Road/Hiway			650		<> Node Code		6	676				200.00 Feet		1	From Node 1
 		Mile Post			Con	Code trol Access	Primary	Contrib Ci	rcums	Primary C	Contributing		First Har		nt F	First Harmf			Harmful	Event
H		Distance to Fix	N/A red Object	Roa	Hwy dway J	Loc unction/	97 Manner	15 of	Li	Unit # at Coordina	1 te			22 Coordinat		ocation	1 Coordinate	Туре	22 Hwy Sid	le
LOCATION AND TIME		N/ School Bus Re		feet Fea	ture ash Se	1 verity	Crash Distracte	7 d Driving			99			9	9		97		3	3
		1	1			0	(99										1		
1		Driver Full Nan MORGAN A		RA CO	BURI		Street Ac 205 PO	WELL F					City and S	ILLE A			ZIP 35173		ephone 5) 308	-2471
UNIT		0		995	Race 1	Sex DL St		License N	o. 34855	:02		DL Class	DLS		estrict iolations	s 97	CDL Status		Endorse Violation	
NO		Month Place of Emplo		ear		Z AL	-		94000	000		D		,		F	Residence Le	ess		
	ÆR	Liability Insurar	nce Co.					99			Liability P						Than 25 Miles nsurance	S		Yes
LEFT	DRIVER	Driver Conditio	on	Sobrie		Insurance Alcohol:	No	Type	Alcoho	ol	Alcohol T		:00005 Tvr	5881 be Drug		Drug ⁻	NAIC Numbe		laneuver	r
SCENE		1 Most Harmful	1 -		r Opini	on Drugs:	No		Given	6	Results Road Cod		/A Tes	st Given		4 Resul	ts 97		Maneuver 1 Total Injuries in Unit 0 ad Are Shaded der Carriage	
		Event for MV	22	i i avei K		VAL	LEY AVE				51	30		2	1		nstance			0
COM VEH		Sequence of Events	Event 1 22		Ev	ent 2 97	Eve	ent 3 97		Event	⁴ 97		irst Harm vent Loc				Areas D	amaged	Are Sha	.ded
\ \tag{2.11}		Veh Year 2013	Make	HOND		Veh Model	CIVIC EX-	L AUTO)	Во	dy 2		V.I.N. 19X	FB2F9	2DEC	70070	14	Unde	r Carriag	je
VEHICLE or NON-MOTORIST	VEHICLE	Owner's Name		nch M	urrill l	_vons			Licens Tag Nu		9	9484AF:	State	AL	Yea	r 2021	7 _	12		
		Street or R.F.D		City			State				11	D	1	N/A						
		Туре	Usa	05 POV		gency Status	Placard St	atus		d Required		ardous Ca		Hazard	dous Ca		_ 10	\Rightarrow	2	
		1 Attachment	Oversized	Load		97 s, Did Owner	3 Contrib		Spee	97 ed Limit	Est Sp	97 eed	Citati	Releasion Offer			9	13	3	16
		1	N/A	A	Have	e Permit? N/A	Defect 1			35 мрн	ا ا	Jnk _{MPH}	1	N	lone		8	}	4	Totaled
		Damage Sever	rity Towed?	Vehic	le Towe	ed By Whom:	•	•		97	•						7		5	
		Towed To Where: 97 Attachment																		
		Point of Initial Impact 12																		
																	iniuai im	расі _	12	
2	DRIVER	Driver Full Nan THOMAS W		EMA			Street Ac 1305 KE)			PI	City and S	state 1 AL			ZIP 35124		ephone 5) 540	-6857
UNIT		0		962	Race 1	Sex DL St		License N	o. 54266	305		DL Class	DL S		estrict iolations	s 97	CDL Status		Endorse Violation	
NO		Month Place of Emplo		ear	'	I AL	-		74200) 3 3		DIVI		,		F	I Residence Le	ess		
		Liability Insurar	nce Co.					99		T	Liability P						Than 25 Mile: nsurance	S		Yes
LEFT		Driver Conditio	on	Sobrie		Insurance Alcohol:	No	Туре	Alcoho	ol	Alcohol T		414130 Typ	030 be Drug		Drug .	NAIC Numbe Test		laneuver	r
SCENE		1 Most Harmful	1 -	Office		on Drugs:	No	Test	Given	6	Results Road Cod			st Given Direction		4 Resul	ts 97 Contributing		3 Total Inj	
		Event for MV	22 Event 1				LEY AVE	ent 3		Event	51	30	irst Harm	2			nstance	~-	in Unit	0
COM VEH		of Events	22	!	Ev	97	Eve	97		Ш,	97		vent Loc				Areas D			
S VEHICLE or NON-MOTORIST	H	Veh Year 2004	Make	LEXS		Veh Model	LS4	30		Во	dy 2		V.I.N. JTH	BN36F	-X401	24501	14	Unde	r Carriaç	je
		Owner's Name	•	S	ame				Licens Tag Nu		į	58YZ61	State	e AL	Yea	r 2021		12		97
		Street or R.F.D		rag rames			State				11	- D	1	N/A						
	ICLE	Type 1	Usa	ige 1	Emer	gency Status	Placard St	atus	Placare	d Required 97	Haza	ardous Ca 97	rgo		dous Ca	irgo 9	7 10		2	
		Attachment	Oversized	Load	1	s, Did Owner	Contrib		Spee	ed Limit	Est Sp		Citati	Releasion Offer			9	13	3	16
	VEHICL	1	N/A			e Permit? N/A	Defect 1			35 MPH	ı l	Jnk _{MPF}	1	N	lone		8	_}	4	Totaled
		Damage Sever 2	rity Towed?	Vehic	le Towe	ed By Whom:				97							7	6	5	
		Towed To Whe	ere:					97										U	Atta	15 chment
																	Point of Initial Im	pact	6	
1																		_		1





Locale 2

Trafficway

Locale 2

NotApplicable

3

Turn

Workers Present Police Present?

No

Police Present?

No

Workzone Law Enforcement

Present?

One-

Way

Street

DOT Railroad Crossing No.

Contributing

Circumstances

Environment

97

No

Total #

s In Unit

N/A

Total #

in Unit

DOT Railroad Crossing No.

N/A

Contrib Matl In

0

Total #

in Unit

0

Total Number of Units 2

97

Total Number of Units

2

No.

Contrib

Material

Source

Involved Road/

Rdway

Curve &

Grade

Light

Roadway Condition

Traffic

Control

Road Surface

Type

Vision

Obscur

ed Bv

Light 1 Weather

Weather

Workzone

Type

Opposing

Separation

Workzone

Related?

Traffic

Control

Functioning

INVESTIGATION									
Name of Photographer		N/A							
Time Police Notified 1618 MT	Time Police Arrived 1633 MT	Time EMS Arrived N/A	EMS Respor	nse Run # N/A					
Name of Investigating Office	Joseph N Bull	ard		Officer ID 52	1	Agency ORI AL0011000			
Name of Investigating Office	er			Officer ID		Agency ORI	_		
The data on this report reflects the best knowledge, opinion, and belief regarding the crash, but no warrant is made as to the factual accuracy thereof.									

LEGEND									
Location	Category	Code	Description	Location	Category	Code	Description		
Report Header	Unit Type	1	Passenger car	Driver	Race	1	White / Caucasian		
Location And Time	Contributing Circumstance	15	Followed too close	Driver	Residence Within 25 Miles	Yes	Yes		
Location And Time	Contributing Unit	10	Unit1	Driver	Travel Direction	2	East		
Location And Time	Controlled Access Highway Location	97	Not a controlled access highway	Vehicle	Attachment	1	None		
Location And Time	Coordinate Status	99	Unknown	Vehicle	Body	2	Four door		
Location And Time	Coordinate Type	97	Not applicable	Vehicle	Citation Offense	99	None		
Location And Time	Crash Manner	7	Rear end (front-to-rear)	Vehicle	Damage Severity	2	Minor		
Location And Time	Crash Severity	0	Property damage only	Vehicle	Defect	1	None		
Location And Time	Distance Node Unit	10	Feet	Vehicle	Emergency Status	97	Not applicable		
Location And Time	Distracted Driving	99	Unknown	Vehicle	Estimated Speed Code	Unk	Unknown		
Location And Time	Harmful Event	22	Collision with vehicle in traffic	Vehicle	Hazardous Cargo	97	Not applicable		
Location And Time	Highway Classification	5	Municipal	Vehicle	Hazardous Cargo Release Type	97	Not applicable		
Location And Time	Highway Side	3	Eastbound	Vehicle	K12 Child Going To Or From School	0	Not Set		
Location And Time	Roadway Feature	1	No special feature	Vehicle	Make	HOND	Honda		
Location And Time	School Bus Related	1	No school bus involved	Vehicle	Make	LEXS	Lexus		
Location And Time	Time Display Format	20	Military	Vehicle	Non-Motorist Action	0	Not Set		
Driver	Alcohol Test Type	6	No Test Given	Vehicle	Non-Motorist Location	0	Not Set		
Driver	Commercial Driver License Status	97	Not applicable / unlicensed	Vehicle	Oversized Load	N/A	NotApplicable		
Driver	Contributing Circumstance	15	Followed too close	Vehicle	Oversized Load Permit	N/A	NotApplicable		
Driver	Contributing Circumstance	97	Not applicable	Vehicle	Owner Address Code	0	Not Set		
Driver	Driver Address Code	0	Not Set	Vehicle	Owner Address Code	Same	Same		
Driver	Driver Condition	1	Apparently normal	Vehicle	Owner Name Code		Not Set		
Driver	Driver License Class Code	0	Not set	Vehicle	Owner Name Code	Same	Same as driver		
Driver	Driver License Endorsement	97	Not applicable	Vehicle	Placard Requirement	97	Not applicable		
Driver	Driver License Number	0	Not set	Vehicle	Placard Status	3	Not applicable (placard not required)		
Driver	Driver License Restriction	97	Not applicable	Vehicle	Tag Number		Not set		
Driver	Driver License State Code	0	Not set	Vehicle	Tag State	0	Not set		
Driver	Driver License Status	С	Current / valid	Vehicle	Tag Year	0	Not set		
Driver	Driver Name Code	0	Not Set	Vehicle	Tow Status	3	Not towed		
Driver	Drug Test Result	97	Not applicable	Vehicle	Towed Code	97	Not applicable		
Driver	Drug Test Type	4	No test given	Vehicle	Unit Type	1	Passenger car		
Driver	Gender	1	Male	Vehicle	Usage	1	Personal vehicle		
Driver	Gender	2	Female	Vehicle	VIN	0	Not set		
Driver	Harmful Event	22	Collision with vehicle in traffic	Vehicle	Year		Not set		
Driver	Liability Ins. Policy Code	0	Not Set	Uninjured Occupants	Age Code	7	21 - 25		
Driver	Liability Insurance NAIC Number Code		Not Set	Uninjured Occupants	Age Code	8	26 - 64		
Driver	Maneuver	1	Movement essentially straight	Uninjured Occupants	Airbag	4	Not deployed, switch on		
Driver	Maneuver	3	Turning right	Uninjured Occupants	Birth Date Code	0	Not Set		
Driver	Phone Number Code	0	Not Set	Uninjured Occupants	Ejection Status	1	Not ejected or trapped		
Driver	Place of Employment	99	Unknown	Uninjured Occupants	Gender	1	Male		

			LEG	END
Location	Category	Code	Description	Loc
Uninjured Occupants	Gender	2	Female	
Uninjured Occupants	Occupant Type	1	Driver	
Uninjured Occupants	Safety Equipment	99	Unknown	
Roadway Environment	Environmental Contributing Circumstance	1	None apparent	
Roadway Environment	Light Condition	1	Daylight	
Roadway Environment	Locale	2	Residential	
Roadway Environment	Opposing Lane Separation	2	Paved surface	
Roadway Environment	Road Bridge Condition	1	None apparent	
Roadway Environment	Road Surface Type	1	Asphalt	
Roadway Environment	Roadway Condtion	1	Dry	
Roadway Environment	Roadway Curvature And Grade	1	Straight, level	
Roadway Environment	Roadway Material	1	None	
Roadway Environment	Roadway Material Source	97	Not applicable	
Roadway Environment	Traffic Control	1	No controls present	
Roadway Environment	Traffic Control Status	97	Not applicable	
Roadway Environment	Trafficway Lane Count	3	Three lanes	
Roadway Environment	Turn Lane Presence	4	Both left and right turn lanes	
Roadway Environment	Vision Obscuration	1	Not obscured	
Roadway Environment	Weather Condition	1	Clear	
Roadway Environment	Workzone Law Encorcement Presence	97	Not applicable	
Roadway Environment	Workzone Relationship	1	Not in / related to workzone	
Roadway Environment	Workzone Type	97	Not applicable	

Code

Description

Category

Location