

DUAL PRODUCT QUALITY COMPLAINT & SAFETY INCIDENT REPORT

PART A: PRODUCT QUALITY COMPLAINT (PQC)

Product Name:	SynthoVial
Batch / Lot Number:	Lot B9912
Defect Description:	Cracked glass vial neck with product leakage upon carton opening
Packaging Condition:	Damaged packaging / cracked vial
Photograph Mentioned:	Yes (Defect diagram embedded below)

PART B: ADVERSE EVENT REPORT (ICSR)

Patient:	Male, 49 years old, 74 kg
Adverse Reaction:	Severe localized itching, erythema, and rash on hands
Reaction Onset:	26 Aug 2026
Outcome:	Recovering
Reporter:	Dr. Henderson, General Practitioner, United States

ATTACHED DEFECT PHOTOGRAPH / SCHEMATIC:

