

C1: Vessel-vs-Job Capability Heatmap

Shallow Water Barge - Shallow-Water Pipelay: 100.0% pass rate across 30 cases; current matrix totals 156 cases.

 Large CSV | Mudmat Installation | 100.0% | 18/18 pass; limiting: Landing bearing pressure

 Large CSV | Jumper Installation | 20.0% | 6/30 pass; limiting: Tie-in alignment tolerance

 Medium CSV | Mudmat Installation | 100.0% | 18/18 pass; limiting: Splash zone hydrodynamic loads

 Medium CSV | Jumper Installation | 20.0% | 6/30 pass; limiting: Tie-in alignment tolerance

 Large PLV | Shallow-Water Pipelay | 83.3% | 25/30 pass; limiting: tension

 Shallow Water Barge | Shallow-Water Pipelay | 100.0% | 30/30 pass; limiting: overbend

Colour cue: green $\geq 80\%$ pass/utilisation margin OK, amber 50-79%, red $< 50\%$ or high utilisation risk

Vessel parameters are representative classes only; not measured telemetry or exact specifications of any named vessel.