

Mission Briefing

MISSION

- Navigation system nominal
- Objective: arrive at port by 16:00
- Communication with port authority is critical

 Ops

TURN 0

Steady Approach

AIR PICTURE

- Air picture clear
- No contacts of concern

 AAWO

TURN 1

Steady Approach

CYBER

- No alerts
- Routine monitoring

 CyOp

TURN 1

Steady Approach

SYSTEMS

- All systems nominal
- No open defects

 EO

TURN 1

Steady Approach

APPROACH

- Course and speed steady at 12 kts
- Channel approach bearing 270
- Visibility ~5 nm

STATUS

- Port approach on schedule
- Pilot boarding in 45 minutes
- No updated traffic warnings

 NAV

TURN 1

Steady Approach

SURFACE

- Surface picture normal
- Several merchant vessels in approach lane

 PWO

TURN 1

Losing Contact

COMMS

- COMMS breaking on port authority channel
- Messages arriving with 10-15 second delays
- Likely congestion on shared VHF frequency

 NAV

TURN 2

Losing Contact

ANOMALY

- GPS and chart position show 0.3 nm lateral offset
- Ship drifting south of planned approach track
- Current stronger than forecast

 NAV

TURN 2

Blind Approach

COMMS

- VHF device works OK

 EO

TURN 3

Blind Approach

ROUTE OPTIONS

- Current correction calculated
- Option A: maintain speed, correct course
- Option B: reduce speed, correct course

 **NAV**

TURN 3

Blind Approach

SURFACE

- Radar / blind navigation drift confirmed

 **PWO**

TURN 3