



VGN MARBLE ARCH – PROJECT PROGRESS UPDATE AS OF 16-09-2025



DINING



KITCHEN



LIVING ROOM



BEDROOM



16-Sep-2025

A-BLOCK – ARCH WORK HAS BEEN COMPLETED



16-Sep-2025

**A-BLOCK – FRONT SIDE ELEVATION: SECOND COAT
PAINTING WORK HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – SECOND COAT EXTERIOR PAINTING WORK
ON THE NORTH FACING SIDE HAS BEEN COMPLETED**



A-BLOCK – ENTRANCE GLASS WORK HAS BEEN COMPLETED



16-Sep-2025

**A-BLOCK – STILT FLOOR MARBLE WORK
HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – STAIRCASE HANDRAIL WORK
HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – FIRST FLOOR CORRIDOR SECOND COAT
PAINTING WORK HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – FIRST, SECOND AND THIRD FLOOR DOOR
INSTALLATION WORK HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – FIRST FLOOR SECOND COAT PAINTING
WORK HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK FIRST FLOOR – SECOND COAT PAINTING
WORK HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – FIRST FLOOR KITCHEN COUNTERTOP
WORK HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – FIRST FLOOR BATHROOM SHOWER GLASS
FIXING WORK HAS BEEN COMPLETED**



**A-BLOCK – FIRST FLOOR BATHROOM CP FITTING
WORK HAS BEEN COMPLETED**



16-Sep-2025

A-BLOCK – SECOND FLOOR CORRIDOR SECOND COAT PAINTING WORK HAS BEEN COMPLETED



16-Sep-2025

**A-BLOCK – CORRIDOR CEILING LIGHTING WORK
HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – STAIRCASE LIGHTING WORK HAS
BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – SECOND FLOOR BATHROOM CP
FITTING WORK HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – THIRD FLOOR SECOND COAT PAINTING
WORK IN THE CORRIDOR HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – THIRD FLOOR SECOND COAT
PAINTING WORK HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – THIRD FLOOR SECOND COAT
PAINTING WORK HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – THIRD FLOOR KITCHEN COUNTERTOP
WORK HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – THIRD FLOOR BATHROOM CP
FITTING WORK HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – FIRST, SECOND AND THIRD FLOOR BALCONY
HANDRAIL WORK HAS BEEN COMPLETED**



**A-BLOCK – SOLAR PANEL INSTALLATION WORK
HAS BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – EXTERNAL ELEVATION LIGHTING
WORK HAS BEEN COMPLETED**



**A-BLOCK – EXTERNAL ELEVATION CCTV
CAMERA FIXING WORK HAS BEEN COMPLETED**



16-Sep-2025

A-BLOCK – LIFT WORK HAS BEEN COMPLETED



16-Sep-2025

**A-BLOCK – PAVER BLOCK ROAD WORK HAS
BEEN COMPLETED**



16-Sep-2025

**A-BLOCK – CAR PARKING EV CHARGING POINT
WORK HAS BEEN COMPLETED**



A-BLOCK – BOOM BARRIER WORK HAS BEEN COMPLETED



16-Sep-2025

**B-BLOCK – SECOND COAT PAINTING WORK ON
THE FRONT ELEVATION HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – SECOND COAT PAINTING WORK ON
THE STILT FLOOR HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – SECOND COAT PAINTING WORK ON
THE STILT FLOOR HAS BEEN COMPLETED**

1		Marble Arch	B- BLOCK
B101		MR. RICHARD & MRS. ALISHA	
B102		MRS. SHARMILA DEVI M	
B103		MRS. BHAVYA CHANDRAMOULI	
B104		MR. AYYAKKUTTI V	
2			
B201		MS. PADMAPRIYA K	
B202		MS. GAYATHRI GUNALAN	
B203			
B204		MR. SANDEEP VENKATACHARI	
B301		MR. RAJESH P	



16-Sep-2025

**B-BLOCK – ENTRANCE GLASS WORK HAS
BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – STAIRCASE HANDRAIL WORK
HAS BEEN COMPLETED**



16-Sep-2025

B-BLOCK – MARBLE WORK HAS BEEN COMPLETED



16-Sep-2025

B-BLOCK – LIFT WORK HAS BEEN COMPLETED



16-Sep-2025

B-BLOCK – 1ST , 2ND & 3RD FLOOR CORRIDOR SECOND COAT PAINTING WORK HAS BEEN COMPLETED



16-Sep-2025

**B-BLOCK FIRST AND SECOND FLOOR – DOOR
INSTALLATION WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – FIRST FLOOR SECOND COAT
PAINTING WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – FIRST FLOOR SECOND COAT
PAINTING WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – WINDOW FRAME AND DOOR FIXING WORK ON
THE FIRST AND SECOND FLOOR HAS BEEN COMPLETED**



**B-BLOCK – FIRST FLOOR KITCHEN COUNTERTOP
WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – FIRST FLOOR TOILET FALSE CEILING
WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – FIRST FLOOR SHOWER GLASS
PARTITION WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – SECOND FLOOR FIRST COAT
PAINTING WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – SECOND FLOOR KITCHEN
COUNTERTOP WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – SECOND FLOOR TOILET FALSE
CEILING WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – SECOND FLOOR SHOWER GLASS
PARTITION WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – FIRST, SECOND AND THIRD FLOOR WINDOW
FIXING WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – DOOR INSTALLATION WORK ON THE
THIRD FLOOR HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – THIRD FLOOR PAINTING WORK HAS
BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – THIRD FLOOR PAINTING WORK
HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – THIRD FLOOR TOILET FALSE CEILING
WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – THIRD FLOOR SHOWER GLASS
PARTITION WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – TERRACE COOLING TILE WORK
HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – TERRACE SOLAR PANEL
INSTALLATION WORK HAS BEEN COMPLETED**



**B-BLOCK – EXTERNAL ELEVATION LIGHT
FIXING WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – EXTERNAL ELEVATION CCTV CAMERA
FIXING WORK HAS BEEN COMPLETED**



16-Sep-2025

**B-BLOCK – PAVER BLOCK ROAD WORK HAS
BEEN COMPLETED**



16-Sep-2025

B-BLOCK – BOOM BARRIER WORK HAS BEEN COMPLETED



16-Sep-2025

A & B-BLOCK – D.G WORK HAS BEEN COMPLETED



16-Sep-2025

**A & B-BLOCK – CENTER PAVER BLOCK ROAD
WORK HAS BEEN COMPLETED**



16-Sep-2025

A & B BLOCK – GAS BANK WORK IS IN PROGRESS



THANK YOU