Edit 100% Analytics Filters

Tab 1

Total Units Produced

4.19K

Units Produced

Defect Rate %

267.11

Defect Rate %

Downtime Hours

102.5

Downtime Hours

Scrap Cost

7.84M

Scrap Cost

Plant Location

Chennai

Production Date

Select value

Units Produced by Plant

Monthly Defect Trend



Defect Type Distribution



Edit 100% Analytics Filters

Tab 1

Units Produced by Plant



Monthly Defect Trend



Defect Type Distribution



Raw Material Supplier and Material Cost per Unit

Rank (Material Cost p...	Raw Material Supplier	Material Cost per Unit
1	GlassMart	2,016,033.13
2	AutoParts India	2,001,256.78
3	ElecComp	1,712,820.22


4.19K
Units Produ
Defect Rate %: 267.11
267.11
Defect Rate %
102.5
Downtime Hours
7.84M
Scrap Cost
Plant Location
Chennai
Production Date
Select value
Units Produced by Plant
Plant Location
Ahmedabad
Chennai
Pune
Monthly Defect Trend
12
Defect Type Distribution
Defect Type
None
Assembly Gap
Trim Issue
Paint Defect
Engine Noise
Electrical Fault
Weld Failure

Tab 1

Total Units Produced

4.19K

Units Produced

Defect Rate %

267.11

Defect Rate %

Downtime Hours

102.5

Downtime Hours

Scrap Cost

7.84M

Scrap Cost

Plant Location

Chennai

Production Date

Select value

2024-01-02

2024-01-13

2024-01-14

2024-01-15

2024-01-22

Units Produced by Plant

Plant Location

Ahmedabad Chennai Pune

Ahmedabad

Chennai

Monthly Defect Trend

12

10

8

Electrical Fault Weld Failure

13

Units Produced by Plant



Raw Material Supplier and Material Cost per Unit

Rank (Material Cost pe...	Raw Material Supplier	Material Cost per Unit
1	PlastiTech	406,045.0
2	SteelCo	367,579.1
3	GlassMart	164,918.7

Monthly Defect Trend



Defect Type Distribution