


Fault Code: 219

Low Oil Level Detected in Centinel™ Make Up Tank

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 219 PID(P): P17 SPN: 1380 FMI: Lamp: Warning SRT:	Engine oil level 2 (remote) low - maintenance. Low oil level is detected in the remote oil reservoir used in the Centinel™ system.	Centinel™ system is deactivated.



ECM

Circuit Description

The oil make up tank provides clean oil to the make up valve of the Centinel™ system to replenish oil that was burned by the Centinel™ system.

Component Location

Varies by installation. Refer to Centinel™ Master Repair Manual 3666231 for further information.

Shoptalk

This fault indicates that the oil is low in the makeup tank.

Refer to Troubleshooting Fault Code t05-219 (/qs3/pubsys2/xml/en/procedures/01/01-t05-219.html)

Last Modified: 29-Jul-2010
