



Service Tool Instruction

**Service Tool Instruction
Number: 3400422**

Revision Level:

**Released Date: 27-oct-
2011**


Description

Inspection Gauge

Purpose

This document provides information for inspection gauge, Part Number 5298508. The gauge is used to check the cylinder head valve guide bore for distortion, and used with valve guide reamer, Part Number 5298510, for repair of QSK19, QSK45, and QSK60 engines.

- For the QSK19, use the following procedure for additional information on the valve guide inspection gauge in the QSK19, QSK19 CM850 MCRS, and QSK19 CM2150 MCRS Service Manual, Bulletin 4021592. Refer to Procedure 002-004 in Section 2.
(/qs3/pubsys2/xml/en/procedures/20/20-002-004-tr.html)
- For the QSK45, QSK60, QSK60 CM850 MCRS and QSK60 CM2150 MCRS, use the following procedure for additional information on the valve guide inspection gauge in the QSK45 and QSK60 Service Manual, Bulletin 4021530. Refer to Procedure 002-004 in Section 2.
(/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)



Inspection Gauge, Part Number 5298508

Document History

Date	Details
2011-10-11	Module Created

Last Modified: 19-Jul-2012
