

Tel: (603) 33417406 Fax: (603) 33417416 www.rentwise.com

Service Order Form

TECHNICAL HOTLINE:
1-800-88-0688

	Service Order Form		1-800-88-0688		
Company	MALAYSIA DEEPWATER PRODUCTION CONTRACTORS SDN BHD	CSV#	161		
Address	Level 9, Menara Perak,	Call date	2013-10-29		
	24, Jalan Perak, 50450 Kuala Lumpur,	Call time	16:45		
Contact person	Rosli (PIC) (Tel:012-2618256 Email: Eis.Rentwise@eis2u.com)	Attended by	vanita		
Asset Tag N	10039672 Serial No CNC634RKWL				
roduct Name (HP 19" LCD BLK/SLV					
Fault Description					
Remark	Engineer to check the faulty monitor and replaced 1 x Monitor(M0024420) if necessary.				
Work performed					
Chargeable?					
Description	of Item/Service U	nit Price (RM)	Qty	Total	

I/we acknowledge receipt of the above mentioned item/s and certify that the service has been carried out to my/our satisfaction. I/we hereby agree to pay for the damages and labour charges incurred if any and relevant consumption taxes that may be levied by the government.

Serviced by:

Name: Date:

Name: Date:	Company Stamp
Internal use only:-	

