REPAIR CUSTOMER COPY

Repair ID : 1003

Vehicle : Fascino TN58BR1234

Date : 08-06-2026

Pay Mode : -

Description:

engine oil, air filter, labour cost

Total : ₹ 2,000.00

Advance : ₹ 0.00

Balance : ₹ 2,000.00

Thank you for your order,visit again.