



Site Safety Inspection

Inspection Details

Project/ job reference:	50 Dutton Street BANKSTOWN
Location:	50 Dutton Street Bankstown
Area inspected:	site excavation
Inspected by:	Leonardo milidone
Date:	2023-06-30

Inspection Checklist

Site Documents	YES
a	
Site signage displayed	YES
a	
Safety signs displayed	YES
a	
Mandatory PPE displayed	YES
a	
Policies displayed	YES
a	
Site rules displayed	YES
a	
Emergency information displayed	YES
a	
First Aid officers displayed	YES
a	
Sign in / our register present	YES
a	
Site Security	YES

a	
Site fence / hoarding present	YES
a	
Appropriate barricades in place	YES
a	
Site access is controlled	YES
a	
Public access is controlled	YES
a	
Safe access and egress in place	YES
a	
Site Processes	YES
a	
All workers inducted on site	YES
a	
All workers inducted onto their SWMS / SOPS	YES
a	
All workers have white cards	YES
a	
All workers following site processes	YES
a	
Daily pre-start meetings being held	YES
a	
Toolbox talks regularly conducted	YES
a	
Housekeeping	YES
a	
Site generally clean	YES

a	
Walkways are clear of obstruction	YES
a	
Materials are safely stowed away	YES
a	
Rubbish and debris is disposed of	YES
a	
Slurry, water and dust removed	YES
a	
Amenities	YES
a	
Sufficient toilets / bubblers provided	YES
a	
Lunchroom and facilities provided	YES
a	
Amenities are clean and tidy	YES
a	
Electrical	YES
a	
Temporary power boards present	YES
a	
Temporary power boards fitted with RCD	N/A
a	
Temporary power board secured to the ground / base	N/A
a	
Temporary power board compliant with AS/NZS 3012:2010	N/A
a	
Electrical equipment has current test tag	N/A

a	
Electrical equipment connected to RCDs	N/A
a	
Extension leads have current test tag	N/A
a	
Electrical leads are elevated off the ground with lead stands / hooks	N/A
a	
Electrical equipment and leads are in good condition	N/A
a	
Working at Heights	N/A
a	
All falls 2m or more are protected	N/A
a	
Temporary edge protection (handrails, mid-rails, toe boards) installed at all leading edges	N/A
a	
Extension ladders secured at top and bottom before use	N/A
a	
Height safety equipment has current test tag	N/A
a	
Penetrations and Voids	N/A
a	
Penetration covers are mechanically fixed and marked	N/A
a	
Where necessary cast in mesh is installed into slab	N/A
a	
Lift shafts / service voids have covers or barriers installed, secured and marked	N/A
a	
Guards in place over stair voids	N/A

a	
Areas delineated / barricaded	N/A
a	
Materials fall protection	N/A
a	
Netting covers all perimeter scaffolding	N/A
a	
Toe boards installed on all guard rails	N/A
a	
Core holes / penetrations / voids covered and mechanically fixed	N/A
a	
Scaffolds	N/A
a	
Scaffold has current test and tag at all entry points	N/A
a	
Handover certificate available	N/A
a	
Adequately braced / tied	N/A
a	
Gaps between scaffold and working face do not exceed 225mm	N/A
a	
All scaffold components are intact	N/A
a	
Access ladders / stairs free of debris, materials etc.	N/A
a	
Bays free from obstruction	N/A
a	
Minimum 450mm wide gap available on bays for worker access	N/A

a	
Bays are not being point loaded	N/A
a	
Bays are not being overloaded	N/A
a	
No missing scaffold planks	N/A
a	
Sole plates founded on solid base	N/A
a	
Lapboards are mechanically secured	N/A
a	
Incomplete scaffold has been barricaded and closed off + signs erected	N/A
a	
PPE	YES
a	
Workers are wearing mandatory PPE	YES
a	
Workers observed using PPE correctly for their tasks (e.g. face masks)	YES
a	
PPE complies with regulatory requirements	YES
a	
Ladders	N/A
a	
Only industrial strength ladders used	N/A
a	
Ladders are in good condition and free of damage	N/A
a	
Safety labels are intact	NO

a	
Extension ladders secured at top and bottom	N/A
a	
Extension ladders extend 1m past top of landing	N/A
a	
Extension ladders placed at correct angle (1:4)	N/A
a	
Ladders not used on scaffold / near fall risks	N/A
a	
Ladders not used in entrance ways / paths of travel without exclusion zone	N/A
a	
Trenches and Excavations	YES
a	
DBYD been obtained before work	N/A
a	
Services have been located and potholed	YES
a	
Excavations / trenches barricaded and sign posted	YES
a	
Correct trench support used where necessary	YES
a	
Trenches greater than 1.5m have edge protection and safe access / egress	YES
a	
Edges of excavations / trenches clear of spoil / materials	YES
a	
Hazardous substances	N/A
a	
Register is kept on site and up to date	YES

a	
SDS available for all hazardous substances	YES
a	
Appropriate signage displayed	YES
a	
adequately stored and ventilated	YES
a	
Kept in original containers with labels	YES
a	
Spill kit available on site	YES
a	
Emergency and First Aid	YES
on site	
Emergency access kept clear at all times	YES
a	
Emergency exit points clearly marked	YES
a	
Emergency evacuation plan displayed	YES
a	
Emergency assembly point displayed	YES
a	
Emergency contact details displayed	YES
a	
Adequate firefighting equipment available	YES
a	
Firefighting equipment has current test tag	YES
a	
First Aid officer & contact displayed	YES

a	
First aid signage displayed	YES
a	
First aid kit fully stocked	YES
a	
First aid and emergency personnel are trained / current certificates	YES
a	
Injury register maintained on site	YES
a	
Hot works are approved and adequately controls / emergency response measures in place	N/A
a	
Cranes	N/A
a	
Certificate of registration available	N/A
a	
Insurances available	N/A
a	
Maintenance and service records available and up to date	N/A
a	
Pre-start inspection are being completed	N/A
a	
Crane crew hold appropriate licences / competency	N/A
a	
Exclusion being used during movement of loads	N/A
a	
Emergency response measures in place	YES
a	
Mobile Plant	YES

a	
Certificate of registration available	YES
a	
Insurances available	YES
a	
Maintenance and service records available and up to date	YES
a	
Operators hold appropriate licences / competency	YES
a	
Exclusion being used where necessary	YES
a	
Emergency response measures in place	YES
a	
Lifting Equipment	YES
a	
Register available and maintained on site	YES
a	
Equipment has current test tag	YES
a	
Equipment correctly stored	YES
a	
Equipment inspected before use	YES
a	
Traffic Control / Public Safety	YES
a	
Traffic Management/ Control plan in place	YES
a	
Fencing / barriers to stop public access to site	YES

a	
Public areas kept clear of materials / rubbish / operations	YES
a	
Traffic controllers certified	N/A
a	
Signs and devices in use	YES
a	
General / additional comments & notations	
Excavation works inspection completed, confirming full compliance with regulatory standards and safety protocols. Thorough examination conducted, and all aspects of the excavation site have been inspected, ensuring adherence to specified guidelines.	