



Site Safety Inspection

Inspection Details

Project/ job reference:

Location:

15 Redmyre Rd Strathfield

Area inspected:

Plumbing

Inspected by:

Aaron

Date:

2025-03-04

Inspection Checklist

Site Documents

YES

Yes

Site signage displayed

YES

Yes

Safety signs displayed

YES

Yes

Mandatory PPE displayed

YES

Yes

Policies displayed

YES

Yes

Site rules displayed

YES

Yes

Emergency information displayed

YES

Yes

First Aid officers displayed

YES

Yes

Sign in / our register present

YES

Yes

Site Security

YES

Yes	
Site fence / hoarding present	YES
Yes	
Appropriate barricades in place	YES
Yes	
Site access is controlled	YES
Yes	
Public access is controlled	YES
Yes	
Safe access and egress in place	YES
Yes	
Site Processes	YES
Yes	
All workers inducted on site	YES
Yes	
All workers inducted onto their SWMS / SOPS	YES
Yes	
All workers have white cards	YES
Yes	
All workers following site processes	YES
Yes	
Daily pre-start meetings being held	YES
Yes	
Toolbox talks regularly conducted	YES
Yes	
Housekeeping	YES
Yes	
Site generally clean	YES

Yes	
Walkways are clear of obstruction	YES
Yes	
Materials are safely stowed away	YES
Yes	
Rubbish and debris is disposed of	YES
Yes	
Slurry, water and dust removed	YES
Yes	
Amenities	YES
Yes	
Sufficient toilets / bubblers provided	YES
Yes	
Lunchroom and facilities provided	YES
Yes	
Amenities are clean and tidy	YES
Yes	
Electrical	YES
Yes	
Temporary power boards present	YES
Yes	
Temporary power boards fitted with RCD	YES
Yes	
Temporary power board secured to the ground / base	YES
Yes	
Temporary power board compliant with AS/NZS 3012:2010	YES
Yes	
Electrical equipment has current test tag	YES

Yes	
Electrical equipment connected to RCDs	NO
Yes	
Extension leads have current test tag	YES
Yes	
Electrical leads are elevated off the ground with lead stands / hooks	YES
Yes	
Electrical equipment and leads are in good condition	YES
Yes	
Working at Heights	YES
Yes	
All falls 2m or more are protected	YES
Yes	
Temporary edge protection (handrails, mid-rails, toe boards) installed at all leading edges	YES
Yes	
Extension ladders secured at top and bottom before use	YES
Yes	
Height safety equipment has current test tag	YES
Yes	
Penetrations and Voids	YES
Yes	
Penetration covers are mechanically fixed and marked	YES
Yes	
Where necessary cast in mesh is installed into slab	YES
Yes	
Lift shafts / service voids have covers or barriers installed, secured and marked	YES
Yes	
Guards in place over stair voids	YES

Yes	
Areas delineated / barricaded	YES
Yes	
Materials fall protection	YES
Yes	
Netting covers all perimeter scaffolding	YES
Yes	
Toe boards installed on all guard rails	YES
Yes	
Core holes / penetrations / voids covered and mechanically fixed	YES
Yes	
Scaffolds	YES
Yes	
Scaffold has current test and tag at all entry points	YES
Yes	
Handover certificate available	YES
Yes	
Adequately braced / tied	YES
Yes	
Gaps between scaffold and working face do not exceed 225mm	YES
Yes	
All scaffold components are intact	YES
Yes	
Access ladders / stairs free of debris, materials etc.	YES
Yes	
Bays free from obstruction	YES
Yes	
Minimum 450mm wide gap available on bays for worker access	YES

Yes	
Bays are not being point loaded	YES
Yes	
Bays are not being overloaded	YES
Yes	
No missing scaffold planks	YES
Yes	
Sole plates founded on solid base	YES
Yea	
Lapboards are mechanically secured	YES
Yes	
Incomplete scaffold has been barricaded and closed off + signs erected	YES
Yes	
PPE	YES
Yes	
Workers are wearing mandatory PPE	YES
Yes	
Workers observed using PPE correctly for their tasks (e.g. face masks)	YES
Yes	
PPE complies with regulatory requirements	YES
Yes	
Ladders	YES
Yes	
Only industrial strength ladders used	YES
Yes	
Ladders are in good condition and free of damage	YES
Yes	
Safety labels are intact	NO

Yes	
Extension ladders secured at top and bottom	YES
Yes	
Extension ladders extend 1m past top of landing	YES
Yes	
Extension ladders placed at correct angle (1:4)	YES
Yes	
Ladders not used on scaffold / near fall risks	YES
Yes	
Ladders not used in entrance ways / paths of travel without exclusion zone	YES
Yes	
Trenches and Excavations	YES
Yes	
DBYD been obtained before work	YES
Yes	
Services have been located and potholed	YES
Yes	
Excavations / trenches barricaded and sign posted	YES
Yes	
Correct trench support used where necessary	YES
Yes	
Trenches greater than 1.5m have edge protection and safe access / egress	YES
Yes	
Edges of excavations / trenches clear of spoil / materials	YES
Yes	
Hazardous substances	NO
No	
Register is kept on site and up to date	YES

Yes	
SDS available for all hazardous substances	YES
Yes	
Appropriate signage displayed	YES
Yes	
adequately stored and ventilated	YES
Yes	
Kept in original containers with labels	YES
Yes	
Spill kit available on site	YES
Yes	
Emergency and First Aid	YES
Yes	
Emergency access kept clear at all times	YES
Yes	
Emergency exit points clearly marked	YES
Yes	
Emergency evacuation plan displayed	YES
Yes	
Emergency assembly point displayed	YES
Yes	
Emergency contact details displayed	YES
Yes	
Adequate firefighting equipment available	YES
Yes	
Firefighting equipment has current test tag	YES
Yes	
First Aid officer & contact displayed	YES

Yes	
First aid signage displayed	YES
Yes	
First aid kit fully stocked	YES
Yes	
First aid and emergency personnel are trained / current certificates	YES
Yes	
Injury register maintained on site	YES
Yes	
Hot works are approved and adequately controls / emergency response measures in place	YES
Yes	
Cranes	NO
No	
Certificate of registration available	YES
Yes	
Insurances available	YES
Yes	
Maintenance and service records available and up to date	YES
Yes	
Pre-start inspection are being completed	YES
Yes	
Crane crew hold appropriate licences / competency	N/A
N/A	
Exclusion being used during movement of loads	YES
Yes	
Emergency response measures in place	YES
Yes	
Mobile Plant	N/A

Yes	
Certificate of registration available	YES
Yes	
Insurances available	YES
Yes	
Maintenance and service records available and up to date	YES
Yes	
Operators hold appropriate licences / competency	YES
Yes	
Exclusion being used where necessary	YES
Yes	
Emergency response measures in place	YES
Yes	
Lifting Equipment	YES
Yes	
Register available and maintained on site	YES
Yes	
Equipment has current test tag	YES
Yes	
Equipment correctly stored	YES
Yes	
Equipment inspected before use	YES
Yes	
Traffic Control / Public Safety	YES
Yes	
Traffic Management/ Control plan in place	YES
Yes	
Fencing / barriers to stop public access to site	YES

Yes	
Public areas kept clear of materials / rubbish / operations	YES
Yes	
Traffic controllers certified	YES
Yes	
Signs and devices in use	YES
Yes	
General / additional comments & notations	
N/A	