



Site Safety Inspection

Inspection Details

Project/ job reference:

Location:

11 Cheddar st

Area inspected:

Full site

Inspected by:

Leonardo

Date:

2025-09-17

Inspection Checklist

Site Documents

YES

Na

Site signage displayed

YES

N

Safety signs displayed

YES

N

Mandatory PPE displayed

YES

N

Policies displayed

YES

N

Site rules displayed

YES

N

Emergency information displayed

YES

N

First Aid officers displayed

YES

N

Sign in / our register present

YES

N

Site Security

YES

N	
Site fence / hoarding present	YES
N	
Appropriate barricades in place	YES
N	
Site access is controlled	YES
N	
Public access is controlled	YES
N	
Safe access and egress in place	YES
N	
Site Processes	YES
N	
All workers inducted on site	YES
N	
All workers inducted onto their SWMS / SOPS	YES
N	
All workers have white cards	YES
N	
All workers following site processes	YES
N	
Daily pre-start meetings being held	YES
N	
Toolbox talks regularly conducted	YES
N	
Housekeeping	YES
N	
Site generally clean	YES

N	
Walkways are clear of obstruction	YES
N	
Materials are safely stowed away	YES
N	
Rubbish and debris is disposed of	YES
N	
Slurry, water and dust removed	YES
N	
Amenities	YES
N	
Sufficient toilets / bubblers provided	YES
N	
Lunchroom and facilities provided	YES
N	
Amenities are clean and tidy	YES
N	
Electrical	YES
N	
Temporary power boards present	YES
N	
Temporary power boards fitted with RCD	YES
N	
Temporary power board secured to the ground / base	YES
N	
Temporary power board compliant with AS/NZS 3012:2010	YES
N	
Electrical equipment has current test tag	YES

N	
Electrical equipment connected to RCDs	NO
N	
Extension leads have current test tag	YES
N	
Electrical leads are elevated off the ground with lead stands / hooks	YES
N	
Electrical equipment and leads are in good condition	YES
N	
Working at Heights	YES
N	
All falls 2m or more are protected	YES
N	
Temporary edge protection (handrails, mid-rails, toe boards) installed at all leading edges	YES
N	
Extension ladders secured at top and bottom before use	YES
N	
Height safety equipment has current test tag	YES
N	
Penetrations and Voids	YES
N	
Penetration covers are mechanically fixed and marked	YES
N	
Where necessary cast in mesh is installed into slab	YES
N	
Lift shafts / service voids have covers or barriers installed, secured and marked	YES
N	
Guards in place over stair voids	YES

N	
Areas delineated / barricaded	YES
N	
Materials fall protection	YES
N	
Netting covers all perimeter scaffolding	YES
N	
Toe boards installed on all guard rails	YES
N	
Core holes / penetrations / voids covered and mechanically fixed	YES
N	
Scaffolds	YES
N	
Scaffold has current test and tag at all entry points	YES
N	
Handover certificate available	YES
N	
Adequately braced / tied	YES
N	
Gaps between scaffold and working face do not exceed 225mm	YES
N	
All scaffold components are intact	NO
N	
Access ladders / stairs free of debris, materials etc.	YES
N	
Bays free from obstruction	YES
N	
Minimum 450mm wide gap available on bays for worker access	YES

N	
Bays are not being point loaded	YES
N	
Bays are not being overloaded	YES
N	
No missing scaffold planks	YES
N	
Sole plates founded on solid base	YES
N	
Lapboards are mechanically secured	YES
N	
Incomplete scaffold has been barricaded and closed off + signs erected	YES
N	
PPE	YES
N	
Workers are wearing mandatory PPE	YES
N	
Workers observed using PPE correctly for their tasks (e.g. face masks)	YES
N	
PPE complies with regulatory requirements	YES
N	
Ladders	YES
N	
Only industrial strength ladders used	YES
N	
Ladders are in good condition and free of damage	YES
N	
Safety labels are intact	NO

N	
Extension ladders secured at top and bottom	YES
N	
Extension ladders extend 1m past top of landing	YES
N	
Extension ladders placed at correct angle (1:4)	YES
N	
Ladders not used on scaffold / near fall risks	YES
N	
Ladders not used in entrance ways / paths of travel without exclusion zone	YES
N	
Trenches and Excavations	YES
N	
DBYD been obtained before work	YES
N	
Services have been located and potholed	YES
N	
Excavations / trenches barricaded and sign posted	YES
N	
Correct trench support used where necessary	YES
N	
Trenches greater than 1.5m have edge protection and safe access / egress	YES
N	
Edges of excavations / trenches clear of spoil / materials	YES
N	
Hazardous substances	YES
N	
Register is kept on site and up to date	YES

N	
SDS available for all hazardous substances	YES
N	
Appropriate signage displayed	YES
N	
adequately stored and ventilated	YES
N	
Kept in original containers with labels	YES
N	
Spill kit available on site	YES
N	
Emergency and First Aid	YES
N	
Emergency access kept clear at all times	YES
N	
Emergency exit points clearly marked	YES
N	
Emergency evacuation plan displayed	YES
N	
Emergency assembly point displayed	YES
N	
Emergency contact details displayed	YES
N	
Adequate firefighting equipment available	YES
N	
Firefighting equipment has current test tag	YES
N	
First Aid officer & contact displayed	YES

N	
First aid signage displayed	YES
N	
First aid kit fully stocked	YES
N	
First aid and emergency personnel are trained / current certificates	YES
N	
Injury register maintained on site	YES
N	
Hot works are approved and adequately controls / emergency response measures in place	YES
N	
Cranes	YES
N	
Certificate of registration available	YES
N	
Insurances available	YES
N	
Maintenance and service records available and up to date	YES
N	
Pre-start inspection are being completed	YES
N	
Crane crew hold appropriate licences / competency	YES
N	
Exclusion being used during movement of loads	YES
N	
Emergency response measures in place	YES
N	
Mobile Plant	YES

N	
Certificate of registration available	YES
N	
Insurances available	YES
N	
Maintenance and service records available and up to date	YES
N	
Operators hold appropriate licences / competency	YES
N	
Exclusion being used where necessary	YES
N	
Emergency response measures in place	YES
N	
Lifting Equipment	YES
N	
Register available and maintained on site	YES
N	
Equipment has current test tag	YES
N	
Equipment correctly stored	YES
N	
Equipment inspected before use	YES
N	
Traffic Control / Public Safety	YES
N	
Traffic Management/ Control plan in place	YES
N	
Fencing / barriers to stop public access to site	YES

N	
Public areas kept clear of materials / rubbish / operations	YES
N	
Traffic controllers certified	YES
N	
Signs and devices in use	YES
N	
General / additional comments & notations	
Site inspection. Completed by Leonardo Milidone	