



Site Safety Inspection

Inspection Details

Project/ job reference:

Location:

asdas

Area inspected:

asdasd

Inspected by:

asdasd

Date:

2023-11-25

Inspection Checklist

Site Documents

YES

asd

Site signage displayed

YES

asd

Safety signs displayed

YES

asd

Mandatory PPE displayed

YES

asd

Policies displayed

YES

asd

Site rules displayed

YES

asd

Emergency information displayed

YES

sdf

First Aid officers displayed

YES

sdfas

Sign in / our register present

YES

ZXCZX

Site Security

YES

asd	
Site fence / hoarding present	YES
sdf	
Appropriate barricades in place	YES
sdf	
Site access is controlled	YES
sdf	
Public access is controlled	YES
dfg	
Safe access and egress in place	YES
asas	
Site Processes	YES
qweqwe	
All workers inducted on site	YES
qwe	
All workers inducted onto their SWMS / SOPS	YES
zxc	
All workers have white cards	YES
sd	
All workers following site processes	YES
re	
Daily pre-start meetings being held	YES
rt	
Toolbox talks regularly conducted	YES
er	
Housekeeping	YES
we	
Site generally clean	YES

we	
Walkways are clear of obstruction	YES
we	
Materials are safely stowed away	YES
qw	
Rubbish and debris is disposed of	YES
ew	
Slurry, water and dust removed	YES
ret	
Amenities	YES
rty	
Sufficient toilets / bubblers provided	YES
yt	
Lunchroom and facilities provided	YES
tyu	
Amenities are clean and tidy	YES
df	
Electrical	YES
sd	
Temporary power boards present	YES
df	
Temporary power boards fitted with RCD	YES
gf	
Temporary power board secured to the ground / base	YES
sd	
Temporary power board compliant with AS/NZS 3012:2010	YES
gf	
Electrical equipment has current test tag	YES

dfgf	
Electrical equipment connected to RCDs	NO
dgf	
Extension leads have current test tag	NO
sd	
Electrical leads are elevated off the ground with lead stands / hooks	YES
sd	
Electrical equipment and leads are in good condition	YES
df	
Working at Heights	NO
sd	
All falls 2m or more are protected	N/A
ds	
Temporary edge protection (handrails, mid-rails, toe boards) installed at all leading edges	YES
df	
Extension ladders secured at top and bottom before use	NO
fg	
Height safety equipment has current test tag	N/A
fg	
Penetrations and Voids	NO
hg	
Penetration covers are mechanically fixed and marked	YES
fgdfsd	
Where necessary cast in mesh is installed into slab	YES
sdf	
Lift shafts / service voids have covers or barriers installed, secured and marked	NO
dfg	
Guards in place over stair voids	YES

dfgds	
Areas delineated / barricaded	YES
sddfd	
Materials fall protection	YES
wewe	
Netting covers all perimeter scaffolding	NO
were	
Toe boards installed on all guard rails	N/A
trrrtrr	
Core holes / penetrations / voids covered and mechanically fixed	YES
erse	
Scaffolds	YES
erd	
Scaffold has current test and tag at all entry points	YES
df	
Handover certificate available	NO
dx	
Adequately braced / tied	NO
df	
Gaps between scaffold and working face do not exceed 225mm	YES
df	
All scaffold components are intact	YES
df	
Access ladders / stairs free of debris, materials etc.	NO
dfgf	
Bays free from obstruction	N/A
fgdf	
Minimum 450mm wide gap available on bays for worker access	YES

trrrtrr	
Bays are not being point loaded	YES
gfdg	
Bays are not being overloaded	NO
dfdf	
No missing scaffold planks	N/A
dgfgf	
Sole plates founded on solid base	YES
dgfg	
Lapboards are mechanically secured	N/A
dffdf	
Incomplete scaffold has been barricaded and closed off + signs erected	NO
sd	
PPE	YES
wee	
Workers are wearing mandatory PPE	NO
rere	
Workers observed using PPE correctly for their tasks (e.g. face masks)	YES
rdf	
PPE complies with regulatory requirements	NO
dfx	
Ladders	N/A
wes	
Only industrial strength ladders used	NO
qwe	
Ladders are in good condition and free of damage	YES
dfxc	
Safety labels are intact	NO

dx	
Extension ladders secured at top and bottom	NO
ghj	
Extension ladders extend 1m past top of landing	N/A
fg	
Extension ladders placed at correct angle (1:4)	NO
ghj	
Ladders not used on scaffold / near fall risks	N/A
ghj	
Ladders not used in entrance ways / paths of travel without exclusion zone	YES
cx	
Trenches and Excavations	NO
dfgg	
DBYD been obtained before work	N/A
ghf	
Services have been located and potholed	YES
gfh	
Excavations / trenches barricaded and sign posted	NO
ghf	
Correct trench support used where necessary	N/A
dfg	
Trenches greater than 1.5m have edge protection and safe access / egress	NO
fgh	
Edges of excavations / trenches clear of spoil / materials	NO
fgh	
Hazardous substances	N/A
fgh	
Register is kept on site and up to date	NO

gfh	
SDS available for all hazardous substances	YES
df	
Appropriate signage displayed	N/A
hgf	
adequately stored and ventilated	N/A
fgh	
Kept in original containers with labels	YES
fgh	
Spill kit available on site	YES
fghfgh	
Emergency and First Aid	YES
ertret	
Emergency access kept clear at all times	YES
erter	
Emergency exit points clearly marked	NO
werwer	
Emergency evacuation plan displayed	NO
wrwer	
Emergency assembly point displayed	N/A
werw	
Emergency contact details displayed	N/A
werw	
Adequate firefighting equipment available	NO
werw	
Firefighting equipment has current test tag	NO
erew	
First Aid officer & contact displayed	YES

werr	
First aid signage displayed	YES
qwerwer	
First aid kit fully stocked	NO
qwe	
First aid and emergency personnel are trained / current certificates	NO
qweq	
Injury register maintained on site	N/A
qwe	
Hot works are approved and adequately controls / emergency response measures in place	N/A
wer	
Cranes	NO
rty	
Certificate of registration available	NO
ert	
Insurances available	YES
ertet	
Maintenance and service records available and up to date	YES
er	
Pre-start inspection are being completed	NO
r	
Crane crew hold appropriate licences / competency	NO
gh	
Exclusion being used during movement of loads	N/A
bg	
Emergency response measures in place	YES
rety	
Mobile Plant	YES

rty	
Certificate of registration available	YES
rty	
Insurances available	NO
rty	
Maintenance and service records available and up to date	NO
rty	
Operators hold appropriate licences / competency	NO
ere	
Exclusion being used where necessary	N/A
werwe	
Emergency response measures in place	N/A
werer	
Lifting Equipment	YES
ret	
Register available and maintained on site	YES
ert	
Equipment has current test tag	YES
rthu	
Equipment correctly stored	NO
yui	
Equipment inspected before use	N/A
yui	
Traffic Control / Public Safety	N/A
yui	
Traffic Management/ Control plan in place	NO
yui	
Fencing / barriers to stop public access to site	NO

yuiy	
Public areas kept clear of materials / rubbish / operations	YES
yui	
Traffic controllers certified	YES
rtyrty	
Signs and devices in use	YES
uyiiuo	
General / additional comments & notations	
dsfsfds	