APEX MUTUAL INSURANCE GROUP
Property & Casualty Claims Intake Operations

FIRST NOTICE OF LOSS (FNOL)
STANDARD AUTOMOBILE LOSS NOTICE

Claim Number: CS-2026-881042
Policy Number: PA-882190-01

Loss Date & Time: 10/14/2026 at 08:35 AM CDT
Intake Date: 10/14/2026 10:15 AM CDT

1. INSURED & DRIVER INFORMATION

Named Insured: David M. Miller	**Contact Phone:** (312) 555-0148	**Email:** dmiller.claims@outlook-demo.com
Mailing Address: 1420 N Lake Shore Dr, Apt 8B, Chicago, IL 60610	**Driver License:** IL • M492-8102-9914 (Class D)	**Relation to Insured:** Named Policyholder
Policy Coverage: Comprehensive & Collision ($500 Ded)	**Policy Effective:** 01/15/2026 – 01/15/2027	**Agent / Producer:** Loop General Agency (IL-041)

2. INSURED VEHICLE SPECIFICATIONS

Year / Make / Model: 2018 Hyundai Elantra SEL	**Body Style:** 4-Door Compact Sedan	**Exterior Color:** Symphony Silver
VIN: 5NPD84LF9JH284192	**License Plate:** IL • 782 4912	**Current Odometer:** 64,120 miles
Vehicle Drivable? Yes (Cosmetic & light structural rear)	**Towed From Scene?** No (Driven to insured residence)	**Primary Impact Point: Rear Center / Right Rear**

3. LOSS LOCATION & ACCIDENT DESCRIPTION

Loss Date / Time: October 14, 2026 at 08:35 AM CDT	**Exact Location: N Michigan Ave & E Adams St, Chicago, IL 60603**
Road Surface: Wet asphalt (Light morning mist)	**Lighting / Weather:** Daylight, overcast, light drizzle

Detailed Loss Narrative:
Insured vehicle was traveling northbound on N Michigan Avenue in the center through lane. Approaching E Adams Street, the traffic signal cycled from green to yellow, and insured brought the vehicle to a controlled, complete stop behind existing queue traffic. Approximately three to four seconds after stopping, insured felt a sharp, violent rear impact. The striking vehicle was a 2019 Chevrolet Silverado 1500 (Summit White) driven by Robert Vance, who stated his tires slid on the damp road grade. Damage to insured vehicle includes compressed and cracked rear bumper fascia, buckled trunk deck lid latch, and shattered right passenger-side tail lamp assembly. Both drivers moved vehicles out of lane, exchanged insurance cards, and called Chicago Police.

4. ADVERSE PARTY & LAW ENFORCEMENT

Adverse Driver: Robert Vance	**Adverse Phone:** (312) 555-0891	**Adverse Vehicle:** 2019 Chevrolet Silverado (White)
Adverse Insurer: State Farm Insurance	**Adverse Policy:** SF-9024188-B	**Adverse Plate:** IL • 914 3801
Police Department: Chicago Police Dept (1st District)	**Police Report Number: RD #JH-482104**	**Officer Name / Star #:** Off. J. Kowalski #14821

FRAUD WARNING & ELECTRONIC SIGNATURE:
Any person who knowingly and with intent to defraud an insurance company files a statement of claim containing false, incomplete, or misleading information commits a fraudulent insurance act. I declare under penalty of perjury that the foregoing facts are true and accurate.

Reported By: David M. Miller (Electronically Authenticated)
Timestamp: 10/14/2026 10:14:22 CDT