SILICON VALLEY PRECISION COLLISION
1890 W San Carlos St, San Jose, CA 95128 • Lic #BAR-CA289140 • Ph: (408) 555-0144

AUTOMOTIVE DAMAGE APPRAISAL
ESTIMATE REF: EST-2026-44021

Customer: Mark T. Henderson • (408) 555-0199
Insurer: Pacific Horizon Mutual • Claim #CS-2026-944218

Vehicle: 2003 Toyota Celica GT Coupe (Liquid Silver Metallic)
Odo: 142,380 • **Recorded VIN:** JT2DD32T430188924

ITEMIZED TEARDOWN & COMPONENT APPRAISAL

Line	Operation	Description / Parts & Labor Items	OEM Part $	Body Hrs	Paint Hrs	Total Amount
1	REPLACE	Front Bumper Fascia Cover (52119-20927)	$485.00	2.0	3.0	$835.00
2	REPLACE	**Left (Driver-Side) Headlamp Assembly**	$320.00	0.6	0.0	$362.00
3	CHECK	Right (Passenger-Side) Headlamp Assembly (Intact/Unbroken)	$0.00	0.3	0.0	$21.00
4	REPLACE	Engine Hood Panel w/ Scoop Recess (53301-20410)	$640.00	2.5	3.2	$1,039.00
5	REPLACE	**Front Left Fender Panel (Driver Side)**	$275.00	1.8	2.2	$555.00
6	REPLACE	Front Left Inner Fender Liner Splash Shield	$88.00	0.5	0.0	$123.00
7	REPLACE	**Left Front Steering Knuckle & Tie Rod Assembly**	$385.00	3.0	0.0	$595.00
8	REPAIR	Radiator Core Support Left Upper Tie Bar Pull	$0.00	4.5	1.5	$420.00
9	PAINT	Paint Supplies & Liquid Silver Basecoat/Clearcoat	$340.00	0.0	9.9	$340.00
10	MECHANICAL	Four-Wheel Thrust Vector Alignment & Steering Check	$165.00	1.5	0.0	$270.00

ESTIMATE FINANCIAL SUMMARY & SPECIAL NOTES	Amounts
Total Parts & Replacement Assemblies:	$2,693.00
Body & Structural Labor (15.8 Hrs @ $70.00/hr):	$1,106.00
Paint & Refinish Labor (9.9 Hrs @ $70.00/hr):	$693.00
Mechanical & Alignment Labor:	$435.00
Paint Materials & Environmental Waste Fees:	$420.00
California Sales Tax (9.375% on Parts/Materials):	$291.84
Miscellaneous Shop Supplies & Hazardous Disposal:	$201.26
GROSS APPRAISED REPAIR COST:	**$5,840.10**

APPRAISER CRITICAL FINDING & SHOP NOTES:
1. Customer intake worksheet claims collision with culvert on right front. However, physical teardown reveals all crushing is located exclusively on the **FRONT LEFT (Driver-Side)**. The passenger headlamp, right fender, and right suspension are undamaged.
2. Inspection of lower core support reveals heavy structural oxidation (surface rust) along previous bend marks, indicating vehicle sustained an unaddressed prior front-end collision prior to this date of loss.
3. Vehicle ACV (Actual Cash Value) is approximately $4,500. This estimate ($5,840.10) exceeds the 75% California total loss statutory threshold.

Lead Appraiser: Robert Giannini, Master ASE

Appraisal Date: 10/19/2026

SYNTHETIC DEMONSTRATION DATA — NOT AN OFFICIAL RECORD — FOR DECISION-SUPPORT EVALUATION ONLY