

5/10/2022

GAS TRANSMISSION WORK ORDER

SEU

WORKORDER

WORK ORDER #: **7956189**

PMNUM:

PARENT WO #: 7889720

DESCRIPTION: Out of Tolerance (low)Annual L 235 M.P. 178.480-P

TARGET START DATE: 5/10/2022

ROUTE NUMBER:

TARGET COMP DATE: 5/10/2023

STATUS: INPRG

SCHEDULE START:

REQUESTED BY: DEBILL

SCHEDULE FINISH:

REPORT DATE: 5/10/2022

PM ACTIVITY CLASS: CP

ASSET #:

ASSET DESCRIPTION:

LOCATION ID: 235-181.57

LOC. DESCRIPTION: Line 235 (170.55 - 181.57) MV#18

PHYSICAL LOCATION:

RESPONSIBLE SUPERVISOR / OWNERWORK TYPEPRIORITYACCOUNT INFO

VICTORVILLE CP /

CCM

3

863102

REMARKS: *Complete**5-19-22*

Date Completed

D.B.

Completed By

SAFETY CHECKLIST COMPLETED?

Estimated Labor HoursLabor Code/CraftQuantityPlanned HoursActual Hours

0

COMMENTS:

~~Read Point: 235- 178.480- *0.850* Tolerance: 0.850- 2.000 *0.809*~~
~~Date Read: 5-10-22 *5-10-22*~~

LOCATION METERS:

LOG:

*5-10-22) adjusted taps on rectifier 177.60. C1, F7 30.64adc to
 C1, FB. current output 36.62, minor change in read.
 O.O.T.*

*5-13-22) dug down and checked for damage on wire. did Survey 100'
 East and west.*

5-19-22) checked p/s. New read. 0.857. in tolerance.