



Jeff Wokutch Autobody, Inc
930 North Ave
Millvale, PA 15209

RO Number: AS26-099

Inspection Number: 3285877

Year: 2024

Insurance: ALLSTATE FIRE AND CASUALTY INSURANCE
COMPANY

Make: Volkswagen

Model: Jetta Sport Manual

VIN: 3VWAM7BU8RM093617

Estimator: Geibel, Dan

IMPORTANT! Please validate vehicle is equipped with listed ADAS system components by performing a visual inspection!

Identified ADAS Related Services to be Performed

Based on the estimate, the following calibrations/initializations have been identified:

ADAS L3: Static Calibration - C (2)
Seat Belt Inspection (1)
Steering Angle Sensor (1)

Recommendations

OPUS recommends a pre-scan on this vehicle. To determine what type of scan should be performed, refer to service information and certification requirements.

OPUS recommends utilizing OEM software to perform a post-scan on this vehicle.

Calibrations

ADAS System/Components

Location

Calibration

Adaptive Cruise Control

Distance Sensor

Front Bumper

ADAS L3: Static Calibration - C

The Adaptive Cruise Control, Front Assist Module requires SVM coding and programming if replaced. calibration if any of the following occurs: adaptive cruise control module, radar sensor is replaced, radiator support set to the service position, adaptive cruise control module, radar sensor is removed and installed, radiator support is replaced, or when adjustments to the rear toe, thrust angle and changes to the vehicles ride height are made. ADAS target are required for system calibration.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?
adasInspection=3285877&adasChecklistMatrixVehicle=1415&type=1&model=Jetta Sport Manual](https://opusadas.z13.web.core.windows.net/links?adasInspection=3285877&adasChecklistMatrixVehicle=1415&type=1&model=Jetta Sport Manual)

Lane Departure / Keep Systems

Driver Assistance Systems Front Camera Windshield

ADAS L3: Static Calibration - C

The Driver Assistance Front Camera control module requires SVM coding and programming if replaced. Calibration is required if any of the following occurs, no or incorrect basic setting/adaptation fault is stored in the event memory, if the front camera is replaced, if the windshield was replaced or removed, if adjustments to the rear toe/thrust angle are performed, if repairs are made to the chassis that influence body height, or if the level control system sensor was readapted on vehicles with damping regulation. ADAS targets are required for system calibration.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?
adasInspection=3285877&adasChecklistMatrixVehicle=3044&type=1&model=Jetta Sport Manual](https://opusadas.z13.web.core.windows.net/links?adasInspection=3285877&adasChecklistMatrixVehicle=3044&type=1&model=Jetta Sport Manual)

Seat Belt Inspection

Seat Belt

Interior

Seat Belt Inspection

Seatbelts must be inspected after a collision to ensure passenger safety even if the airbags have not deployed.

OEM Reference:[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3285877&adasChecklistMatrixVehicle=4435&type=1&model=Jetta Sport Manual)[adasInspection=3285877&adasChecklistMatrixVehicle=4435&type=1&model=Jetta Sport Manual](https://opusadas.z13.web.core.windows.net/links?adasInspection=3285877&adasChecklistMatrixVehicle=4435&type=1&model=Jetta Sport Manual)**Steering Angle Sensor**

Steering Angle Sensor

Column

Steering Angle Sensor

Calibrate the Steering Angle Sensor after:

- removing or replacing Steering Angle Sensor.
- suspension axle adjustments

OEM Reference:[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3285877&adasChecklistMatrixVehicle=4549&type=1&model=Jetta Sport Manual)[adasInspection=3285877&adasChecklistMatrixVehicle=4549&type=1&model=Jetta Sport Manual](https://opusadas.z13.web.core.windows.net/links?adasInspection=3285877&adasChecklistMatrixVehicle=4549&type=1&model=Jetta Sport Manual)

Identified ADAS Systems

<u>System</u>	<u>Component</u>	<u>Location</u>
Adaptive Cruise Control	Distance Sensor	Front Bumper
Backup Cameras	Rearview Camera	Trunk Lid
Blind Spot Monitoring Systems	Lane Change Assistance - Rear	Rear Bumper
Lane Departure / Keep Systems	Driver Assistance Systems Front Camera	Windshield
Occupant Detection	Occupant Detection System	Passenger Seat
Seat Belt Inspection	Seat Belt	Interior
Steering Angle Sensor	Steering Angle Sensor	Column

The Fine Print:**The Fine Print (Legaleze)**

The ADAS MAP™ report is for informational purposes only and should not be considered as a replacement for Original Equipment Manufacturers (OEM) diagnostic, repair or calibration recommendations and procedures. The ADAS MAP™ platform utilizes data from multiple sources such as VIN, ADAS and safety system build data. While this data is considered accurate, Auto Techcelerators, LLC. makes no guarantees about its accuracy or completeness because it is being generated and delivered by third-parties.