



Nairobi City County Water & Sanitation Department

Sub-Surface Infrastructure Resilience & Flow Management Audit

Operational Scope: 7-Day Network Telemetry & Siltation Audit | Generated: 13 Aug 2026, 12:12

Executive Summary & Key Performance Indicators

Critical Asset Stress Points	0
Pending Remediation Actions	2
Operations Completed	13
Average Resolution Time	423 hrs 18 mins
Cumulative Catchment Inflow Index	2964.94 mm/hr
Network Operational Health	38%

CRITICAL ACTION ITEM

South C Bridge / NODE-001

Diagnostic: No notes available

Rainfall rate: 2964.94 mm/hr | Flow speed 300 cm/s | Siltation flag: NO

Critical Action Items & Maintenance Backlog

Ticket ID	Location & Node ID	Priority	Status	Diagnostic Summary
TKT-A2BFC869	South C Bridge NODE-001	Medium	Pending	-
TKT-66C43133	CBD - Tom Mboya Street Culvert NODE-003	Medium	Pending	-

Completed Operations & Accountability Trail

Ticket ID & Location	Dispatched Asset	Verified Operator	Time to Resolve
TKT-B57C039F Industrial Area Enterprise Rd	Unit 2 - Large Vacuum Truck	John Kamau	44 hrs 39 mins
TKT-51D2BEBE Industrial Area Enterprise Rd	Unit 2 - Large Vacuum Truck	John Kamau	0 mins
TKT-39596F46 Kilimani Ring Road Drain	Unit 3 - High-Pressure Jetting Unit	Alice Achieng	5 hrs 35 mins
TKT-2F0A1503 Mbagathi Way Junction	Unit 2 - Large Vacuum Truck	John Kamau	44 hrs 45 mins
TKT-EC7156BD Museum Hill Underpass	Unit 2 - Large Vacuum Truck	John Kamau	44 hrs 50 mins
TKT-559B2D4E Industrial Area Enterprise Rd	Unit 4 - Vacuum Truck	—	41 mins
TKT-5C87C8A0 Kilimani Ring Road Drain	Unit 2 - Large Vacuum Truck	—	54 mins
TKT-F539FA69 Industrial Area Enterprise Rd	—	—	240 hrs 0 mins
TKT-D6FDD885 South C Bridge	—	—	365 hrs 29 mins
TKT-1A933D89 Industrial Area - Enterprise Rd	—	—	1218 hrs 29 mins
TKT-8A75FC9A Kilimani - Argwings Kodhek Rd	—	—	1093 hrs 17 mins
TKT-78A915D3 Mbagathi Way - Highway Bridge	Unit 2 - Large Vacuum Truck	John Kamau	1219 hrs 35 mins
TKT-56AF3E67 South C - Muhoho Ave Junction	Unit 1 - Manual Desilting Crew	—	1224 hrs 46 mins

Sign-Off & Operational Recommendations

1. Dispatch a remediation crew immediately to South C Bridge (NODE-001) to assess desilting requirements.
2. Resolve 2 pending remediation action(s) and update ticket statuses to Resolved once verified in the field.
3. Allocate desilting budget and vacuum-truck resources proportional to the cumulative catchment inflow index of 2964.94 mm/hr.
4. Schedule a follow-up telemetry and siltation audit in 7 days to validate infrastructure resilience improvements.
5. Escalate network health score (38%) to the Water Operations control room for immediate intervention.