REPORT CONTAMINACIÓN

nº: 81521

FACILITY NAME: Auchenlosh Landfill Site 81522

FacilityInspireID: UK.SEPA/200000082.Facility

COUNTRY: United Kingdom CONTINENT: EUROPE

CITY: Dalbeattie

**EPRTRSectorCode:** 5 **eprtrSectorName:** Waste and wastewater management

MainActivityCode: 5(d)

targetRealase: AIR pollutant: Methane (CH4)

emissions: 101000

**DAY:** 15 **MONTH:** 4 **YEAR:** 2019

**METEOROLOGICAL CONDITIONS** 

max\_wind\_speed: 1,46E+16 min\_wind\_speed: 1,7E+16 avg\_wind\_speed: 1,47E+16

**max\_temp:** 9,74E+15 **min\_temp:** 1,1E+16 **avg\_temp:** 9,23E+15

DAYS FOG: 2

**REPORTER NAME** Brian Sims

**CITY\_ID** d52bec466f0edb76a6fc14c109598ba2