

**REPORT CONTAMINACIÓN**

nº: 81569

**FACILITY NAME:** Dalinlongart Landfill Site, Sandbank

81570

**FacilityInspireID:** UK.SEPA/200001325.Facility**COUNTRY:** United Kingdom**CONTINENT:** EUROPE**CITY:** Dunoon**EPTRSectorCode:** 5 **eptrSectorName:** Waste and wastewater management**MainActivityCode:** 5(d)**targetRelease:** AIR **pollutant:** Methane (CH<sub>4</sub>)**emissions:** 148000**DAY:** 22 **MONTH:** 1 **YEAR:** 2019**METEOROLOGICAL CONDITIONS****max\_wind\_speed:** 1,58E+16 **min\_wind\_speed:** 2,4E+16 **avg\_wind\_speed:** 1,89E+15**max\_temp:** 1,04E+16 **min\_temp:** 1,7E+16 **avg\_temp:** 1,23E+16**DAYS FOG:** 2**REPORTER NAME** Joshua Oliver**CITY\_ID** bc9dc084a859e6b840b69d6146c646df